

National Aeronautics and
Space Administration

JSC 14651

Lyndon B. Johnson Space Center
Houston, Texas 77058

ORBITER SUBSYSTEM
HARDWARE/SOFTWARE INTERACTION ANALYSIS

VOLUME VIII: AFT REACTION CONTROL SYSTEM

PART 2

(NASA-TM-80959) ORBITER SUBSYSTEM N80-18088
HARDWARE/SOFTWARE INTERACTION ANALYSIS.
VOLUME 8: FORWARD REACTION CONTROL SYSTEM
(NASA) 119 p HC A06/MF A01 CSCL 09B Unclass
G3/16 14301



JANUARY 1980.

PREFACE


The Orbiter subsystem hardware/software interaction analysis examines software interaction with hardware failure modes. Each failure mode identified in subsystem FMEA (failure mode and effects analysis) is examined for interaction with software. The analysis is based upon key questions which identify potential issues. These potential issues are to be resolved by providing rationale for retention or identifying and implementing changes to eliminate the issue.


The figure on the following page illustrates the relationship of the hardware/software interaction analysis to the verification process which leads to the statement of flight readiness. As shown, the analysis is a supporting item which is a portion of the data base utilized by the FRAT's (flight readiness assessment teams) and the associated SEAM (Systems Engineering Assessment Meeting) teams in planning and controlling the verification process. The overall issue of hardware/software interface compatibility is addressed by the verification process itself. The analysis scope is limited to examination of single failure modes, as identified in the FMEA, and the interaction of these failure modes with the software as reflected by the software requirements.

The hardware/software interaction analysis is performed on a preliminary basis by the JSC Reliability Division. Results are then coordinated with JSC engineering and Rockwell/Space Systems Group engineering and reliability to obtain inputs and approval signatures. The approval sheet for the AFT Reaction Control System are presented below. The Rockwell signatures represent their review of the open issues and risks, if any, performed against the summarization of the analysis. Section 5.0 presents the analysis summary which groups the failure modes by similar retention rationale and is a convenience in identifying groups of failure modes in which the analysis is similar. The reviews with Rockwell did not cover each checklist. The minutes presented in the appendix document the nature and depth of the Rockwell analysis review.

This analysis verified that no open issues remain.

Approved:

NB

Joseph H. Levine
Chief, Reliability Division
TE.



HARDWARE/SOFTWARE INTERACTION ANALYSIS

AFT - RCS
SUBSYSTEM

FMEA # SD72-SH-0103-2

ANALYSIS DATE November 5, 1979

Don Cagle
HARDWARE/SOFTWARE ANALYST

APPROVED:

Earl R. Smith 12-12-79
JSC Reliability

V. P. Oschard 1/7/80
Rockwell Reliability

Thomas Jenkins 12/4/79
JSC Engineering - FRAT Sponsor

Don F. Meyer
Rockwell Engineering - FRAT Sponsor

TABLE OF CONTENTS

| | <u>Page</u> |
|---|-------------|
| 1.0 INTRODUCTION | 1 |
| 2.0 SCOPE | 1 |
| 3.0 APPLICABLE DOCUMENTS | 1 |
| 4.0 DESCRIPTION | 2 |
| 5.0 ANALYSIS SUMMARY SHEETS | 9 |
| 6.0 ANALYSIS CHECKLIST SHEETS | 13 |

LIST OF FIGURES

| | |
|--|---|
| 4-1 HARDWARE/SOFTWARE ANALYSIS CHECKLIST | 3 |
| 4-2 CHANGE/RETENTION RATIONALE | 6 |
| 4-3 HARDWARE/SOFTWARE ANALYSIS SUMMARY | 7 |

| | |
|--------------------|-----|
| Appendix | 129 |
|--------------------|-----|

1.0 INTRODUCTION. This report documents the results of the analysis of the hardware/software interaction analysis for the AFT Reaction Control System. This analysis examines the interaction between hardware failure modes and software in order to identify associated issues/risks. These issues/risks are resolved through changes to software requirements to remove them, or surfaced to project/program management with appropriate retention rationale.

2.0 SCOPE. All Orbiter subsystems and interfacing program elements which interact with the Orbiter computer flight software are analyzed. The analysis for each subsystem or interfacing element is presented in a separate volume of this report (see section 3.1).

The analysis examines failure modes identified in the subsystem/element FMEA (failure mode and effects analysis). Potential interaction with software is examined through evaluation of the software requirements, not detailed implementation. The analysis is restricted to flight software requirements only, and excludes utility/checkout software. The BFS (backup flight system) software is considered only as necessary, and only as it differs from the primary; the basic thrust of the analysis is keyed to the primary system.

The analysis is based upon the hardware design and software requirements as they existed as of the date of the analysis. Future updates will be published as necessary to incorporate changes to either the hardware or software.

3.0 APPLICABLE DOCUMENTS.

3.1 HARDWARE/SOFTWARE INTERACTION ANALYSIS REPORT VOLUMES. The hardware/software interaction analysis results are reported on a subsystem basis, each in a separate volume. The separate volumes which make up this report are as follows:

| <u>Volume</u> | <u>Subsystem</u> |
|---------------|--|
| I | Purge, Vent, and Drain |
| II | Payload Deployment and Retention |
| III | Payload Bay Doors |
| IV | Main Propulsion |
| V | Data Processing Subsystem |
| VI | Hydraulics |
| VII | Auxiliary Power Unit |
| VIII | Reaction Control |
| IX | Electrical Power Generation |
| X | Orbital Maneuvering |
| XI | Environmental Control and Life Support |
| XII | Integrated Avionics |
| XIII | Electrical Power Distribution & Control |
| XIV | GNC (Guidance, Navigation & Control) Support |
| XV | Displays & Controls |
| XVI | Communications & Tracking |
| XVII | Instrumentation |

3.2 REFERENCE DOCUMENTS. The primary documents used in performing the analysis included the following:

- a. SD75-SH-17A, "Failure Mode Effects Analysis, AFT Reaction Control Subsystem," July 18, 1977.
- b. JSC 11174, "OV-102 Space Shuttle Systems Handbook," September 22, 1977.
- c. SD76-SH-0026A, "Functional Subsystem Software Requirements, Sequence Requirements," March, 1978.
- d. SD76-SH-0020, "Functional Subsystem Software Requirements, Displays and Controls," February 1, 1978.
- e. SD76-SH-0027D, "Functional Subsystem Software Requirements, Systems Management," October 16, 1978.
- f. MG038103, "Backup Flight System Management/Special Processes and Sequencing Program Requirements Document," December 20, 1978.
- g. SD76-SH-0010E "Functional Subsystem Software Requirements, Redundancy Management," June 1, 1979.

4.0 DESCRIPTION.

4.1 GROUND RULES. The hardware software analysis is performed according to the following ground rules:

- a. The hardware/software analysis will be limited to investigating the software interaction with the failure modes of the hardware as delineated in the subsystem FMEA's.
- b. Software interaction will be limited to involvement of software of the onboard computers.
- c. Only failure modes of hardware with software interfaces (software monitoring and/or software control) are analyzed.
- d. The software detection must be considered with respect to each phase of the mission [prelaunch (OPS 1 only), ascent, onorbit, and entry].

4.2 ANALYSIS CHECKLIST. The basic tool for the analysis is the checklist (figure 4-1). A separate checklist is used for each failure mode analyzed. Note that the "FMEA Number" in the heading refers to the FMEA document number, not the page number on which the failure mode is treated.

The checklist consists of three sections: Body, change/retention rationale summary, and explanation/comments. Each of these sections is discussed below.

4.2.1 CHECKLIST BODY. The checklist body contains the questions which drive the analysis. Blocks representing the possible answers for each question are provided. Those answers identified by asterisks entail potential issues and require explanation.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST

SUBSYSTEM _____

FMEA NUMBER _____

ITEM _____

FAILURE MODE _____

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☐
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☐
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☐ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

Figure 4-1. Hardware/Software Analysis Checklist

The questions in the checklist body are answered using the following guidelines:

a. Question 1. Will the information provided to the onboard software and the processing of that information cause annunciation of the failure and/or initiation of a corrective action in response to this failure mode?

b. Question 1a. Answer question 1a. if the answer to question 1 is "no." Information available to the software could be in the form of (1) sensor data used by onboard software but not for automatic fault detection (data used in software routines or fault detection available through callup or dedicated displays); (2) system and/or subsystem performance parameters; or (3) measurements which are downlisted. Answer "yes" if such information could be used to annunciate the failure condition or initiate responsive action. In explanation comments, specifically identify the information available for software detection.

c. Question 2. If all of the following questions are answered "no," check the "no" block and explain the difference in the explanation/comments section:

(1) Are the master measurements listed under "Failure Detectability In-flight" on the FMEA (1) used by the onboard software in detecting time critical failures (if routed to GPC), or (2) used by the onboard software in annunciating non-time critical failures via callup displays, or (3) downlisted for non-time critical failures?

(2) Are other measurements, dedicated displays, crew detection, and system/subsystem parameters available or able to detect this failure mode?

(3) If "failure detectability in-flight" specifies only software action, does the software actually initiate the corrective action as called out in the "corrective action" portion of the FMEA?

d. Question 3. The question considers only the cases wherein the software determines a failure.

e. Question 3a. Answer question 3a if the answer to 3 is "no." If the answer to 3a is "yes," call out the possible corrective action in the explanation/comments section.

f. Question 4. The question is considered for both the detected and the undetected failure. The overstress or inducement of another failure may be acceptable action. Overstress by software is improper commands, sequencing, or timing resulting in action exceeding hardware design requirements or exposing hardware to excessive environments.

g. Question 5. The question is considered for both the detected and the undetected failure. Limit adverse effects to effects directly resulting from software commands or subsequent actions resulting from erroneous inputs as a result of the failure.

h. Question 6. The hardware/software may change the method of detection and/or correction after the first or the second failure; consider this in answering the question. Determine if the software will be able to use the

redundance of the hardware. If the hardware/software interaction following the particular failure mode changes the criticality, in comparison to the FMEA, check the box provided in the summary section of the checklist.

i. Question 7. If crew action is not required to respond to the failure, check the "N/A" block. Cues which provide inputs to the crew include but are not limited to cathode-ray tube annunciation, caution and warning, visual cues, audible cues, callup and dedicated displays, subsystem status data, panel meters, etc.

j. Question 8.A and 8.B. Answer these questions only if either question 1 or 3 is "yes."

(1) Question 8.A. Consider that the failure occurs while the vehicle is being flown using the primary system. What will happen if the BFS must be engaged subsequent to the failure? Will the fact that the failure has occurred prevent the BFS from operating properly, under any conditions? A "no" answer is a potential issue (requiring explanation) only if the BFS can normally tolerate the failure (when it occurs during BFS operation).

(2) Question 8.B. Consider that the failure occurs while the vehicle is under BFS control. A "no" answer is an issue (requiring explanation) only if the BFS response differs from that for the primary system.

4.2.2 Change/Retention Rationale Summary. Each failure is assigned to one of six possible groups, based upon the answers obtained in the checklist body. Boxes are provided to indicate the category assigned. Figure 4-2 presents the criteria for group assignment.

A box is also provided to indicate that changes are required to the FMEA. The FMEA evaluation of in-flight detectability is sometimes inaccurate and requires change. In addition, other errors (e.g., incorrect criticality assignment or incorrect evaluation of redundancy screens) are occasionally noted during the analysis and are documented here.

A space is provided to detail acceptance rationale, change recommendations, or suggested FMEA changes. This space may also be used to provide a short general comment to expand the retention rationale grouping.

4.2.3 Explanation/Comments. Each question answered by checking a box identified with an asterisk is discussed in this section. The circumstances for checking a box not identified with an asterisk are discussed, and the rationale for not making such a change is presented, if applicable. This section may also be used to explain, expand, or qualify answers. Each discussion is identified with the corresponding question number.

4.3 ANALYSIS SUMMARY. The analysis results are summarized on the basis of retention rationale grouping and recommended changes/retention rationale. Figure 4-3 depicts the form utilized for this purpose. A particular retention rationale definition, acceptance rationale statement, or recommended change is listed in the left column, with the applicable failure modes listed on the right. The issue/risk is briefly described with acceptance rationale or software requirements change recommendation. The summary provides a basic overview of the total analysis results.

CHANGE/RETENTION RATIONALE

1. NO * CHECKED - NO HARDWARE/SOFTWARE ISSUES ARE APPARENT FROM THE ANALYSIS. SYSTEM IS FAIL OPERATIONAL/FAIL SAFE WITH RESPECT TO THIS FAILURE MODE UNDER CURRENT DESIGN.
2. ONLY * CHECKED ON QUESTION 6 - NO HARDWARE/SOFTWARE ISSUES ARE APPARENT FROM THE ANALYSIS. RISK HAS BEEN ACCEPTED VIA HARDWARE CIL.
3. ONLY * (YES) CHECKED ON QUESTION 1a - NO SOFTWARE DETECTION IS PROVIDED. FAILURE EFFECT IS NOT TIME CRITICAL. FAILURE MAY BE DETECTED BY OTHER MEANS OR FUNCTION IS NOT MISSION/SAFETY CRITICAL.
4. * CHECKED ON QUESTION 3a - * ON 1a MAY OR MAY NOT BE CHECKED - SOFTWARE DOES NOT TAKE CORRECTIVE ACTION FOR FAILURE. FAILURE EFFECT IS NOT TIME CRITICAL. CORRECTIVE ACTION MAY BE INITIATED BY CREW. PLANNED CHECKOUT ACTIVITIES WILL DETECT FAILURE. SYSTEM IS FAIL OPERATIONAL/FAIL SAFE WITHOUT SOFTWARE DETECTION AND CORRECTION.
5. STANDARD RETENTION RATIONALE DOES NOT APPLY. SPECIFIC RETENTION RATIONALE IS SUMMARIZED FOR THIS FAILURE.
6. ISSUES IDENTIFIED AND CHANGES ARE DESIRABLE. SPECIFIC CHANGES ARE SUMMARIZED.

NOTE: DO NOT CONSIDER ANSWER TO QUESTION 2 IN DETERMINATION OF CHANGE/RETENTION RATIONALE SUMMARY CODE. CONSIDER RESPONSES TO BOTH QUESTION 2 AND 6 IN DETERMINING WHETHER AN FMEA CHANGE IS REQUIRED.

6.0 ANALYSIS CHECKLIST SHEETS

Following are the analysis checklist sheets for each failure mode evaluated.

Figure 4-2. Change/Retention Rationale

HARDWARE/SOFTWARE ANALYSIS SUMMARY

SUBSYSTEM _____

FMEA

| ANALYSIS RESULT | ITEM/FAILURE MODE |
|--|-------------------|
| Figure 4-3. Hardware/Software Analysis Summary | |

Figure 4-3. Hardware/Software Analysis Summary

The subsystem failure modes not analyzed are also identified. These failure modes were evaluated as having hardware/software interfaces. Figure 4-4 depicts the form utilized for this purpose.

5.0 ANALYSIS SUMMARY SHEETS. The analysis results are summarized on the following sheets. The failure modes have been grouped by issue/retention rationale (or change), affording an overview of the results for the entire subsystem.

FAILURE MODES NOT INCLUDED IN HARDWARE/SOFTWARE ANALYSIS
EVALUATED AS INVOLVING NO HARDWARE/SOFTWARE INTERFACE

SUBSYSTEM _____

FMEA _____

| ITEM | FAILURE MODE |
|------|--------------|
|------|--------------|

Failure modes analyzed included only those items currently on the critical items list. All other failure modes will be analyzed at a future date.

Figure 4-4. Failure Modes Not Included In
Hardware/Software Analysis

HARDWARE/SOFTWARE ANALYSIS SUMMARY

SUBSYSTEM AFT - RCS

FMEA SD72-SH-0103-2

| ANALYSIS RESULT | ITEM/FAILURE MODE |
|-----------------------|--|
| HARDWARE ACCEPTS RISK | <p>Helium Tank - External Leak (03-2A-201010-1)</p> <p>Helium Feed Line - External Leakage (03-2A-201013-1)</p> <p>D. C. Solenoid Valve, Helium - Fails Closed (03-2A-201020-1)</p> <p>Line, Low Pressure Helium - External Leak (03-2A-201035-1)</p> <p>Helium Fill Quick Disconnect - Fails Open (03-2A-201070-1)</p> <p>Purge Quick Disconnect, Propellant - External Leakage (03-2A-201080-1)</p> <p>Test Quick Disconnect - External Leakage (03-2A-201090-1)</p> <p>Feedline and Fittings, Fuel - External Leakage (03-2A-202108-1)</p> <p>Propellant Fill and Bleed Disconnect - Fails Open (03-2A-202150-1)</p> <p>Propellant Tank Assembly - External Leak (03-2A-211110-1)</p> <p>Propellant Tank Assembly - Bubbles in Propellant (03-2A-211110-2)</p> <p>Injection Plate - Restricted Flow (03-2A-221311-1)</p> <p>Thrust Chamber - Burn-Thru (03-2A-221312-1)</p> <p>Nozzle Extension - Burn-Thru (03-2A-221313-1)</p> <p>Vernier Thruster - Loss of Output (03-2A-231310-1)</p> <p>Vernier Thruster - Fails to Stop Firing (03-2A-231310-2)</p> <p>Vernier Thruster - Burn-Thru (03-2A-231310-3)</p> |

HARDWARE/SOFTWARE ANALYSIS SUMMARY

SUBSYSTEM AFT - RCSFMEA SD72-SH-0103-2

| ANALYSIS RESULT | ITEM/FAILURE MODE |
|---------------------------|---|
| DETECTION DURING CHECKOUT | Helium Pressure Regulator - Restricted Flow - Fails Closed (03-2A-201030-2) Helium Quad Check Valve - Fails Closed (03-2A-201095-2) Feedline and Fittings, OX - External Leakage (03-2A-202109-1) Tank Isolation Valve, A. C. - Fails Closed (03-2A-202110-1) Tank Isolation Valve, A. C. - Fails Closed (03-2A-202110-3) Interconnect Valve, A. C. - Fails Closed (03-2A-202111-2) Manifold Isolation Valve, A. C. - Fails Closed (03-2A-202120-3) Manifold Isolation Valve, D. C. - Fails Closed (03-2A-202140-1) Gimbal Joint - External Leakage (03-2A-211120-1) Bellows Assembly - External Leakage (03-2A-221308-1). Engine Inlet Valve - Fails Closed (03-2A-221310-4) |

HARDWARE/SOFTWARE ANALYSIS SUMMARY

SUBSYSTEM AFT - RCS

FMEA SD72-SH-0103-2

| ANALYSIS RESULT | ITEM/FAILURE MODE |
|-----------------------|--|
| NO SOFTWARE DETECTION | Relief Valve - External Leak - Fails Open (03-2A-201060-4) |

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER

03-2A-201010-1

ITEM He Tank

FAILURE MODE

External Leak

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☒ NO ☐
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. V42P3110, 3113 (Right AFT) or V42P2110, 2113 (left AFT) He tank transducers will issue a class 3 alarm, RM GAX blue light on the crew-cockpit glare shield, upon sensing low pressure < 500 psi. Gross leak detection C&W is first indication.

5. A He tank leak will adversely affect the RCS quantity monitor principal function by causing meter M4 (panel 03) "RMS/OMS propellant quantity" to indicate an erroneously low percent quantity remaining. This is because He tank pressure is used in the software calculation. See FSSR 26 "sequencing", principal function 4.102.

6. No redundant tanks - loss of RCS function. Crossfeed is available.

8B. Same as primary.

STUDIES IN POLYMER SCIENCE: ANALYTICAL SUBJECTS ANALYSIS - 1951-1952, 1953

[illegible]

WELFARE SY:

Andi Kilye 6-Y:

122

3 TELECAST

۱۱۹

424

1. ARTISTS

4. EL

117. 127

• FILED - FIRST, SECOND AND THIRD

• 1997-1998

1. 1-TON, 4-1/2" DIA. X 6' X JACKING PRESSURE OF 4000 PSI PER

DESCRIPTION OF THE AIRCRAFT VEHICLE'S PROPELLER DRIVE SYSTEM. The
CONSISTS OF DOUBLE FUEL IN LINE WITH GROSS KEVIN 40 H.P. AND 100
GAL. FUEL TANK OVERHEAD. P.S. IS 11.71 IN. VOLUME IS 20.00 CU. IN.

APPENDIX B: STRUCTURAL FAILURE (5)

• AT 1000000

$$\bullet \text{ } P'_{34} (c) =$$

• TITANIUM, CURE EPO, POLY-EP, EPOXY CURE IN EPO, TESTIMONIALS, GROSS, VIO, INALVES OVERPRESS (CNC), INALVES MOUNTING

1. (A) SUBSYSTEM (B) INTERFACES (C) MESSAGE (D) CHANNEL/VEHICLE :

• (A) LOSS OF FUNCTION/SYSTEM (B) LOSS OF INTERFACE FUNCTIONS -

• POTENTIAL DEPLETION/ILLIQUID ASSET, POSSIBLE DAMAGE TO THE STRUCTURE

TPS. (C) MISSILE MULTIPLICATION - X-FEED FROM OWS UNUS. (D) POSSIBLE
LOSS OF OWS VEHICLE EXCESS RATE OF LEAK MAY EXCEED PDS VMT CAP.
CAUSING DAMAGE TO PDS STRUCT & DEGRAD OF THERMAL PROT SYS. EXCESS
RELIABILITY OF PDS MAY AFFECTLY AFFECT VMT SYN DURING ENTRY & UNDO.

• COUNTERING ACTIONS:

• X-FIELD PROP FROM CMS OF ACS. ULLAGE MAY BE ADJG PER PROP FIELD FROM
FAILED POS.

• 01/05/47 11 4 :

EXCESS RATE OF LEAK MAY EXCEED FUEL VENT CAPAB CAUSING DUE TO FUEL
SUCKED. EXCESS OF INTERNAL PRESSURE (MOLECULAR WEIGHTING PUMP WITH LEAK
LEAK). EXCESS RATE OF LEAK MAY ADVERSELY AFFECT VEH DYN LUNGS ENTRY
G LUNG. NO HAZARD FOR TANKS. REF HAZ NO 1YXA-CR2-C2.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201010-1 REV:11/08/79
 .ASSEMBLY :PRESSURIZATION ABORT: CRIT. FUNC: 1
 .P/N PI :MC282-0032-0031/-0032 CRIT. HOW: 1
 .P/N VENDOR:BLD-999040-1/-2 MISSIONS: HF VF X FF OF SM
 .QUANTITY :4 PHASE(S): PL X LO X CO X DO X LS
 . :TWO BOTTLES REQ'D PER
 . :MODULE:ONE PER PROP. TK.
 . REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

.PREPARED BY:
 .DES J TAGGART
 .REL C AKERS

APPROVED BY:
 DES *[Signature]*
 REL *[Signature]* 12/79

APPROVED BY (NASA):
 SSM *[Signature]*
 REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

- .ITEM: TANK
- . HELIUM STORAGE, FILAMENT WOUND
- .FUNCTION:
 - . TO STORE HELIUM AT A MAX WORKING PRESSURE OF 4000 PSI FOR PRESSURIZATION OF THE AFT RCS MODULE'S PROPELLANT SUPPLY SYSTEM. TANK CONSISTS OF DOUBLE MELT TI LINER WITH DUPONT KEVLAR 49 FIBER AND EPOXY RESIN BONDING OVERLAP. D.O. IS 18.71 IN. VOLUME IS 3008 CU. IN.
- .FAILURE MODE: STRUCTURAL FAILURE (S)
- . EXTERNAL LEAK
- .CAUSE(S):
 - . MAT'L DEF, LINER DEF, FAULTY FAB, EPOXY CURE INADEQ, TEST/HANDL DAM, SHOCK, VIB, INADVER OVERPRESS (GMO), INADEQ MOUNTING
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 - . (A) LOSS OF FUNCTION/SUBSYSTEM (B) LOSS OF INTERFACE FUNCTION - INABILITY TO DEplete/UTILIZE PROP, POSSIBLE DAMAGE TO POD STRUCTURE & TPS. (C) MISSION MODIFICATION - X-FEED FROM OMS OR PCS. (D) POSSIBLE LOSS OF CREW VEHICLE EXCESS RATE OF LEAK MAY EXCEED POD VENT CAPAB CAUSING DAMAGE TO POD STRUCT & DEGRAD OF THERMAL PROT SYS. EXCESS RETENTION OF PROP MAY ADVERSELY AFFECT VEH DYN DURING ENTRY & LNDG.
- .DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
 - . (A) FILAMENT WOUND TANKS ARE DESIGNED TO LEAK BEFORE RUPTURE WHICH LIMITS FAILURE PROPAGATION DUE TO SHRAPNEL. KEVLAR 49 FIBER HAS A TENSILE STRENGTH OF 500KSI ALLOWING LIGHT WEIGHT WITH GREAT STRENGTH. INCREASED STRAIN CAPABILITY IS PROVIDED BY THE COMPRESSIVE LOAD ON A UNPRESSURIZED LINER. VENT DOORS ARE OPEN ON ORBIT AND WILL RELIEVE ANY PRESSURE BUILDUP DUE TO LEAKAGE. THE F.S. (BURST) IS 1.5 X WORKING PRESS. (B) 1000 PRESSURE CYCLES ARE PERFORMED DURING QUAL WHICH IS MORE THAN 4 X ANTICIPATED OPERATING LIFE. A 90-DAY CREEP TEST UNDER PRESSURE IS ALSO PERFORMED AFTER WHICH THE TANK IS EXAMINED TO VERIFY NO PERMANENT DEFORMATION OR FLAW GROWTH. PROOF PRESSURE (1.10 X WORKING PRESSURE) AND LEAKAGE TESTS ARE PERFORMED DURING ATP. (C) AN IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. RAW MAT'L AND PURCHASED COMPONENT REQMTS ARE VERIFIED BY RECEIVING INSP. MEASUREMENT STANDARDS AND TEST EQUIP. STANDARDS ARE IMPLEMENTED PER REQMTS OF MIL SPECS. THE FOLLOWING ITEMS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSPECTION POINTS - PARTS PROTECTION, MFG. PROCESSES, FINISHES, ASSY AND INSTALLATION. THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 5-23-77 - CORROSION PROTECTION PROVISIONS, TEST HANDLING, AND STORAGE

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201010-1 REV:11/03/77
ENVIRONMENTS. TENSILE, HEAT TREAT AND WELD SAMPLES ARE TESTED DURING
IN-PROCESS FABRICATION IN ADDITION TO X-RAY & DYE PENETRANT FOR THE
LINES. WIND PATTERN & WINDING CONTROL ARE USED FOR THE KEVLAR FIBER
DURING IN-PROCESS MANUFACTURE. WEIGHT CONTROL IS USED FOR THE EPOXY
RESIN. TURNAROUND - MONITOR LEAKAGE TESTS PERFORMED AFTER INSTALLATION
INTO THE SYSTEM AND AS PART OF THE CHECKOUT PROCEDURE PRIOR TO FLIGHT.
PRESSURE CYCLES ACCUMULATED ARE ALSO RECORDED. (D) NONE AVAILABLE NEW
DESIGN.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-201013-1

ITEM He Feed Line

FAILURE MODE External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. V42P3110, 3113 (Right AFT) or V42P2110, 2113 (left AFT) He Tank transducers will issue a class 3 alarm, RM GAX blue light on the crew-cockpit glare shield, upon sensing low pressure < 500 psi. Gross leak detection C&W is first indication.
2. FMEA Change - For "failure detectable in flight" V42P-2110C through 2114C and 3110C through 3114C should be V42P2110C, 2112C, 2112C, 2113C, 2114C and 3110C, 3112C, 3113C 3114C dropping out 2111C and 3111C which do not exist.
6. Feedlines are criticality 1 with no remaining success paths. Crossfeed is available.
- 8b. Same as primary.

1. 1. 2

[illegible]

APPROVED BY:

343

٤٤٤

. . . 17% 1941% 1993 LVL

194211 1

1/2 X .042 COAL S.S. LINE TO PROVIDE HELIUM PRESS FROM HELIUM TANKS TO
HELIUM REGULATION/RESTORATION SYSTEM PANEL

FAILURE MODE: STRUCTURAL FAILURE (S)

FAILURE MODE: STRUCTURAL FAILURE (S)

REPORT, INTERNATIONAL LIAISON

• Exhibit (C) :

• SADDLE OFF (NULPFIID STAIRS), VIB, SHOCK, STRUCT FAIL, FATIGUE, SELL
OFF, STRESS CORROSION, INC INSTALL.

• REFLECT(S): (A) SUPPSYS (B) INTERFACES (C) MISSION (D) CRIT/VARIABLES:

(4) LOSS OF SUBSYSTEM PRESSURIZATION CAPABILITY IF ACT 25-L FAIL

• INSTRUCTIONS OF ISOL VLV-INABILITY TO DEFEATE/UTILIZE WEPD). (B) LOSS OF INTERFACE FUNCTION (INABILITY TO REFRESH PROP LINK - POL FOR STRONG & RES

14. (C) FERTILIZATION (LOSS OF PRESS) (D) POSSIBLE LOSS OF
CONE/VEHICLE - IF FLARE EXCESS OR FUZZY/PS DAM OCCURS

• 63620 185 801104

• EVAL FOR 'A'. UTILIZE PROP TANK ULLAGE PRESS & GNS LE ACS PROP X-FEEL
AS INDIC. IN PROP REC & REP.

• 1957 年 65/44 号 IS:

• V.I. LYN MAY BE AVER. AFF IF SIC CUAN OF PRGP REMAINS. PCD OVERLOOKS MAY RESULT IN DAM TO STRUCT & OPS. REF HAZ NO 1YXX-(302-22).

ORIGINAL PAGE IS
OF POOR QUALITY.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A - 201013-1 REV: 12/13/78
 . ASSEMBLY : PRESSURIZATION HELIUM ABGRT: CRIT. FUNC: 1
 . P/N RI : MC621-0059 CRIT. HDW: 1
 . P/N VENDOR: 73A630000 MISSIONS: HF VF X FF CF SM
 . QUANTITY : 4 PHASE(S): PL X LO X OO X DO X LS X
 . : ONE SET PER PROPELLANT
 . : PER MODULE

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

. PREPARED BY:
 . DES N C GLAVINICH
 . REL C M AKERS

APPROVED BY:
 DES *[Signature]*
 REL *[Signature]*

APPROVED BY (NASA):
 SSM *[Signature]*
 REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

. ITEM: HELIUM FEED LINE

. FUNCTION:

. 1/2 X .042 304L S.S LINES TO PROVIDE HELIUM FEED FROM HELIUM TANKS TO
 HELIUM REGULATION/PRESSURIZATION SYSTEM PANEL

. FAILURE MODE: STRUCTURAL FAILURE (S)

. RUPTURE, EXTERNAL LEAKAGE

. CAUSE(S):

. MAT'L DEF (SULPHIDE STRINGER), VIB, SHOCK, STRUCT FAIL, FATIGUE, WELD
 DEF, STRESS CORROS, IMP INSTALL.

. EFFECT(S): CN (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

. (A) LOSS OF SUBSYSTEM PRESSURIZATION CAPABILITY IF NOT ISOL (FAIL
 UPSTREAM OF ISOL VLV-INABILITY TO DEplete/UTILIZE PSCP). (B) LOSS OF
 INTERFACE FUNCTION (INABIL TO REPRESS PSCP TANK - POT POD STRUCT & TPS
 DAM. (C) ABORT DECISION (LOSS OF PRESS) (D) POSSIBLE LOSS OF
 CREW/VEHICLE - IF LEAK EXCESS OR POD/TPS DAM OCCURS

. DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

. (A) F.S. IS 1.5 TO 4.0 MAXIMUM OPERATING PRESSURE (SYSTEM RELIEF).
 THE WELDED CONSTRUCTION ELIMINATES JOINTS AND POSSIBLE LEAK PATHS.
 THE ANNEALED AREA (DUE TO WELDING) IS BACKED UP BY A SLEEVE.
 FASTENING CLAMPS ALLOW FREEDOM OF MOVEMENT. TUBING BENDS ARE
 CONTROLLED BETWEEN FIXED POINTS TO FACILITATE INSTALLATION AND
 ACCOMMODATE VEHICLE GROWTH AND MOVEMENT. (B) ROCKWELL PERFORMED
 TUBING CERTIFICATION TESTS PER "ORBITER TUBING VERIFICATION
 PLAN" (SD 75-SH-0205). THIS TESTING INCLUDED PRESSURE CYCLING AND FOR
 TYPICAL SHUTTLE LINES & JOINTS. SYSTEM EVALUATION TESTS AT WSTF WILL
 ALSO ALLOW EVALUATION IN THE INSTALLED SYSTEM CONDITION. LEAKAGE TESTS
 ARE PERFORMED IN-PROCES FOR TUBING SECTIONS. OPTICAL INSPECTIONS ARE
 ALSO PERFORMED AT THIS TIME IN ADDITION TO X-RAY AND DYE PENETRANT.
 LEAKAGE TESTS ARE ALSO PERFORMED AFTER INSTALLATION INTO THE SYSTEM AND
 ADDITIONAL WELDS ARE ALSO SUBJECTED TO NOE. (C) AN IDENTIFICATION IS
 PERFORMED AND THE UNIT TAGGED. CONTAM. CONTRL PROCESSES, COPROS.
 PROTECTION PROVISIONS, NOE EXAM OF WELDS AND INSP. FOR SURFACE AND
 SUB-SURFACE DEFECTS IS VERIFIED BY INSPECTION. THE FOLLOWING ITEMS ARE
 VERIFIED BY SHOP TRAVELEER MANDATORY INSP. POINTS. RAW MAT'L (LOT
 CERTIFICATION), PARTS PROTECTION, MANUF., COATING, PLATING, INSTLLATION
 AND ASSEMBLE OPERATIONS. HARDWARE IS INSP. IN ACCORDANCE WITH QUALITY
 PLANNING REQMTS DOCUMENT (QPRO) WHICH HAS BEEN APPROVED BY NASA.

SHUTTLE CRITICAL ITEMS LIST - CR3ITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201013-1 REV:12/13/79
TURNAROUND - LINES IN ACCESSIBLE AREAS ARE VISUALLY INSPECTED FOR
EVIDENCE OF DAMAGE AND FLOW AND PRESSURE FUNCTIONAL TESTS ARE MONITORED
FOR EVIDENCE OF OBSTRUCTION OR LEAKAGE. (O) MISC HISTORY -
CORROSION/FAB PROBLEMS DETECTED DURING APOLLO CHECKOUT AND CORRECTED.

ORIGINAL PAGE IS
OF POOR QUALITY

990

SD75-SH-0003

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-201020-1

ITEM D.C. Solenoid Valve, He

FAILURE MODE Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☒ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

See Note 2.

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Ullage transducer will give C&W alert < 200 psi.

2. Measurement numbers V42X2124X, 2126X, 3124X, and 3126X (Fu He isolation valves) needs to be added for detectability since only the measurement stimulus identification numbers for the oxidizer valves are listed now.

FUNCTION FAILURE MODE AND EFFECTS ANALYSIS - GATES 104

SUBSYSTEM NAME - FLIGHT CONTROL AREA NO 13-2A - 100000-1 REV 12/1/77
 ANALYSIS APPROPRIATION ALRT: C 11. P 100: 1
 DATE: 10-15-77 C 11. P 100: 1
 ANALYST: J. L. GATES
 TITLE: VALVE FOR EACH NUMBER OF SUCCESS PATHS REPAIRS
 AFTER FIRST FAILURE: 100
 REDUNDANCY SCHEME: A-PASS B-PASS C-PASS
 FAILURE DETECTABLE IN FLIGHT? YES TIME TO EFFECT: 100
 POSITION INDICATIONS 042 212 X, 2127 X, 2120 X, 2122 X MINUTES
 REPAIRING DOCUMENTS: 100
 NO 601-0059
 NO 70-43101
 NO 72-24-0103-2
 NO 70-0101-015

PREPARED BY: DES REL K BURKHART C W AKERS APPROVED BY: DES REL

- 1. VALVE, L.C. SOLENOID
- 2. OPERATED, HIGH PRESSURE. HELIUM (1/2") SI-STABLE. (LATCHING - 100000-1 SPRING FORCE) LV 201/202/203/204/301/102/303/204.
- 3. FUNCTION:
 - 4. DESIGNED TO CONTROL FLIGHT PRESSURIZATION SYSTEM IN THE AFT MODULE. IN THE OPEN POSITION A FLOW PATH IS PROVIDED FROM THE FLIGHT SUPPLY TANK(S) TO THE REGULATORS. TWO PARALLEL PATHS ARE PROVIDED FOR EACH PROPELLANT TANK. ONE PATH IS NORMALLY OPEN PER TANK. THE OPEN VALVE MAY BE CLOSED AND THE PARALLEL VALVE OPENED SUBSEQUENT TO A LOST-TO-A-FAILURE.
- 4. FAILURE MODE: FAILS CLOSED (F)
- 5. CAUSE(S):
 - 6. VOLT CONTINUOUS INADVERT CLOSING SIGNAL DUE TO SHORT CIRCUIT. SHOCK, CONNECTOR PIN OR LICE DAMAGE, JAMMING OF POPPET, PLUGGED ORIFICE.
- 6. EFFECT(S): (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 - 7. (1) LOSS OF REDUNDANCY - PARALLEL PATH AVAILABLE. (2) NO EFFECT.
 - 8. (3) AFFECT MISSION - (4) TO ONLY ONE PATH REMAINING FROM 1. CRITICAL EFFECT. (5) NO EFFECT. (6) FUNCTIONAL CRITICALITY EFFECT - POSSIBLE CREW VEHICLE LOSS - FAILURE OF REDUNDANT PARALLEL FLOW PATH COULD RESULT IN INABILITY TO BURN OR DEPLET RCS PROPELLANT. THIS WOULD RESULT IN POSSIBLE INABILITY TO CONTROL VEHICLE DURING ENTRY DUE TO INABILITY TO USE RESERVED ENTRY PROPELLANT OR C.O. PROBLEMS RESULTING FROM PROPELLANT WEIGHT.
- 7. CORRECTING ACTION:
 - 8. IF CAUSED BY VIBRATION, THE VALVE MAY BE CAPABLE OF OPENING WITH A NEW COMMAND, OR SWITCH TO PARALLEL PATH.
- 8. REMARKS/HAZARDS:
 - 9. POTENTIAL TIME CRITICAL HAZARD RELATED TO REACTION TIME FOR SWITCHING TO ALTERNATE PATH DURING CRITICAL MODES OF OPERATION SUCH AS E.T.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - DWT 1123 177

SYSTEM SAFE - SELECTION CONTROL. DATA DWT 1123-24 - 11/10/70 - 11/12/70
OPERATION, REPAIRS, ETC. SEE CONSOLIDATED CONTROL DATA SHEET
DWT 1123-25. LABEL 12/1/70 (REV E). SEE DATA TO DATA-1123-25.

ORIGINAL PAGE IS
OF POOR QUALITY

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - CR8ITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -201020-1 REV: 12/12/73
ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1R
P/N RI : MC284-0419-0011/-0012 CRIT. HOW: 2
P/N VENDOR: 73835 MISSIONS: HF VF X FF OF SM
QUANTITY : 8 PHASE(S): PL X LD X OD X DD X LS
• TWO VALVES REQ'D FOR EAC
• H HELIUM SUPPLY

REDUNDANCY SCREEN: A-PASS B-PASS C-FAIL

PREPARED BY: DES R BURKHART APPROVED BY: *[Signature]* APPROVED BY (NASA): *[Signature]*
REL C M AKERS DES *[Signature]* SSM *[Signature]*
REL *[Signature]* REL *[Signature]*

APPROVED WITH CHANGES
See Section 13.0

ITEM: VALVE, D.C. SOLENOID
OPERATED, HIGH PRESSURE. HELIUM (1/2") 91-STABLE. (LATCHING -
MAGNETIC & SPRING FORCE) LV 201/202/203/204/301/302/303/304.

FUNCTION:

UTILIZED TO CONTROL HELIUM PRESSURIZATION SYSTEM IN THE AFT MODULES.
IN THE OPEN POSITION A FLOW PATH IS PROVIDED FROM THE HELIUM SUPPLY
TANK(S) TO THE REGULATORS. TWO PARALLEL PATHS ARE PROVIDED FOR EACH
PROPELLANT TANK. ONE PATH IS NORMALLY OPEN PER TANK. THE OPEN VALVE
MAY BE CLOSED AND THE PARALLEL VALVE OPENED SUBSEQUENT TO A DOWNSTREAM
FAILURE.

FAILURE MODE: FAILS CLOSED (F)

CAUSE(S):

VIB CONTINUOUS INADVERT CLOSING SIGNAL DUE TO SHORT CIRCUIT, SHOCK,
CONNECTOR PIN OR DIODE DAMAGE, JAMMING OF PUPPET, PLUGGED CRIFICE.

EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

(A) LOSS OF REDUNDANCY - PARALLEL PATH AVAILABLE. (B) NO EFFECT.
(C) ABORT DECISION - DUE TO ONLY ONE PATH REMAINING PRIOR TO CRITICAL
EFFECT. (D) NO EFFECT. (E) FUNCTIONAL CRITICALITY EFFECT - POSSIBLE
CREW VEHICLE LOSS - FAILURE OF REDUNDANT PARALLEL FLOW PATH WOULD
RESULT IN INABILITY TO BURN OR DEplete RCS PROPELLANT. THIS WOULD
RESULT IN POSSIBLE INABILITY TO CONTROL VEHICLE DURING ENTRY DUE TO
INABILITY TO USE RESERVED ENTRY PROPELLANT OR C.G. PROBLEMS RESULTING
FROM PROPELLANT WEIGHT.

DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

(A) PARALLEL VALVES AND REDUNDANT POWER SOURCES ARE PROVIDED. ULLAGE
PRESS IS ADEQ FOR PROP FEED WITH LESS THAN 35 PERCENT PROP REMAINING.
ONE VALVE IS MAINTAINED IN THE LATCHED OPEN POSITION WITH NO POWER
APPLIED & THE OTHER IS LATCHED CLOSED. AN INDUCTIVE VOLTAGE SUPPRESSION
CIRCUIT IS PROV IN THE ELECTRICAL SYSTEM TO PREVENT DAMAGE TO OTHER
ON-LINE COMP. REDUN DIODES LIMIT THE POSS OF DIODE FAILURE ALLOWING
CURRENT SHUNT FROM THE COIL. A 100-MICRON FILTER IS PROV TO LIMIT THE
POSS OF CONTAM CAUSING LEAKAGE, JAMMING MOVING PARTS - OR PLUGGING PILOT
CONTROL ORIFICES. TO LIMIT THE ELECT SHORT POTENTIAL, THE LEAD AND
MAGNET WIRES ARE ENCAP BY POTTING AND A FIXTURE IS USED DURING ASSEMBLY
TO ENSURE THAT INSUL IS NOT DAMAGED BY THE EXIT NOTCH WHEN THE COIL
SLEEVE IS PRESSED ONTO THE COIL. (B) 4000 OPER CYCLES (ON-OFF-FLOW) AND
RANDOM VIB AT ANTIC MISSION LEVELS ARE PERF DURING QUAL. ITEM IS USED

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201020-1 REV:12/12/73
DURING SYS EVAL TESTS AT MSTF ALLOWING EVAL UNDER SIMUL MISSION USAGE
COND. PROOF PRESSURE, LEAKAGE, OPER AND INSUL TESTS ARE PERF DURING
ATP. APROP LOCATED TEST POINTS ALLOW PRE/POST FLIGHT LEAKAGE TESTS AND
OPER TESTS ARE ALSO CONDUCTED AT THIS TIME. (C) AN IDENT IS PERF AND
THE UNIT TAGGED. CONTAM CONT PROCESS, CORROS. PROT PROV, ADE EXAM. OF
WELDS AND BRAZES, INSP. FOR SURFACE AND SUBSURFACE DEFECTS AND PROPER
ELECT TERMINATIONS ARE VERIF BY INSP. THE FOLLOWING ITEMS ARE VERIF BY
SHOP TRAVELER MANDATORY INSP. POINTS - RAW MAT'L (LOT CERT), PARTS PROT,
MANUF., COATING, PLATING INSTALL AND ASSEMBLY OPER. THE ABOVE ITEMS AND
THE FOLL ITEMS WERE VERIF BY AUDIT COND 8-31-77. CONTAM CONT
PROCESSES, CORROS. PROT PROV. TURNAROUND - FUNCT FLOW TESTS ARE
MONITORED TO VERIFY THAT VALVES OPEN AND CLOSE PROPERLY UPON COMMAND.
(D) APOLLO FAILURES WERE MAINLY ASSOC WITH REVERSE POLARITY AND
DEGAUSSING OF MAGNETS. THE SHUTTLE VALVE UTILIZES A CONNECTOR (RATHER
THAN LEAD WIRES) AND BLOCKING DIODE WHICH PREVENTS THIS TYPE OF ERROR
DURING CONN. A POTENT ELECT SHORTING PROBLEM ON A SIMILAR VALVE DUE TO
INSUL DAMAGE WAS DISCOV DURING QUAL AND CORR AS DESCRIBED IN ITEM (A)
ABOVE.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-201030-2

ITEM He Pressure Regulator

FAILURE MODE Restricted Flow - Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☒ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☐
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Ullage transducer will give C&W alert < 200 psi.
- 3A. Software could provide automatic switch over to parallel leg.
6. 1 success path remaining after first failure.
7. Cathode-ray tube and downlist is available.

SOUTH AFRICA: RISK AND EFFECTS ANALYSIS - CHAPTER 157

[illegible]

ተክፍተ ልጊዬ ፍሃ፡

٤٠٤

 $x \in L$

G. IRVING

C. A. AKERS

44-38861-24

415

١٢٤

REGULAIR PLEES, INC.

SEVERE - SUBSAFE. LIT. OF UNEQUAL OUTLET PRESSURE (P/P
= 1/207/312/312).

✓ = Yes () = No

TO REGULATE STORED HELIUM PRESSURE FROM 4000 PSIG MAX TO RELEASE
PRESSURE OF 240 (+ OR - 2) PSIG FOR PURPOSE OF PROPELLANT FILL IN
T-BUSTERS. TWO PARALLEL TANKS WITH TWO SERIES REGS ARE PROVIDED FOR
EACH PROPELLANT TANK. PRIMARY ELEMENT SET 11 PSI LOWER THAN SECONDARY.
EXHAUST VALVE: BAILS CLOSED (F)

ATTORNEY GENERAL: FILES CLOSED

• RESTRICTED - FLUSH.

• C, USL(S) :

• LUNAR (FLOYD SCHLIER), FROZEN FOIST, SPRING/STEEL FRACTURE, FISTON
FROGS, FROGS DOGE PRESS, CROCKED SPRINGS, NAT'L LEE.

DEFECT(S): ON (A) CULSYSTEM (B) INTERFACES (C) MISSED (D) OIL / VEHICLE:

• (A₂) LOSS OF REDUNDANCY (ONE OF 2 FEED PATHS). (C) 4-BIT DECISION.

(1) NO EFFECT UNLESS SECOND PATH FAILS CLOSED, RE-ENTRY CAPAB IS LOST IF
FAILURE OCCURS EARLY IN ENTRY SUCH THAT COLLAGE PRESS IS NOT SOFT.

(1) EXISTENTIAL CRITICALITY EFFECT - POSSIBLE CATASTROPHIC LOSS. FAILURE

(2) FUNCTIONAL CRITICALITY EFFECT - POSSIBLE EMPLOYABLE LOSS. FILES -
OF THE HORIZONTAL PARALLEL FIELD. PAIR WOULD RESULT IN INSTABILITY OF

PC PLUMMER'S PROPRIETARY FUEL PAYS NO SIGNIFICANT INFLUENCE ON THE
FUEL'S PROPELLANT. THIS WOULD RESULT IN POSSIBLE LIABILITY TO

EXHAUST GAS PROPPELLANT. THIS WOULD RESULT IN POSSIBLE INABILITY TO
CONTROL VEHICLE DURING ENTRY DUE TO INABILITY TO USE RESERVED ENTRY

CONTROL VEHICLE DURING ENTRY DUE TO INABILITY TO USE RESERVED ENTRY
PROPELLANT ON C.B. PROBLEMS RESULTING FROM PROPELLANT POLYMER.

APPLICATION, ACTION:

- UTILIZE SERIAL PATH. IF BOTH PATHS ARE FAILED CLOSED EVAL ALL IN ALL 100 PPS. INTERCONNECT WITH CMC MAY BE UTILIZED.

• 3144845/42, 1, 2 :

• PRESS ADVISORY EFFECT OF VEH BYN IF PROX CANNOT BE DEPLETED PRIOR TO
LNDG. FUELION MOIST CONTENT CONTROL REQ'D. SEE FAIRCHILD T4EA
047-139-11 STAND-BY RECORD OF REGULATOR FLOW PATHS IS 0111. SEE HAZ 11
100X-1302-10

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - C2BITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -201030-2 REV: 11/08/75
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 12
 .P/N RI : MC284-0418-0001/-0002 CRIT. HOW: 2
 .P/N VENDOR: 74339C01 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 8 PHASE(S): PL LO X CC X DC X LS
 . : TWO PARALLEL, DUAL
 . : STAGE UNITS PER TANK
 . : REDUNDANCY SCREEN: A-PASS B-PASS C-PASS
 .PREPARED BY: J. TAGGART APPROVED BY: APPROVED BY (NASA):
 .DES DES REL REL REL
 .REL C M AKERS REL REL REL
 . : APPROVED WITH CHANGES
 . : See Section 13.0
 .ITEM: REGULATOR PRESS, HE
 . SERIES REDUNDANT. SET AT UNEQUAL OUTLET PRESSURES (PP
 301/302/303/304).
 .FUNCTION:
 . TO REGULATE STORED HELIUM PRESSURE FROM 4000 PSIG MAX TO ULLAGE
 PRESSURE OF 245 (+ OR - 3) PSIG FOR PURPOSE OF PROPELLANT FEED TO
 THRUSTERS. TWO PARALLEL PATHS WITH TWO SERIES REGS ARE PROVIDED FOR
 EACH PROPELLANT TANK. PRIMARY ELEMENT SET 11 PSI LOWER THAN SECONDARY.
 .FAILURE MODE: FAILS CLOSED (F)
 . RESTRICTED FLOW.
 .CAUSE(S):
 . CONTAM (PILOT SCREEN), FROZEN MOIST, SPRING/STEM FRACTURE, PISTON
 BINDS, EXCESS DOME PRESS, COCKED SPRINGS, MAT'L DET.
 .EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 . (A,B) LOSS OF REDUNDANCY (ONE OF 2 FLOW PATHS). (C) ABORT DECISION.
 . (D) NO EFFECT UNLESS SECOND PATH FAILS CLOSED, REENTRY CAPAB IS LOST IF
 FAILURE OCCURS EARLY IN ENTRY SUCH THAT ULLAGE PRESS IS NOT SUFF.
 . (E) FUNCTIONAL CRITICALITY EFFECT - POSSIBLE CREW/VEHICLE LOSS. FAILURE
 OF REDUNDANT PARALLEL FLOW PATH WOULD RESULT IN INABILITY TO BURN OR
 DEplete RCS PROPELLANT. THIS WOULD RESULT IN POSSIBLE INABILITY TO
 CONTROL VEHICLE DURING ENTRY DUE TO INABILITY TO USE PRESERVED ENTRY
 PROPELLANT OR C.G. PROBLEMS RESULTING FROM PROPELLANT WEIGHT.
 .DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
 . (A) PARALLEL REGULATORS ARE PROVIDED. ULLAGE PRESS IS ADEQ FOR PROP FEED
 WITH LESS THAN 35 PERCENT PROP REMAINING. A 25-MICRON ABS GBR PLUS
 10-MICRON ABS GBR PILOT FILTER IS PROV TO LIMIT THE POSSIBILITY OF
 CONTAM CAUSING JAMMING OF MOVING PARTS OR PLUGGING PILOT CONTROL
 ORIFICES. (B) 50,000 OPER FLOW CYCLES AND RANDOM VIB AT ANTIC MISSION
 LEVELS ARE PERFORMED DURING QUAL. ITEM IS USED DURING SYS EVAL TESTS AT
 WSTF ALLOWING EVAL UNDER SIMUL MISSION USAGE COND. PROOF PRESS, LEAKAGE
 AND FLOW TESTING IS PERFORMED DURING ATP. FUNCT AND LEAKAGE TESTS ARE
 PERFORMED DURING PRE/POST FLIGHT CHECKOUT. (C) AN ID IS PERF AND THE
 UNIT TAGGED. MAT'L & EQUIP CONFORMANCE TO CONTRACT REQMTS IS VERIF BY
 INSP. THE FOLL ITEMS ARE VERIF BY SHOP TRAVELER MANDATORY INSP POINTS -
 RAW MAT'L, PARTS PROTECTION, MANUF, COATING, PLATING, INSTALL AND ASSY
 OPERATIONS. THE ABOVE ITEMS AND THE FOLL ITEMS WERE VERIF BY AUDIT
 CONDUCTED 4-5-77 - CONTAM CONT PROCESSES AND CORROS PROT PROV, CONTAM
 CONT PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIR. THE FOLLOWING

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201030-2 PEV:11/08/73
ITEMS WERE VERIFIED BY AUDIT OF MARCH 6, 1978. INSPECTION VERIFIES
ASSEMBLY PER INSPECTION POINTS IN MASTER RECORD. LOG OF CLEAN ROOM AND
CALIBRATION OF TOOLS VERIFIED. CRITICAL DIMENSION 100% VERIFIED BY
INSPECTION. PARTS CLEANLINESS AND PASSIVATION BY INSPECTION. NDE
INSPECTION PERFORMED AFTER ASSEMBLY. TURNAROUND - PUNCT FLOW TESTS ARE
MONITORED TO VERIFY THAT THERE IS NO RESTRICTED FLOW. (C) NO FAILURE
HISTORY OF THIS MODE FOR THIS REGULATOR.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT -RCS

FMEA NUMBER 03-2A-201035-1

ITEM Line, Low Pressure He

FAILURE MODE External Leak

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☒ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Ullage transducer will give C&W alert < 200 psi. Gross leak detection will give first indication.

3A. The helium insulation valves could be automatically closed by software upon sensing a caution and warning low pressure of 200 psi.

6. Initiate cross-feed function.

7. Caution and warning low pressure light - "Right RCS" - cathode-ray tube and downlink available.

8B. Same as primary.

STRUCTURE FAILURE MODE AND EFFECTS ANALYSIS - CAPTION 101

1. SYSTEM NAME - REACTION CONTROL
 2. ANALYST - ENGINEERING
 3. P/N 1 - 100-21-0000
 4. P/N 2 - 100-21-0000
 5. QUANTITY - 1
 6. 100-21-0000
 7. 100-21-0000
 8. 100-21-0000
 9. 100-21-0000
 10. 100-21-0000
 11. 100-21-0000
 12. 100-21-0000
 13. 100-21-0000
 14. 100-21-0000
 15. 100-21-0000
 16. 100-21-0000
 17. 100-21-0000
 18. 100-21-0000
 19. 100-21-0000
 20. 100-21-0000
 21. 100-21-0000
 22. 100-21-0000
 23. 100-21-0000
 24. 100-21-0000
 25. 100-21-0000
 26. 100-21-0000
 27. 100-21-0000
 28. 100-21-0000
 29. 100-21-0000
 30. 100-21-0000
 31. 100-21-0000
 32. 100-21-0000
 33. 100-21-0000
 34. 100-21-0000
 35. 100-21-0000
 36. 100-21-0000
 37. 100-21-0000
 38. 100-21-0000
 39. 100-21-0000
 40. 100-21-0000
 41. 100-21-0000
 42. 100-21-0000
 43. 100-21-0000
 44. 100-21-0000
 45. 100-21-0000
 46. 100-21-0000
 47. 100-21-0000
 48. 100-21-0000
 49. 100-21-0000
 50. 100-21-0000
 51. 100-21-0000
 52. 100-21-0000
 53. 100-21-0000
 54. 100-21-0000
 55. 100-21-0000
 56. 100-21-0000
 57. 100-21-0000
 58. 100-21-0000
 59. 100-21-0000
 60. 100-21-0000
 61. 100-21-0000
 62. 100-21-0000
 63. 100-21-0000
 64. 100-21-0000
 65. 100-21-0000
 66. 100-21-0000
 67. 100-21-0000
 68. 100-21-0000
 69. 100-21-0000
 70. 100-21-0000
 71. 100-21-0000
 72. 100-21-0000
 73. 100-21-0000
 74. 100-21-0000
 75. 100-21-0000
 76. 100-21-0000
 77. 100-21-0000
 78. 100-21-0000
 79. 100-21-0000
 80. 100-21-0000
 81. 100-21-0000
 82. 100-21-0000
 83. 100-21-0000
 84. 100-21-0000
 85. 100-21-0000
 86. 100-21-0000
 87. 100-21-0000
 88. 100-21-0000
 89. 100-21-0000
 90. 100-21-0000
 91. 100-21-0000
 92. 100-21-0000
 93. 100-21-0000
 94. 100-21-0000
 95. 100-21-0000
 96. 100-21-0000
 97. 100-21-0000
 98. 100-21-0000
 99. 100-21-0000
 100. 100-21-0000

ORIGINAL PAGE IS
 OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -201035-1 REV: 11/08/78
 .ASSEMBLY : PRESSURIZATION ABCRT: CRIT. FUNC: 1
 .P/N RI : MC621-0059 CPIT. HDW: 1
 .P/N VENDOR: 73A630030 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 4 PHASE(S): PL X LD X CC X DC X LS X
 . : ONE SET PER PROPELLANT
 . : PER MODULE

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY:
 .DES N C GLAVINICH
 .REL C M AKERS

APPROVED BY:
 DES *[Signature]*
 REL *[Signature]* 11/79

APPROVED BY (NASA):
 SSM *[Signature]*
 REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

.ITEM: LINE, LOW PRESSURE HE.
 . FEED LINE (3/4")

.FUNCTION:

. 3/4 X .020 304L S.S LINES TO PROVIDE HELIUM FEED FROM REGULATORS TO
 PROP TANK.

.FAILURE MODE: STRUCTURAL FAILURE (S)

. RUPTURE, EXTERNAL LEAKAGE.

.CAUSE(S):

. MECHANICAL SHOCK, VIBRATION/FATIGUE, IMPROPER INSTALLATION (WELD).
 STRESS CORROS. MAT'L DEFICIENCY (SULPHIDE STRINGER)

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) LOSS OF SUBSYSTEM HELIUM SUPPLY. INABILITY TO DEplete/UTILIZE
 PROPELLANT. (B) LOSS OF INTERFACE FUNCTION INABILITY TO REPRESSURE
 PROP TANK-POTENT POD STRUCTURE & TPS DAMAGE. (C) POTENTIAL LOSS OF
 MISSION OR EARLY MISSION TERMINATION. (D) POTENTIAL LOSS OF
 CREW/VEHICLE IF GROSS LEAK OCCURS OR TPS DAMAGE OCCURS PRECLUDING SAFE
 ENTRY.

.DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

. (A) F.S. IS 1.5 TO 4.0 MAXIMUM OPERATING PRESSURE (SYSTEM RELIEF).
 THE WELDED CONSTRUCTION ELIMINATES JOINTS AND POSSIBLE LEAK PATHS.
 THE ANNEALED AREA (DUE TO WELDING) IS BACKED UP BY A SLEEVE. FASTENING
 CLAMPS ALLOW FREEDOM OF MOVEMENT. TUBING BENDS ARE CONTROLLED
 BETWEEN FIXED POINTS TO FACILITATE INSTALLATION AND ACCOMMODATE
 VEHICLE GROWTH AND MOVEMENT. (B) ROCKWELL PERFORMED TUBING
 CERTIFICATION TESTS PER "ORBITER TUBING VERIFICATION PLAN"
 (SD75-SH-0205). THIS TESTING INCLUDED PRESSURE CYCLING AND FATIGUE FOR
 TYPICAL SHUTTLE LINES & JOINTS. SYSTEM EVALUATION TESTS AT WSTF WILL
 ALSO ALLOW EVALUATION IN THE INSTALLED SYSTEM CONDITION. LEAKAGE TESTS
 ARE PERFORMED IN-PROCESS FOR TUBING SECTIONS. OPTICAL INSPECTIONS ARE
 ALSO PERFORMED AT THIS TIME IN ADDITION TO X-RAY AND DYE PENETRANT.
 LEAKAGE TESTS ARE ALSO PERFORMED AFTER INSTALLATION INTO THE SYSTEM AND
 ADDITIONAL WELDS ARE ALSO SUBJECTED TO NDE. (C) AN IDENTIFICATION IS
 PERFORMED AND THE UNIT TAGGED. CONTAM. CONTRCL PROCESSES, CORROS.
 PROTECTION PROVISIONS, NDE EXAM OF WELDS AND INSP. FOR SURFACE AND
 SUB-SURFACE DEFECTS IS VERIFIED BY INSPECTION. THE FOLLOWING ITEMS ARE
 VERIFIED BY SHOP TRAVELER MANDATORY INSP. POINTS, RAW MAT'L (LOT
 CERTIFICATION), PARTS PROTECTION, MANUF., COATING, PLATING, INSTALLATION
 AND ASSEMBLY OPERATIONS. HARDWARE IS INSP. IN ACCORDANCE WITH QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NG 03-2A -201035-1 REV:11/03/73
PLANNING REQMITS DOCUMENT (QPRD) WHICH HAS BEEN APPROVED BY NASA.
TURNAROUND. LINES IN ACCESSIBLE AREAS ARE VISUALLY INSPECTED FOR
EVIDENCE OF DAMAGE AND FLOW AND PRESSURE FUNCTIONAL TESTS ARE MONITORED
FOR EVIDENCE OF OBSTRUCTION OR LEAKAGE. (D) MINOR HISTORY -
CORROSION/FAB PROBLEMS DETECTED DURING APOLLO CHECKOUT AND CORRECTED.
HISTORY - CORROSION/FAB PROBLEMS DETECTED DURING APOLLO CHECKOUT AND
CORRECTED.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-201060-4

ITEM Relief Valve

FAILURE MODE External Leak -- Fails Open

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☒ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Gross leak detection will give first indication.
- 1a. Measurements V42P2115, 2116, 3115, and 3116 provide propellant tank ullage pressure signals from transducers.
6. Left and right AFT RCS pods provide redundancy.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

2

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -201060-# REV: 12/14/78
 . ASSEMBLY : PRESSURIZATION. ABCRT: CRIT. FUNC: 1R
 . P/N RI : MC284-0421-0001/-0002 CRIT. HDW: 2
 . P/N VENDOR: 5760009-101/576-0009-102 MISSIONS: HF VF X FF OF SM
 . QUANTITY : 4 PHASE(S): PL LO X CO X DO X LS
 . : ONE PER PROPELLANT TANK

REDUNDANCY SCREEN: A-PASS B-FAIL C-PASS

PREPARED BY: DES R. GONZALEZ R.G. DES APPROVED BY: APPROVED BY (NASA):
 . REL C M AKERS REL REL SSM
 . APPROVED WITH CHANGES
 . See Section 13.0

ITEM: VALVE
 . RELIEF, PRESSURE, BURST DISC & POPPET.

- FUNCTION:
- PROVIDES PRESSURE RELIEF IN EVENT REGULATOR FAILS OPEN OR PROPELLANT PRESSURE RISES DUE TO THERMAL INCREASE. THE S.S. BURST DISC RELIEF PRESSURE IS 324-340 PSIG. THE MAIN POPPET CRACK AND RELIEF PRESSURE IS 315 PSIG AND THE MINIMUM RESEAT PRESSURE IS 310 PSI. AMBIENT PRESSURE SENSING INTERNAL IS PROVIDED SINCE THE VALVE OUTLET IS SUBJECTED TO BACK-PRESSURE.
 - FAILURE MODE: EXTERNAL LEAK (F)
 - FAILS OPEN, MAIN POPPET OR DIAPHRAGM LEAKS OR MAIN POPPET DOES NOT RESEAT AS REQ'D AFTER BURST DISC RUPTURE.
 - CAUSE(S):
 - CORROSION, CONTAMINATION, POPPET BINDS IN GUIDE, SPRING BREAKS OR COCKS, SEAT CRACKS, MOISTURE FREEZES, VIBRATION, SHOCK.
 - EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 - (A) LOSS OF SUBSYSTEM PRESSURIZATION. (B) LOSS OF INTERFACE FUNCTION. (INABILITY TO RE-PRESSURIZE PROPELLANT TANKS DUE TO HELIUM LOSS). POSSIBLE INABILITY TO USE/DEplete PROPELLANT. (C) LOSS OF ENTRY CAPABILITY - ASSUMES ULLAGE PRESSURE IS ALSO VENTED OVERBOARD & PROP CANNOT BE DEPLETED. (2 FAILURES - FIRST IS RELIEF REQ'T). ABORT DECISION IF LEAK RATE IS SMALL. (D) NO EFFECT (FIRST FAILURE. (E) FUNCTIONAL CRITICALITY EFFECT - POSSIBLE LOSS OF CREW VEHICLE - SEE ITEM (C) ABOVE. PROP IN ONE POD MAY NOT BE ADEQUATE FOR ENTRY. POSS ENTRY CONTROL & LANDING HAZARD. (C.G.) IF PROP CANNOT BE DEPLETED PRIOR TO LANDING.
 - DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
 - (A) THE BURST DISC IS REDUNDANT TO THE MAIN POPPET FOR THE EXTERNAL LEAKAGE MODE. (MAIN POPPET LEAKAGE WOULD NOT BE SENSED UNTIL AFTER BURST DISC ACTUATION OR FAILURE). A 25-MICRON FILTER DOWNSTREAM OF THE BURST DISC WILL REDUCE THE POTENTIAL FOR CONTAMINATION CAUSED LEAKAGE FAILURE. THE HELIUM ISOLATION VALVE COULD BE CLOSED DURING STATIC PERIODS. THIS WOULD PREVENT CONTINUING LOSS OF SOURCE PRESSURE. THE MAIN POPPET STEM IS A SEPARATE PIECE FROM THE MAIN SENSING SPRING ACTUATION MECHANISM. THIS PROVIDES CLOSE TOLERANCE CONTROL OF OPENING PRESSURE & ALLOWS THE POPPET TO SEAT INDEPENDENTLY OF THE LARGE SENSOR SPRING FORCE. (B) 36,000 PRESSURE EXCURSION CYCLES AT SYSTEM OPERATING

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-24 -201060-4 REV:12/14/73
PRESSURE AND 400 PRESSURE RELIEF CYCLES ARE CONDUCTED DURING QUAL.
(C) AN IDENTIFICATION IS PERFORMED CONTAMINATION CONTROL PROCESS,
CONTAMINATION CONTROL PLAN, CORROS, PROTECTION PROVISION, NDE EXAM OF
WELDS, INSP FOR SURFACE AND SUBSURFACE DEFECTS, PROPERLY MONITORED
HANDLING AND STORAGE ENVIRONMENT, AND MAT'L AND EQUIP, CONFORMANCE TO
CONTRACT REQMTS. ARE VERIFIED BY INSP. THE FOLLOWING ITEMS ARE VERIFIED
BY SHOP TRAVELER MANDATORY INSP POINTS-RAW MAT', (LOT CERTIFICATION),
PARTS PROTECTION, MANUF., COATING, PLATING, INSTALLATION AND ASSY
OPERATIONS. TURNAROUND - LEAKAGE TESTS ARE MONITORED TO VERIF. THAT THE
BURST DISC IS STILL INTACT AND THAT THE MAIN POPPET LEAK RATE IS WITHIN
SPECIFICATION REQMTS. VISUAL INSP FOR EVIDENCE OF DETERIORATION IS ALSO
PERFORMED. (D) APOLLO FAILURES WERE DUE LARGELY TO GALVANIC CORROS. &
CONTAMINATION CORRECTED BY DESIGN & TEST PROCESSING CHANGES. (THE
SHUTTLE RELIEF VALVE IS A NEW DESIGN WHICH CONTAINS A FILTER & DOES NOT
USE DISSIMILAR METALS).

4
,
2
9
4
1

TIME TO REFLECT:
 IMMEDIATE TO MAYO
 FURTHER DOCUMENTS.
 60 811-004
 5070-1001-010
 5072-SF-0100-7
 5070-421001

APPROVED : Y :

100
REL

* FULLER, PETER, BORN DISC & MODEL. RV 201/202/203/204. DIS PSIA.
RV 201/202/203/204.

PROVIDES PRESSURE RELIEF IN EVENT REGULATOR FAILS WHEN IT PROMPTLY AT
EXISTING LINES DUE TO THERMAL INCREASE. THE S&S. MUST ALSO RELIEF
PRESSURE IS 324-340 PSIG. TOP MAIN PIPELINE CRACK AND RELIEF PRESSURE IS
215 PSIG AND THE MINIMUM RESET PRESSURE IS 310 PSI. A LIFTING PRESSURE
SERVING INFLUENCE IS PROVIDED SINCE THE VALVE OUTLET IS SUBJECTED TO
BACK-PRESSURE.

• FALLS OPEN, MAIN POPPET OR LIAPRAPHM LEAKS OR MAIN POPPET CLOS NOT
SEPARATES 1/2" TO AFTER FIRST DISC RUPTURE.

- CORROSION, CONTAMINATION, POCKET SIZES IN COILS, SPRING ECLARS ON COILS, SEAT CRACKS, MOISTURE FREEZES, VIBRATION, SHOCK.

- (1) LOSS OF SOLUBLE PRECURSORS. (2) LOSS OF INTERFAC. REACTION.

Possible inability to use/deplete propellant. (C) Loss of battery

CONFIDENTIAL. 12 FAILURES - FIRST IS BELIEF OF "HILL". AR/1

• FUNCTIONAL CRITICALITY EFFECT - POSSIBLE LOSS OF TOWN VEHICLE - SEE

ENTRY CONTROL & LANDING HAZARD (C.G.) IF PRDP CANNOT BE LIFTED PRIOR

*CLIPPING: PULL:

IS NOT ADOPTED FOR ENTRY. DEPOSITE DISABLE POD PRUP FIRST TIME POSSIBLE

1
—
4
• 11
11
11

NY 62-117147

ORIGINAL PAGE IS
OF POOR QUALITY

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-201070-1

ITEM He Fill Quick Disconnect

FAILURE MODE Fails Open

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-Flight detectability

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Gross leak detection will give first indication.
6. Capped quick disconnect provides one redundant success path.
Pod Redundancy

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -201070-1 REV: 12/12/78
 .ASSEMBLY : PRESSURIZATION ABORT: CRIT. FUNC: 1
 .P/N RI : MC276-0C17-0402/-0403 CRIT. HOW: 1
 .P/N VENDOR: 7537200C-0401/-0403 MISSIONS: HF VF X FF OF SM
 .QUANTITY : 4 PHASE(S): PL X LO X CC X DO X LS X
 . : ONE PER HELIUM TANK PER
 . : POD

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY: DES C SCARLETT APPROVED BY: DES C. Scarlett 12/15/78 APPROVED BY (NASA): SSM W. K. Kinsler
 .REL C M AKERS REL C. E. Danner 1/2/79 REL W. K. Kinsler
 . : APPROVED WITH CHANGES
 . : See Section 13.0

- .ITEM: DISCONNECT, QUICK, FILL, HE
- . (1/4") WITH SPRING LOADED POPPET AND STRUCTURAL END CAP. NO 219/220
- .FUNCTION:
- . PROVIDE HELIUM TANK FILL AND VENT POINT FOR GROUND SERVICING OPERATIONS AND LOADING. COUPLING IS ACCESSIBLE AT THE HELIUM SERVICING PANEL.
- .FAILURE MODE: FAILS OPEN (S)
- . EXCESS OF ACCEPTABLE RATE, SEALS DAMAGED.
- .CAUSE(S):
- . CONTAMINATION, VIBRATION, MECHANICAL SHOCK, PIECE-PART STRUCTURAL FAILURE, EXCESS OR IMPROPER USE, INADEQ MAINT OF GSE HALF, NO LINE SUPPORT - SHAFT OR BORE BENT. RETAINING CAP LOOSENS NEGATING CAP SEAL REDUNDANCY.
- .EFFECT(S): ON (A) SUBSYSTEM (4) INTERFACES (C) MISSION (D) CREW/VEHICLE:
- . (A) LOSS OF SUB-SYSTEM PRESSURIZATION. (B) LOSS OF INTERFACE FUNCTION (INABILITY TO REPRESSURIZE PROPELLANT TANKS DUE TO HELIUM LOSS). (C) LAUNCH DELAY OR ABORT. (D) POTENTIAL CREW LOSS DURING MISSION IF PROPELLANT CANNOT BE UTILIZED OR DEPLETED.
- .DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
- . (A) F.S. IS 2.0 X WORKING PRESS. ULLAGE PRESS IS ADEQ TO EXPEL PROP WITH 35 PERCENT OR LESS REMAINING. GROUND HALF COUPLINGS AND LINES ARE SUPPORTED TO LIMIT ANY UNDEQ STRESS ON THE COUPLING DURING SERVICE AND PREV DAMAGE TO SEALS. A SAFETY FEATURE DURING SERVICING AND PRIOR TO REMOVAL OF THE END CAP IS A PROV WHEREBY ANY LEAKAGE PAST THE AIRBORNE POPPET SEAL CAN BE VENTED OVERBOARD BY ROTATING A BLEED SCREW. COMPLETE STRESS ANAL HAS BEEN CONDUCTED. UTIL OF STRUCT CAP MINIMIZES LEAKAGE POTENTIAL AND PROVIDES A REDUN SEAL EXCEPT FOR STRUCT FAILURE. (B) THE COUPLING IS SUB TO 600 OPERATIONAL CYCLES (COUPLING AND UNCOUPLING) DURING QUAL. RANDOM VIB TESTING IS ALSO CONDUCTED AT ANTIC VEH LEVELS FOR 48 MINUTES IN TWO AXES. USAGE DURING SYS EVAL TESTS AT WSTF ALLOWS EVAL UNDER ACTUAL USAGE CON. PROOF PRESS TESTS ARE CONDUCTED DURING ATP AND LEAKAGE TESTS ARE PERF BEFORE AND AFTER OPER CYCLES. (C) AN IDENT IS PERF. RAW MAT'L, NDE EXAM, VISUAL INSP FOR CRITICAL SURFACE DEFECTS, AND EQUIP CONFORMANCE TO CONTRACT REQMTS ARE VERIF BY RECEIVING INSP. MEASUREMENT STANDARDS AND TEST EQUIP. STANDARDS ARE IMPLEMENTED PER REQMTS OF MIL SPEC. THE FOLLOWING ITEMS ARE VERIF BY SHCP TRAVELER MANDATORY INSP POINTS. PARTS MFG. PROCESSES, COATING, ASSY AND INSTALLATION. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 5-23-77. CORROS PROT PROV, CONTAM CONT PRCCESSES, TEST

SHUTTLE CRITICAL ITEMS LIST - CR3ITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201070-1 REV:12/12/78
HANDLING, AND STORAGE ENVIR. THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT
OF MARCH 6, 1978. INSPECTION VERIFIES ASSEMBLY PER INSPECTION POINTS IN
MASTER RECORD. LOG OF CLEAN ROOM AND CALIBRATION OF TOOLS VERIFIED.
CRITICAL DIMENSION 100% VERIFIED BY INSPECTION. PARTS CLEANLINESS AND
PASSIVATION VERIFIED BY INSPECTION. NDE INSPECTION PERFORMED AFTER
ASSEMBLY. TURNAROUND. COUPLINGS ARE VISUALLY INSP FOR EVID OF DAMAGED
SEALS AND LEAK TESTS ARE PERFORMED. (C) APOLLO FAILURE HISTORY WAS IN
THE MAIN ASSOC WITH GROUND USAGE, IMPROPER HANDLING.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-201080-1

ITEM Purge Quick Disconnect, Propellant

FAILURE MODE External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Gross leak detection will give first indication.
2. The above statement indicates in-flight detection.
6. Need minimum of 2 yaw thrusters. Cross-feed is available. Pods are redundant.

100

DECLASSIFIED IN FULL? ☐ NO

✓ 16 JUL 1968 P-01108

PROBABLE SOURCE: GARY FALL 6-70

1156-10-448501;
 500125-10-5071
 500022-10-50004-018;
 50 001-009
 50070-5001-015
 5072-50-0103-2
 5070-401-01

APPROVED BY:

C. SCARLETT

31

K. i.

C. H. AKERS

351

• VENT, PROPELLANT WITH STRUCTURAL END CAP AND STRING LOADED PUFFET (1/2").

- TREATMENT OF AND PURGE OF PROPELLANT MANIFOLDS DURING TOWARDABLE OPERATIONS.

- O-RING LEAKS, SEALS DAMAGED RETAINING NUT LOOSENS NEGATIVE CAP SEAL
FROM ARMY.

- VIBRATION. PIECE PART STRUCTURAL FAILURE, CONTAMINATION, MECHANICAL STRESS, SEAL DAMAGES, INADEQ MAINT OF GSE WALK, NO LINE SUPPORT - STAFF USE LIFE LINE

• (A,*) LOSS OF REDUNDANCY (ONE COUPLING -CS EACH OF 2 VARIABLES -

PROPELLANT SAVIHFIED ISOLATION VALVE COULD ISOLATE LEAK. (C) DESIGN MODIFICATION OR ALERT DECISION. (D) NO EFFECT UNLESS MULTIPLE FAILURES OCCUR OR EXCESS LOSS OF PROPELLANT OCCURS. (E) FUNCTIONAL CRITICALITY EFFECT - MULTIPLE CSM/VEHICLE LOSS - LOSS OF RCS ENTRY FROM LEAK. POSSIBLE LOSS OF VEHICLE CONTROL DURING ENTRY.

- DETERMINE LEAK LOCATION. CLOSE DEPLELLANT MANIFOLD ISOLATION VALVE.
EVALUATE NEXT ID ABORT.

- POTENTIAL CORROSION TO SURROUNDING AREA. CAP CONSIDERED AS STRUCTURE, POTENTIAL TOXIC & FIRE, OR EXPLOSIVE HAZARD (IF HIGH TEMPERATURE OR REACTANTS ARE PRESENT). REF HAZ NO 1YXX-0304-04.

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201080-1 REV:11/08/73
 .ASSEMBLY :PRESSURIZATION ABORT: CRIT. FUNC: 1R
 .P/N RI :MC276-0018 CRIT. HDW: 2
 .P/N VENDOR:76361000 & 76316000 MISSIONS: HF VF X FF CF SM
 .QUANTITY :28 PHASE(S): PL LQ X CG X DO X LS

. :
 . :14 PER POD
 . :12 OF 1/2 IN.
 . :2 OF 1/4 IN.

REDUNDANCY SCREEN: A-PASS B-FAIL C-PASS

.PREPARED BY: C SCARLETT
 .DES C SCARLETT
 .REL C M AKERS

APPROVED BY:
 DES C. Scarlett 12/5/78
 REL C. E. James 12/1/78

APPROVED BY (NASA):
 SSM W. K. Smith
 REL W. K. Smith

APPROVED WITH CHANGES
 See Section 13.0

.ITEM: DISCONNECT, QUICK, PURGE.
 . VENT, PROPELLANT WITH STRUCTURAL END CAP AND SPRING LOADED POPPET
 (1/2" & 1/4 IN.).

.FUNCTION:
 . TO ALLOW GROUND PURGE OF PROPELLANT MANIFOLDS DURING TURNAROUND
 OPERATIONS.
 .FAILURE MODE: EXTERNAL LEAKAGE (S)
 . CAP LEAKS, SEALS DAMAGED RETAINING NUT LOOSENS NEGATING CAP SEAL
 REDUNDANCY.

.CAUSE(S):
 . VIBRATION, PIECE PART STRUCTURAL FAILURE, CONTAMINATION, MECHANICAL
 SHOCK. SEAL DAMAGE, INADEQ MAINT OF GSE HALF, NO LINE SUPPORT - SHAFT
 OR BORE BENT

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 . (A,B) LOSS OF REDUNDANCY

(PROPELLANT MANIFOLD ISOLATION VALVE COULD ISOLATE LEAK). (C) MISSION
 MODIFICATION OR ABORT DECISION. (D) NO EFFECT UNLESS MULTIPLE FAILURES
 OCCUR OR EXCESS LOSS OF PROPELLANT OCCURS. (E) FUNCTIONAL CRITICALITY
 EFFECT - POSSIBLE CREW/VEHICLE LOSS - LOSS OF RCS ENTRY PROPELLANT.
 POSSIBLE LOSS OF VEHICLE CONTROL DURING ENTRY.

.DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
 . (A) F.S. IS 2.0 X WORKING PRESS. REDUNDANCY PROVIDED BY INTERNAL SEAL,
 CAP & MANIFOLD ISOLATION VALVE. GROUND HALF COUPLINGS AND LINES ARE
 ADEQ SUPPORTED TO LIMIT ANY UNDEQ STRESS ON THE COUPLING DURING SERVICE
 AND PREV DAMAGE TO SEALS. A SAFETY FEATURE DURING SERVICING AND PRIOR
 TO REMOVAL OF THE END CAP IS A PROV WHEREBY ANY LEAKAGE PAST THE
 AIRBORNE POPPET SEAL CAN BE VENTED OVERBOARD BY ROTATING A BLEED SCREW.
 COMPLETE STRESS ANAL HAS BEEN CONDUCTED. UTIL OF STRUCT CAP MINIMIZES
 LEAKAGE POTENTIAL AND PROVIDES A REDUM SEAL EXCEPT FOR STRUCT FAILURE.
 FAILURE CAN BE ISOLATED AT MANIFOLD VALVE. (B) THE COUPLING IS SUBJ TO
 600 OPER CYCLES (COUPLING AND UNCOUPLING) DURING QUAL IN ADDITION TO
 PRESS SURGE CYCLING AND PROP EXPOSURE TESTS. RANDOM VIB TESTING IS
 ALSO CONDUCTED AT ANTIC VEH LEVELS FOR 34 MINUTES IN EACH-AXIS. USAGE
 DURING SYS EVAL TESTS AT WSTF ALLOWS EVAL UNDER ACTUAL USAGE COND.
 PROOF PRESS TESTS ARE CONDUCTED DURING ATP AND LEAKAGE TESTS ARE PERF
 BEFORE AND AFTER OPER CYCLES. (C) AN IDENT IS PERF. RAW MAT'L, NDE
 EXAM. VISUAL INSP FOR CRITICAL SURFACE DEFECTS, AND EQUIP CONFORMANCE TO
 CONTRACT REQMTS ARE VERIF BY RECEIVING INSP. MEASUREMENT STANDARDS AND

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201080-1 REV:11/08/78
TEST EQUIP. STANDARDS ARE IMPLEMENTED PER REQMTS OF MIL SPECS. THE
FOLLOWING ITEMS ARE VERIF BY SHOP TRAVELER MANDATORY INSP POINTS-PARTS
PROT, MFG. PROCESSES, COATING, ASSY AND INSTALLATION. THE ABOVE ITEMS
AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 5-23-77.
CORROS PROT, PROV CONTAM CONT PROCESSES, TEST HANDLING, AND STORAGE
ENVIR. THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT OF MARCH 6, 1978.
INSPECTION VERIFIES ASSEMBLY PER INSPECTION POINTS IN MASTER RECORD.
LOG OF CLEAN ROOM AND CALIBRATION OF TOOLS VERIFIED. CRITICAL DIMENSION
100% VERIFIED BY INSPECTION. PARTS CLEANLINESS AND PASSIVATION VERIFIED
BY INSPECTION. NDE INSPECTION PERFORMED AFTER ASSEMBLY.
TURNARCUND-COUPPLINGS WILL BE VISUALLY INSPECTED FOR EVIDENCE OF CAP SEAL
DAMAGE AND CAP LEAKAGE. (D) APOLLO FAILURE HISTORY WAS IN THE MAIN
ASSOC WITH GROUND USAGE, IMPROPER HANDLING.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-201090-1

ITEM Test Quick Disconnect

FAILURE MODE External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Gross leak detection gives first indication.
2. FMEA change - in flight detectability should include above measurement numbers.
6. Pod redundancy.

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 1039 1040 1

SD 72-51-113-

ΔΓΕΝ: Vελ = 1:

455

xiii

1. 01. (1747) WITH SPRING LOADED JOINTS AND STRUCTURAL LAY OUT. 20

3. PROVIDE ACCESS TO THE PRESSURE SUPPLY SYSTEM AT VARIOUS POINTS IN THE SYSTEM (RELIEF VALVES/ CUSH PIPES, ACCURATORS, CHECK VALVES). PROVIDED FOR EACH OF PRESSURE SUPPLY COMPONENTS. COMPONENT INPUTS & OUTPUTS ARE ACCESSIBLE AT THE SERV. PANEL. THE END CAP PROVIDES REDUNDANCY FOR INTERNAL LINES.

(5)

7-25-68 (1) :

• (PREFIGURES): (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CMTL./VEHICLE:

- LOSS OF INTERFACIAL FUNCTION (LOSS OF PROPELLANT FUEL CAPABILITY). (CFC) NO EFFECT DUE TO RELEVANT SUPPORT CODES AND USE.
- FUNCTIONAL CRITICALITY EFFECT - POSSIBLE CREW/VEHICLE LOSS. LOSS OF PRESSURE RESULTS IN INABILITY TO BURN OR DEplete RCS PROPELLANT. THIS WOULD RESULT IN POSSIBLE INABILITY TO CONTROL VEHICLE DURING EMERGENCY INABILITY TO USE RESERVED ENTRY PROPELLANT OR C.C. PROPELLANT (RESULTING FROM PROPELLANT WEIGHT).

- ISOLATE LEAK IF POSSIBLE. CONSULT USAGE OF ULLAGE PRESSURIZATION AND NECESSITY FOR ALERT. CLOSE ISOLATION VALVE DURING STATIC PERIODS.

- FAILURE MUST PROBABLY DURING GROUND USAGE. GSE LINES MUST BE SUPPLIED. POSSIBLE ADVERSE EFFECT ON VEHICLE DYNAMICS IF PROP CANNOT

CRITICAL FAILURE MODE AND EFFECTS ANALYSIS - CFFMA 100

SUBSYSTEMS: 1 - SECTION CONTROL FILE NO 01-2A-101000-1 0000000000
 1 - TELETYPE UNIT REF FILE NO 1000000000-1

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201090-1 REV:12/12/70
 .ASSEMBLY :PRESSURIZATION ABORT: CRIT. FUNC: 12
 .P/N RI :ME270-0032-0005,7,19,21 CRIT. HOW: 3
 .P/N VENDOR:RR42670-5,-7RG42900-18-3 MISSIONS: HF VF X FF CF SM
 .QUANTITY :36 PHASE(S): PL LD X GC X OG X LS
 . :18 PER MODULE

REDUNDANCY SCREEN: A-FAIL B-FAIL C-PASS

PREPARED BY: DES C SCARLETT APPROVED BY: DES *C. Scarlett 12/15/70* APPROVED BY (NASA): *W. Karasulu*
 REL C M AKERS REL *C.E. Samuel 12/17* REL *W. Karasulu*

APPROVED WITH CHANGES
 See Section 13.0

.ITEM: DISCONNECT, QUICK, TEST

. PT. (1/4") WITH SPRING LOADED POPPET AND STRUCTURAL END CAP. NO
 201-204/207-216/301-304/207-316

.FUNCTION:

. TO PROVIDE ACCESS TO THE HELIUM SUPPLY SYSTEM AT VARIOUS POINTS IN THE
 SYSTEM (RELIEF VALVES/BURST DISCS REGULATORS, CHECK VALVES). PROVIDES
 FOR C/O OF PRESS SUB-SYS COMPONENTS. COMPONENT INPUTS & OUTPUTS ARE
 ACCESSIBLE AT HE SERV PANEL. THE END CAP PROVIDES REDUNDANCY FOR
 EXTERNAL LEAK.

.FAILURE MODE: EXTERNAL LEAKAGE (S)

. CAP LEAKS, SEALS DAMAGED.

.CAUSE(S):

. VIBRATION, PIECE PART STRUCTURAL FAILURE (POPPET, SEAL), MECHANICAL
 SHOCK. EXCESS TORQUE, SEAL DAMAGE, INADEQ MAINT OF GSE HALF, NO LINE
 SUPPORT - SHAFT OR BORE BENT.

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) LOSS OF SUBSYSTEM PRESSURIZATION OR REDUNDANCY DEPENDING ON
 LOCATION. (B) LOSS OF INTERFACE FUNCTION (LOSS OF PROPELLANT FEED
 CAPABILITY). (C,D) NO EFFECT DUE TO REDUNDANT POPPET SEALS & END CAP.
 (E) FUNCTIONAL CRITICALITY EFFECT - POSSIBLE CREW/VEHICLE LOSS. LOSS
 OF PRESSURANT RESULTS IN INABILITY TO BURN OR DEplete RCS PROPELLANT.
 THIS WOULD RESULT IN POSSIBLE INABILITY TO CONTROL VEHICLE DURING ENTRY
 DUE TO INABILITY TO USE RESERVED ENTRY PROPELLANT OR C.G. PROBLEMS
 RESULTING FROM PROPELLANT WEIGHT.

.DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

. (A) F.S. IS 2.0 X WORKING PRESS. ULLAGE PRESS IS ADEQ TO EXPEL PRGP
 WITH 35 PERCENT OR LESS REMAINING. GROUV HALF COUPLINGS AND LINES ARE
 ADEQ SUPPORTED TO LIMIT ANY UNDUE STRESS ON THE COUPLING DURING SERVICE
 AND PREV DAMAGE TO SEALS AND WELD JOINTS. A SAFETY FEATURE DURING
 SERVICING AND PRIOR TO REMOVAL OF THE END CAP IS A PROV WHEREBY ANY
 LEAKAGE PAST THE AIRBORNE POPPET SEAL CAN BE VENTED OVERBOARD BY
 ROTATING CAP. UTIL OF STRUCT CAP MINIMIZES LEAKAGE POTENTIAL AND
 PROVIDES A REDUN SEAL EXCEPT FOR STRUCT OR WELD FAILURES. (B) THE
 COUPLING IS DESIGNED FOR 400 OPER CYCLES (COUPLING AND UNCOUPLING).
 USAGE DURING SYS EVAL TESTS AT WSTF ALLOWS EVAL UNDER ACTUAL USAGE COND.
 PROOF PRESS TESTS ARE CONDUCTED DURING ATP AND LEAKAGE TESTS ARE PERF
 BEFORE AND AFTER OPER CYCLES. (C) AN IDENT IS PERF AND THE UNIT TAGGED.
 RAW MAT'L, NOE EXAM OF WELOS, VISUAL INSP. OF WELD JOINTS FOR

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201090-1 REV:12/12/78
CONFORMANCE TO STANDARD WELD PRACTICE, SURFACE DEFECTS, AND EQUIP
CONFORMANCE TO CONTRACT REQTS ARE VERIF BY RECEIVING INSP. MEASUREMENT
STANDARDS AND TEST EQUIP. STANDARDS ARE IMPLEMENTED PER REQTS OF MIL
SPECS. THE FOLLOWING ITEMS ARE VERIF BY SHOP TRAVELER MANDATORY INSP
POINTS- PARTS PROT, MFG. PROCESSES, COATING, PLATING, ASSY AND
INSTALLATION. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY
AUDIT CONDUCTED 11-3-76. COMPDS PROT PROV, CONTAIN CONT PROCESSES, TEST
HANDLING, AND STORAGE ENVIR. TURNAROUND- COUPLINGS WILL BE VISUALLY
INSPECTED FOR EVIDENCE OF SEAL DAMAGE AND CAP LEAKAGE. (COUPLINGS
BETWEEN THE HELIUM ISOL VALVE & REGULATOR & THOSE ASSOCIATED WITH PROP
TANK C/O ARE NOT ACCESSIBLE AT SERVICING PANELS) (D) ACCLO FAILURE
HISTORY WAS IN THE MAIN ASSOC WITH GROUND USAGE, IMPROPER HANDLING.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-201095-2

ITEM He Quad Check Valve

FAILURE MODE Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☐ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1 & 2. Upon using the thrusters, propellant tank ullage pressure will decay until <200 psi which will give a class 2 alarm, caution and warning. (Red Light)

SEATTLE FAILURE MODE AND EFFECTS ANALYSIS - DEFINITION

SYSTEM NAME - REACTION CONTROL
 ANALYSIS DESCRIPTION
 ANALYST - [REDACTED]
 DATE - [REDACTED]
 FACILITY - [REDACTED]
 PART NAME - HELIUM SUPPLY
 PART NUMBER
 PART DESCRIPTION
 PART QUANTITY
 PART WEIGHT
 PART MATERIAL
 PART FINISH
 PART TOLERANCE
 PART TEST POINTS
 PART EQUIP

EXHA NO 02-74-10105-1
 REPORT
 MISSILES: [REDACTED]
 PHASE(S): [REDACTED]
 NUMBER OF SUCCESS STATES DURING
 AFTER FIRST FAILURE:
 REDUNDANCY SURF AT: [REDACTED]
 TIME TO EFFECT:
 MINUTES
 REFERENCE DOCUMENTS:
 M0501-0054
 M070-0001-010
 S070-00-0105-2
 V070-00-0105-2

PREPARED BY:

DES R. LUKKHOFF
 MEL C. WAKERS

APPROVED BY:

DES _____
 MEL _____

ITEM: VALVE, GATE, CHECK, etc.
 CY 101/102/103/104

RESULTS:

FROM GATE VALVE GATE WITH 4 POPPETS IN SERIES - PARALLEL ARRANGEMENT
 PROVIDES PARALLEL REDUNDANCY FOR HELIUM PRESSURIZATION AND GATE
 REDUNDANCY TO LIMIT BACK FLOW OF PROPELLANT VAPORS FROM THE PARALLEL
 TANKS TO THE REGULATOR. A 75 MICRON FILTER IS UTILIZED AT THE
 INLET. VALVE UTILIZES CUTTER SEAL BOSTON CONCEPT (TWO SEALING SURFACES
 PER POPPET)

FAILURE MODE: FAILS CLOSED (F)

RESTRICTED FLOW.

CAUSE(S):

STUCK FAILURE, STICK, VIB, POPPET BINDS IN GUIDE, CONTAM, VAPOR
 RELEASES IN GATE VALVE, CORROS.

EFFECT(S): (A) SUBSYSTEM (F) INTERFACES (C) MISSING (D) CREW/VEHICLE:

(A) LOSS OF REDUNDANCY - PARAL FLOW PATH. (B,C,D) NO EFFECT UNLESS
 PARAL POPPETS FAIL CLOSED. FAILURE OF PARAL POPPETS WOULD CAUSE A
 FLOW SHIFT AND POSSIBLY PREVENT UTIL/DEPLETION OF ALL GASE (POPPETS
 NOT FULLY CLOSED). (E) POTENTIAL CRITICALITY EFFECT - POSSIBLE LOSS OF
 VEHICLE LOSS. FAILURE OF PARALLEL POPPETS WOULD POSSIBLY RESULT IN
 INABILITY TO TURN ON OR DEplete ALL RCS PROPELLANT IN ADDITION TO STATION
 KNOB PROBLEMS WITH REGULATOR THRUSTER FIRING PROBLEMS. POSSIBLE
 INABILITY TO CONTROL VEHICLE DURING ENTRY DUE TO INABILITY TO UTILIZE
 RESERVE PROPELLANT AND C.O. PROBLEMS DUE TO PROPELLANT WEIGHT.

CORRECTING ACTION:

IF PRESSURE IS PRONOUNCED, CLOSE HELIUM ISOL VALVE & UTILIZE CLEAN
 PRESSURE UNTIL POPPET UNSEATS.

REMARKS/HAZARDS:

ENG HAZ IF PRO NOT DEPLETED PRIOR TO ENG. POSS CHANGE IN PROG LEAD
 MAY CAUSE FARD START. FAILURE NOT DETECTABLE UNLESS PARAL POPPETS

HOSTILE FAILURE MODE AND EFFECTS ANALYSIS - PART 10.

1. SYSTEM API - REACTION CONTROL AREA 00-03-2A - 201. 2-1-77 14:17/11/77
2. EFFECTS: CONSIDERED AS HOSTILE BACK-UP. REF 502-10
3. 2-1-77.

SHUTTLE CRITICAL ITEMS LIST - CR3ITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201095-2 REV:12/12/79
 .ASSEMBLY :PRESSURIZATION ASORT: CRIT. FUNC: 13
 .P/N RI :MC284-3481-0001/-0002 CRIT. HOW: 3
 .P/N VENDGR:RS010500-001-011 MISSIONS: HF VF X FF CF SM
 .QUANTITY :4 PHASE(S): PL LD X CC X DO X LS
 . :ONE PER HELIUM SUPPLY

REDUNDANCY SCREEN: A-PASS B-FAIL C-PASS

PREPARED BY: DES R. BURKHART APPROVED BY: DES *[Signature]* APPROVED BY (NASA): *[Signature]*
 .REL C M AKERS REL *[Signature]* SSM *[Signature]*
 .REL *[Signature]* REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

.ITEM: VALVE, QUAD, CHECK, HE.
 . CV 201/202/301/302
 .FUNCTION:

. EACH CHECK VALVE QUAD WITH 4 POPPETS IN SERIES - PARALLEL ARRANGEMENT PROVIDES PARALLEL REDUNDANCY FOR HELIUM PRESSURIZATION AND SERIES REDUNDANCY TO LIMIT BACK FLOW OF PROPELLANT VAPORS FROM THE PROPELLANT TANKS TO THE REGULATOR. A 304L 25 MICRON FILTER IS UTILIZED AT THE INLET. VALVE UTILIZES CUTTER SEAL DESIGN CONCEPT (TWO SEALING SURFACES PER POPPET)

.FAILURE MODE: FAILS CLOSED (F)

. RESTRICTED FLOW.

.CAUSE(S):

. STRUCT FAILURE, SHOCK, VIB, POPPET BINDS IN GUIDE, CONTACT, VAPOR FREEZES IN COLD VALVE, COPROS.

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

. (A) LOSS OF REDUNDANCY - PARAL FLOW PATH... (B,C,D) NO EFFECT UNLESS PARAL POPPETS FAIL CLOSED. FAILURE OF PARAL POPPETS WOULD CAUSE MIX RATIO SHIFT AND POSSIBLY PREVENT UTIL/DEPLETION OF ALL PROP (POPPETS EVENTUALLY UNSEAT). (E) FUNCTIONAL CRITICALITY EFFECT - POSSIBLE CREW VEHICLE LOSS. FAILURE OF PARALLEL POPPETS WOULD POSSIBLY RESULT IN INABILITY TO BURN OR DEplete ALL RCS PROPELLANT IN ADDITION TO MIXTURE RATIO PROBLEMS WITH RESULTANT THRUSTER FIRING PROBLEMS. POSSIBLE INABILITY TO CONTROL VEHICLE DURING ENTRY DUE TO INABILITY TO UTILIZE RESERVED PROPELLANT AND C.G. PROBLEMS DUE TO PROPELLANT WEIGHT.

.DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

. (A) SERIES-PARALLEL REDUNDANT POPPETS PROVIDE REDUNDANCY FOR THE CLOSED FAILURE MODE. TO LIMIT THE POTENTIAL FOR POPPET SHAFT BINDING, OR GENERATION OF CONTAMINATION THE GUIDE PINS UTILIZE SAPPHRE AS A WEAR RESISTANT SURFACE. A 25-MICRON INLET FILTER WILL ALSO REDUCE THE POTENTIAL FOR A CLOSED FAILURE BY LIMITING THE POTENTIAL FOR CONTAMINATION TO CAUSE BINDING OF MOVING PARTS. (B) 100,000 OPERATION CYCLES (FLOW) AND RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS ARE PERFORMED DURING QUAL. ITEM IS USED DURING SYSTEM EVALUATION TESTS AT WSTF ALLOWING EVALUATION UNDER SIMULATED MISSION USAGE CONDITIONS. PROOF PRESSURE, LEAKAGE, & OPERATION (CRACKING PRESSURE AND FLOW) TESTS ARE PERFORMED DURING ATP. APPROPRIATELY LOCATED TEST POINTS ALLOW PRE/POST FLIGHT LEAKAGE TESTS AND OPERATION TESTS WHICH ARE CONDUCTED AT THIS TIME. (C) AN IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED.

1010

SD75-SH-0003

SHUTTLE CRITICAL ITEMS LIST - CRSITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -201095-2 REV:12/12/75
CONTAMINATION CONTROL PROCESS, CORROS. PROTECTION PROVISIONS, NDE EXAM. .
OF WELDS AND BRAZES, INSP. FOR SURFACE AND SUBSURFACE DEFECTS ARE
VERIFIED BY INSPECTION. THE FOLLOWING ITEMS ARE VERIFIED BY SHOP
TRAVELER MANDATORY INSP. POINTS - RAW METAL (LOT CERTIFICATION), PARTS
PROTECTION, MANUF., COATING, PLATING INSTALLATION AND ASSEMBLY
OPERATIONS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY
AUDIT CONDUCTED 12-2-77. CONTAMINATION CONTROL PROCESSES, CORROS.
PROTECTION PROVISIONS. TURNAROUND - FUNCTIONAL FLOW AND LEAKAGE
(BACK-FLOW) TESTS ARE PERFORMED. (D) NO PRIOR HISTORY FOR CLOSE FAILURE
MODE FOR THIS TYPE OF DESIGN.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-202108-1

ITEM Feedline & Fittings, Fuel

FAILURE MODE External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-flight detectability

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Gross leak detection gives first indication.
2. V42P2115 and 3115 should be deleted from this FMEA page as they are in the oxidizer system and not the fuel system.

S-1011L, FALCON, 1001 PM, CHEMICAL ANALYSIS - 05/17/78 - 10

[illegible]

LETTERS BY:

6-4

W. S. CLAVICH

6-1

5. ACCESS

APPROVED BY:

443

344

• LIPS: FIVE AND FIFTEEN

• FLOW TANK IS 1) FLOW VALVES, 2) SAMPLE VALVES, 3) 2) PRESSURES.

(1) 1 1/2 IN. 2.023 STD. L.S.S. FROM TANK TO DISTRIBUTION PANEL; (2) 1 1/2 IN. 2.023 STD. L.S.S. FROM TANK TO DISTRIBUTION VALVE TO TRANSFER TO TANK; (3) 1 1/2 IN. 2.023 STD. L.S.S. FROM TANK TO PROVIDE FEED TO APPROPRIATE PROCESS COMPONENTS FOR THE INTER OPERATING AXIS COORDINATION CONTROL AND SENSITIVE CONTROL.

• FAILURE MODE: STRUCTURAL FAILURE (S)

• 4007 号に、INTERNET LINK-CO.

• 222 (9) :

• WIRE, FATHOM, STICK, WELD DEF, INSTALL DAG, EXHAUSTOR SEAL FATHOM, "WAT"
WEL (SOLUBLE STRINGER).

• STRENGTHS: (A) SUPPLYING (B) INTERFACES (C) MISSING LINKS/VARIABLES

(c) POLYMER DEGRADATION - LOSS OF PROP. (d) BLOCKADE OF

1. DISTANCE FUNCTION. - POSS CONSIDER DAMAGE IN PDS. (1) EXPOSED. DELAY
IN DECISION. (2) POSSIBLE LOSS OF CRYO/VEHICLE-IF TIME FROM
PDS OUTLET PORTABLE. SOLID IN INABILITY TO UTILIZE/RELLI. PDS
WILL CAUSE LIT. FIRE. MAX. DANGERS FIRE OR EXPLOSION.

• 2:24-07116 ACI:Gv:

- ISOLATE LEAK USING 4" FOLD OR TANK ISOL VALVES. UTILIZE GMS PROP AS REFILL. ALERT MAY BE NEEDED.

42711 25/HB2A25:

PIE PIPE, EXPLOS. TEX & CORROS. HAZ FROM FUEL PROP IN FUEL. NO AERIAL
PRIV. SOME LEAK POINTS MAY NOT BE ISOLATABLE (UPSTREAM OF TANK ISOL.
VALVES). P. COMP. OF FUEL NOT CAUS. BELOW SCOF UNLESS AIR OR CATALYST
PRESENT. MAX HEAT SHIELD TEMP (INSIDE) IS 350°. ALL HAZ AL-
15XX-1212-14.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO. 03-24 -202108-1 REV:11/08/78
 .ASSEMBLY :PROPELLANT FEED, FUEL ABORT: CRIT. FUNC: 1
 .P/N RI :MC621-0059 CRIT. HDW: 1
 .P/N VENDOR:73A560001 : MISSIONS: HF VF X FF OF SM
 .QUANTITY :2 PHASE(S): PL LJ X GJ X DD X LS
 . :ONE SET PER PROPELLANT
 . :PER MODULE

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY: APPROVED BY: APPROVED BY UNASA:
 .DES N G GLAVINICH DES *[Signature]* SSM *[Signature]*
 .REL C M AKERS REL *[Signature]* REV *[Signature]*
 . APPROVED WITH CHANGES
 . See Section 13.0

- .ITEM: FEEDLINE AND FITTINGS
- . FROM TANK TO 1) TANK VALVES, TO 2) MANIFOLD VALVES, TO 3) THRUSTERS.
- .FUNCTION:
 - . (1) 1 1/2 X.028 304 L S.S. FROM TANK TO DISTRIBUTION PANEL, (2) 1 1/4 X.028 FROM MANIFOLD ISOLATION VALVE TO THRUSTER MANIFOLD, (3) 5/2 X.028 THRUSTER MANIFOLD TO PROVIDE FEED TO APPROPRIATE PROPELLANT COMPONENTS FOR THRUSTER OPERATION-3 AXIS ACCELERATION CONTROL AND ROTATIONAL CONTROL.
- .FAILURE MODE: STRUCTURAL FAILURE (S)
- . RUPTURE, EXTERNAL LEAKAGE.
- .CAUSE(S):
 - . VIB, FATIGUE, SHOCK, WELD DEF, INSTALL DAM, DYNATUBE SEAL FAILURE, MAT DEF (SULPHIDE STRINGER).
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 - . (A) SUBSYSTEM DEGRADATION - LOSS OF PROP. (B) DEGRADATION OF INTERFACE FUNCTION - POSS CORROS DAMAGE IN POD. (C) LAUNCH DELAY OR ABORT DECISION. (D) POSSIBLE LOSS OF CREW/VEHICLE-IF LINE FROM TANK OUTLET RUPTURES RESULTING IN INABILITY TO UTILIZE/DEplete PROP OR PROP REACTS WITH FUEL OR OX CAUSING FIRE OR EXPLOSION.
- .DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
 - . (A) F.S. IS 1.5 TO 4.0 MAXIMUM OPERATING PRESSURE (SYSTEM RELIEF). DYNATUBES HAVE DUAL SEALING SURFACES. THE WELDED CONSTRUCTION ELIMINATES JOINTS AND POSSIBLE LEAK PATHS. THE ANNEALED AREA (DUE TO WELDING) IS BACKED UP BY A SLEEVE. FASTENING CLAMPS ALLOW FREEDOM OF MOVEMENT. TUBING BENDS ARE CONTROLLED BETWEEN FIXED POINTS TO FACILITATE INSTALLATION AND ACCOMMODATE VEHICLE GROWTH AND MOVEMENT.
 - . (B) ROCKWELL PERFORMED TUBING CERTIFICATION TESTS PER "ORBITER TUBING VERIFICATION PLAN" (SD 75-SH-0205). THIS TESTING INCLUDED PRESSURE CYCLING AND FATIGUE FOR TYPICAL SHUTTLE LINES & JOINTS. SYSTEM EVALUATION TESTS AT WSTF WILL ALSO ALLOW EVALUATION IN THE INSTALLED SYSTEM CONDITION. LEAKAGE TESTS ARE PERFORMED IN-PROCESS FOR TUBING SECTIONS. OPTICAL INSPECTIONS ARE ALSO PERFORMED AT THIS TIME IN ADDITION TO X-RAY AND DYE PENETRANT. LEAKAGE TESTS ARE ALSO PERFORMED AFTER INSTALLATION INTO THE SYSTEM AND ADDITIONAL WELDS ARE ALSO SUBJECTED TO NDE. (C) AN IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. CONTAM. CONTROL PROCESSES, CORROS. PROTECTION PROVISIONS, NDE EXAM OF WELDS AND INSP. FOR SURFACE AND SUB-SURFACE DEFECTS IS VERIFIED BY INSPECTION. THE FOLLOWING ITEMS ARE VERIFIED BY SHOP TRAVELER

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -202108-1 PEV:11/03/79
MANDATORY INSP. POINTS- RAW MAT'L (LOT CERTIFICATION), PARTS PROTECTION,
MANUF., COATING, PLATING, INSTALLATION AND ASSEMBLY OPERATIONS.
HARDWARE IS INSP. IN ACCORDANCE WITH QUALITY PLANNING REQMS DOCUMENT
(QPRD) WHICH HAS BEEN APPROVED BY NASA. TURNAROUND- LINES IN ACCESSIBLE
AREAS ARE VISUALLY INSPECTED FOR EVIDENCE OF DAMAGE AND FLOW AND
PRESSURE FUNCTIONAL TESTS ARE MONITORED FOR EVIDENCE OF OBSTRUCTION OR
LEAKAGE. (D) MINOR HISTORY - CORROSION/PAB PROBLEMS DETECTED DURING
APOLLO CHECKOUT AND CORRECTED.
CORRECTED.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-202109-1

ITEM Feedline & Fittings, OX

FAILURE MODE External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☒ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES. | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Gross leak detection gives first indication.

1. 1. 1.

[illegible]

APPROVED BY:

ՀԵՏ
ՔԷԼ

ՀՀ Կոնստիտուցիոնալ դատարանի նախագահի պաշտոնատեղի
 Երևան, Կոնստիտուցիոնալ դատարանի պաշտոնատեղի
 Երևան, Կոնստիտուցիոնալ դատարանի պաշտոնատեղի

[illegible]

2) INK VALVES TO 2) MANIFOLD VALVES TO 3) FROSTING.

1. *Introduction*

(1) 1/2" NPT 304L SS. FRS TANK TO DISTRIBUTION MANIFOLD, (2) 1/2" NPT FRS MANIFOLD ISOLATION VALVE TO THRUSTER MANIFOLD, (3) 3/4" NPT THRUSTER MANIFOLD TO PROVIDE FUEL TO APPX PRIVATE FUEL LEGS, (4) COMMENTS FOR THRUSTER OPERATION - 5 AXIS ACCELERATION, CLIMB AND ORBITAL CONTROL.

• FAILURE - TYPE: STRUCTURAL FAILURE (S)

$$\bullet \quad \text{Axiom 10: } \lambda \Gamma \exists^{\leq} N, L \text{ } L \text{ is } \Gamma \text{ } N \text{ } \Gamma \text{ } L.$$
 $\cdot \cup / j^6 : (\setminus) :$

- VIBRATIONAL SHOCK, VIBRATION/FATIGUE, IMPROPER INSTALLATION (WELD).
- YIELD/SCREW FAILURE/PILE DEFICIENCY (SOLPIDE SPRINGERS).

• QUESTION 1: (S) PROBES (P) INTERFACES (C) MUSIC (D) CLUB/SCENES:

- (4) SUB-SYSTEM DEGRADATION - LOSS OF PROPPELLANT. (5) DEGRADATION OF THE REAR FUNCTION - POTENTIAL CORROSION FROM FREE PROPPELLANTS IN SPACE. (6) ADAPT DECISION. (7) POSSIBLE LOSS OF CARGO VEHICLE - IF LIFE FROM TANK TOTAL EXPLOSIONS RESULTING IN INABILITY TO UTILIZE/REEL IN OF PROP VEHICLE WITH FULL OR EXISTING CARGO. FIRE OR EXPLOSION.

• CLIP-CLIP ACTION:

- ATTEMPT TO ISOLATE AND IDENTIFY AGENT. UTILIZE GAS CHROMATOGRAPHY AS REQUIRED. AGENT DECISION MAY BE REQ'D.

• 1994-1995:

POTENTIAL TOXIC & CORROSIVE HAZARD FROM FREE PROPELLANTS, SURE LEAK POINTS MAY NOT BE ISOLATABLE (UPSTREAM OF TANK ISOLATION VALVES). REF HQ 4 NS 10XA-0202-05.

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - CRBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NC 03-2A - 202109-1 REV: 11/03/78
 ASSEMBLY : PROPELLANT FEED, OXIDIZER ABORT: CPIT. FUNC: 1
 P/N RI : MC621-0059 CPIT. HDW: 1
 P/N VENDOR: 73A5600Q2 MISSIONS: HF VF X FF CF SM
 QUANTITY : 2 PHASE(S): PL X LO X CO X DO X LS X
 : ONE SET PER PROPELLANT

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY:
 DES N C GLAVINICH
 REL C M AKERS

APPROVED BY:
 DES *[Signature]*
 REL *[Signature]* 11/79

APPROVED BY (NASA):
 SSM *[Signature]*
 REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

ITEM: FEEDLINE AND FITTINGS

FROM TANK TO 1) TANK VALVES TO 2) MANIFOLD VALVES TO 3) THRUSTERS.

FUNCTION:

(1) 1 1/4 X.028 304L S.S. FROM TANK TO DISTRIBUTION PANEL, (2) 1 1/2 X.028 FROM MANIFOLD ISOLATION VALVE TO THRUSTER MANIFOLD (3) 3/4 X.028 THRUSTER MANIFOLD TO PROVIDE FEED TO APPROPRIATE PROPELLANT COMPONENTS FOR THRUSTER OPERATION - 3 AXIS ACCELERATION CONTROL AND ROTATIONAL CONTROL.

FAILURE MODE: STRUCTURAL FAILURE (S)

RUPTURE, EXTERNAL LEAKAGE.

CAUSE(S):

MECHANICAL SHOCK, VIBRATION/FATIGUE, IMPROPER INSTALLATION (WELD), DYNATUBE SEAL FAILURE MAT'L DEFICIENCY (SULPHIDE STRINGER).

EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

(A) SUB-SYSTEM DEGRADATION - LOSS OF PROPELLANT. (B) DEGRADATION OF INTERFACE FUNCTION - POTENTIAL CORROSION FROM FREE PROPELLANTS IN MODULE. (C) ABORT DECISION. (D) POSSIBLE LOSS OF CREW VEHICLE - IF LINE FROM TANK OUTLET RUPTURES RESULTING IN INABILITY TO UTILIZE/DEplete PROP OR PROP REACTS WITH FUEL OR OXIDIZER CAUSING FIRE OR EXPLOSION.

DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

(A) F.S. IS 1.5 TO 4.0 MAXIMUM OPERATING PRESSURE (SYSTEM RELIEF). DYNATUBES HAVE DUAL SEALING SURFACES. THE WELDED CONSTRUCTION ELIMINATES JOINTS AND POSSIBLE LEAK PATHS. THE ANNEALED AREA (DUE TO WELDING) IS BACKED UP BY A SLEEVE. FASTENING CLAMPS ALLOW FREEDOM OF MOVEMENT. TUBING BENDS ARE CONTROLLED BETWEEN FIXED POINTS TO FACILITATE INSTALLATION AND ACCOMMODATE VEHICLE GROWTH AND MOVEMENT. (B) ROCKWELL PERFORMED TUBING CERTIFICATION TESTS PER "ORBITER TUBING VERIFICATION PLAN" (SD75-SH-0205). THIS TESTING INCLUDED PRESSURE CYCLING AND FATIGUE FOR TYPICAL SHUTTLE LINES & JOINTS. SYSTEM EVALUATION IN THE INSTALLED SYSTEM CONDITION. LEAKAGE TESTS ARE PERFORMED AT THIS TIME IN ADDITION TO X-RAY AND DYE PENETRANT. LEAKAGE TESTS ARE ALSO PERFORMED AFTER INSTALLATION INTO THE SYSTEM AND ADDITIONAL WELDS ARE ALSO SUBJECTED TO NDE. (C) AN IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. CONTAM. CONTROL PROCESSES, CORROS. PROTECTION PROVISIONS, NDE EXAM OF WELDS AND INSP. FOR SURFACE AND SUB-SURFACE DEFECTS IS VERIFIED BY INSPECTION. THE FOLLOWING ITEMS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP. POINTS- RAW MAT'L (LOT

SHUTTLE CRITICAL ITEMS LIST - CPBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -202109-1 REV:11/09/79
CERTIFICATION, PARTS PROTECTION, MANUF., COATING, PLATING, INSTALLATION
AND ASSEMBLY OPERATIONS. HARDWARE IS INSP. IN ACCORDANCE WITH QUALITY
PLANNING REQMITS DOCUMENT (QPRD) WHICH HAS BEEN APPROVED BY NASA.
TURNAROUND- LINES IN ACCESSIBLE AREAS ARE VISUALLY INSPECTED FOR
EVIDENCE OF DAMAGE AND FLOW AND PRESSURE FUNCTIONAL TESTS ARE MONITORED
FOR EVIDENCE OF OBSTRUCTION OR LEAKAGE. (D) MINOR HISTORY -
CORROSION/FAB PROBLEMS DETECTED DURING APPOLLO CHECKOUT AND CORRECTED.
ARE MONITORED FOR EVIDENCE OF OBSTRUCTION OR LEAKAGE. (D) MINOR
HISTORY - CORROSION/FAB PROBLEMS DETECTED DURING APPOLLO CHECKOUT AND
CORRECTED.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-202110-1

ITEM Tank Isolation Valve, A.C.

FAILURE MODE Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☒ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. First indication "failed off" thruster C&W for 1/2 leg. Redundant paths on 3,4,5 leg.
- 3A. Software could be designed to automatically position the appropriate tank isolation valve.
6. One success path remains after first failure.
- 8B. Same as primary.

ORIGINAL PAGE IS
OF POOR QUALITY

15 JUL 124450Z 85Z ANZ PER CTS 10745313 - 01047 - 10

[illegible]

PREPARED BY: DES R. GONZALEZ
REL C. M. BENSE

APPROVED BY: DES _____

[illegible]

LITERATURE VALUE AND EFFECTS ANALYSIS - continued. 112

- [illegible]

ORIGINAL PAGE IS
OF POOR

SHUTTLE CRITICAL ITEMS LIST - CPBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -202110-1 REV:12/12/79
 .ASSEMBLY : PROPELLANT FEED ABORT: ABORT, CRIT. FUNC: 12
 .P/N RI : MC284-0430-0007/-0003 RTLS CRIT. HOW: 2
 .P/N VENDOR: 5750025/5750026 MISSIONS: HF VF X FF GF SM
 .QUANTITY : 12 PHASE(S): PL LO X CO X DO X LS
 . : THREE VALVES PER PROP
 . : TANK

REDUNDANCY SCREEN: 4-PASS 8-PASS C-PASS

PREPARED BY: DES R GONZALEZ AS. DES APPROVED BY: *[Signature]* APPROVED BY NASA: *[Signature]*
 REL C H AKERS REL *[Signature]* SSM *[Signature]*
 REL *[Signature]* REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

ITEM: VALVE.

- TANK ISOLATION 3 PHASE 400 HZ AC MOTOR ACTUATED (115-230V) LV261-266, LV 361-366. (1-1/2 IN.)

FUNCTION:

- THREE REDUNDANT ISOLATION VALVES ARE USED PER TANK TO ISOLATE GROUPS OF MANIFOLDS (ONE TANK ISOL VALVE CONTROLS 2 MANIFOLDS AND TWO PARALLEL ISOL VALVES CONTROL THE REMAINING 2 PRIMARY MANIFOLDS AND THE VERNIER MANIFOLD) THAT MAY EXHIBIT OPEN OR LEAKAGE FAILURES AND TO ISOLATE THE TANK DURING INTERCONNECT & RCS OR OMS CROSSFEED OPERATIONS. ALSO USED TO PREVENT HELIUM INGESTION TO ENGINE AT PROP SHUT-DOWN (MANUAL SWITCH). FUEL & OXID VALVES CAN BE OPERATED INDEPENDENTLY FOR C/T. LINE PRESS RELIEF TO TANK IS PROVIDED.

FAILURE MODE: FAILS CLOSED (F)

- FAILS TO OPEN, FAILS TO REMAIN OPEN.

CAUSE(S):

- LIMIT SWITCH MALFUNCTION, PREMATURE POWER TO MOTOR, ELECTRICAL SHORT, RPC OPEN, JAMMING OF BALL SHAFT OR CAMS.

EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

- (A,B) LOSS OF REDUNDANCY PROPELLANT FLOW TO TWO MANIFOLDS (ON ONE SIDE) AND SUBSEQUENT LOSS OF THRUSTER FUNCTION, POTENTIAL THRUSTER DAMAGE FROM INDUCED SURGE. (C) ABORT DECISION (DEPENDENT ON WHICH TANK ISOL VALVE FAILS, ONE TANK ISOL VLV CLOSED MAY LOSE TWO MANIFOLDS). (D) NO EFFECT FOR SINGLE FAILURE FOR OBT MISSIONS (LOSS OF THRUSTER MAY BE CRITICAL FOR RTLS IN SUBSEQUENT MISSIONS FOR OMS DEPLETION BURN). CRIT 1 FOR RTLS - LOSS OF TWO MANIFOLDS (PER POD AFT) IS CRITICAL FOR ET SEPARATION & MATED COAST DURING RTLS. (E) FUNCTIONAL CRITICALITY EFFECT - POSSIBLE CREW/VEHICLE LOSS DUE TO UTILIZE/DEplete RCS PROPELLANT. POSSIBLE INABILITY TO CONTROL VEHICLE DURING ENTRY DUE TO INABILITY TO UTILIZE RESERVED PROPELLANT & C.G. PROBLEMS DUE TO PROP WEIGHT.

DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

- (A) AC MOTOR VALVE IS 3-PHASE - 2 OF 3 WINDINGS ARE ADEQUATE FOR VALVE FUNCTION. SERIES (HYBRID) RELAYS PROVIDE REDUNDANCY FOR THE PREMATURE CLOSE MODE. PARALLEL (HYBRID) RELAYS PROVIDE REDUNDANCY FOR ELECTRICAL POWER SIGNAL. ADDITIONALLY, REDUNDANT VALVES ARE PROVIDED. (ONE TANK ISOL VALVE CONTROLS 2 OF 4 MANIFOLDS AND TWO PARALLEL TANK ISOL VALVES CONTROL THE REMAINING 2 PRIMARY MANIFOLDS AND THE VERNIER MANIFOLD). A 400-MICRON FILTER IS UTILIZED ON THE INLET AND OUTLET TO LIMIT THE POTENTIAL FOR CONTAMINATION CAUSED FAILURE OR JAMMING OF MOVING PARTS.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -202110-1 REV:12/12/73
(R) 2500 OPERATION CYCLES (OPEN-CLOSE-OPEN) AND RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS ARE PERFORMED DURING QUAL. ITEM IS USED DURING SYSTEM EVALUATION TESTS AT WSTF ALLOWING EVALUATION UNDER SIMULATED MISSION USAGE CONDITION. PROOF PRESSURE, LEAKAGE, OPERATION, CONDUCTED AS PART OF PRE/POST FLIGHT CHECKOUT. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED. CONTAMINATION CONTROL PROCESS, CORDS. PROTECTION PROVISIONS, NOE EXAM OF WELDS, INSP FOR SURFACE AND SUBSURFACE DEFECTS AND PROPER ELECTRICAL TERMINATIONS, RAW MAT'L (LOT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP POINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED JULY 1976/ CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L AND EQUIP CONFORMANCE TO CONTRACT REQMTS. TURNAROUND/FUNCTIONAL FLOW & LEAKAGE TESTS ARE MONITORED TO VERIFY THAT VALVES OPEN AND CLOSE PROPERLY UPON COMMAND. (D) NO PRIOR FAILURE HISTORY FOR THIS TYPE DESIGN.

Hardware/Software Analysis Checklist SD72-SH-0103-2

SUBSYSTEM AFT -- RCS

FMEA NUMBER 03-2A-202110-3

ITEM Tank Isolation Valve, A. C.

FAILURE MODE Fails Open

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☒ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☒ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1A. Tank isolation valve discreets are available.

CRITICAL FAILURE MODE AND EFFECTS ANALYSIS - CRITERIA FOR

SYSTEM: RF - REMOTE CONTROL
 ANALYST: [REDACTED]
 DATE: 1977-01-01
 PROJECT: [REDACTED]
 COUNTRY: [REDACTED]
 TITLE: [REDACTED]
 NUMBER OF SUBJECTS: [REDACTED]
 AFTER FIRST FOLLOWUP:
 REDUNDANCY SCORE: [REDACTED]
 FIRST TO EFFECTS:
 SECOND TO EFFECTS:
 REFERENCE TO DOCUMENTS:
 10021-0009
 10070-0001-011
 1072-00-0103-0
 1070-001001

PREPARED BY:

DES

REL

R. GAZALEZ

C. Y. ANERS

APPROVED BY:

DES

REL

1. TANK VALVES:

1. TANK ISOLATION 2 PHASE 400 HZ AC MOTOR ACTUATED (115-200V) LVDT-200, 1/2-1-000.

2. FUNCTIONS:

1. TANK ISOLATION ISOLATE VALVES ARE USED FOR TANK TO ISOLATE GROUPS OF MANIFOLDS (ONE TANK ISOLATE VALVE CONTROLS 2 MANIFOLDS AND THE ISOLATE VALVE CONTROLS THE REMAINING 2 PRIMARY MANIFOLDS AND THE REMAINING MANIFOLDS THAT MAY EXHIBIT OPEN OR LEAKAGE FAILURES AND TO ISOLATE THE TANK DURING INTERCOMBUSTION OF FOS OR ONE CROSSFIELD OPERATION. ALSO USED TO PREVENT FUEL/PROP INTO ENGINE AT PREP FOR-001 (TANK ISOLATE VALVE). FUEL & OXY VALVES CAN BE OPERATED INDEPENDENTLY FOR O/C. LINE P/S IN RELIEF TO TANK IS PROVIDED.

2. FAILURES MODE: INTERNAL LEAKAGE (F)

1. FAILS OPEN, FAILS TO CLOSE, FAIL TO REMAIN CLOSED.

3. CAUSES:

1. VIBRATION, LIMIT SWITCH MALFUNCTION, STRUCTURAL FAILURE, SEAT CORROSION, CONTAMINATION, CORROSION, LOSS OF SIGNAL (COIL, REL, SPOOLS OR WIRING).

2. EFFECT(S): (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) C/P/VARIABLES

1. (A) LOSS OF REDUNDANCY - (MANIFOLD ISOLATION). (C) LOSS OF SIGNAL -

1. MANIFOLD MANAGEMENT PROBLEMS DURING CROSSFIELD OPERATIONS. (D) IS

1. EFFECT - CRIT 1 FOR RTLS. IF RCS TANK ISOLATION VALVE WILL NOT CLOSE DURING O/S DEPLETION FURN THE RCS PROPELLANT MAY BE DEPLETED IF ASSOC MANIFOLD ISOLATION VALVES ARE NOT CLOSED.

3. CORRECTIVE ACTION:

1. MAY NEED TO INHIBIT CROSSFIELD OPERATIONS TO PREVENT TRANSFER OF PROPELLANTS BETWEEN RCS OR O/S PROP INTO RCS PROP TANK.

2. PARAMETERS:

1. ITEM CHANGED FROM CRIT 3 TO CRIT 2 PER NASA REQUEST.

SHUTTLE CRITICAL ITEMS LIST - CREITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-21 -202110-3 REV:12/12/73
 .ASSEMBLY :PROPELLANT FEED ABORT: ABORT, CRIT. FUNC: 2
 .P/N RI :MC234-0430-0007/-0008 RTLS CRIT. HDW: 2
 .P/N VENDOR:5750025/5750026 MISSIONS: HF VF X FF CF SM
 .QUANTITY :12 PHASE(S): PL LC X CC X DO X LS
 . :THREE VALVES PER PROP
 . :TANK

REDUNDANCY SCREEN: A-PASS B-PASS C-PASS

PREPARED BY: DES R. GONZALEZ P.S. DES APPROVED BY: *[Signature]* APPROVED BY: (NAB) *[Signature]*
 .REL C M AKERS REL *[Signature]* 12/77 SSM *[Signature]*
 . APPROVED WITH CHANGES
 See Section 13.0

- .ITEM: VALVE.
- . TANK ISOLATION 3 PHASE 400 HZ AC MOTOR ACTUATED (115-200V) LV261-266, LV 361-366.
- .FUNCTIONS:
 - . THREE REDUNDANT ISOLATION VALVES ARE USED PER TANK TO ISOLATE GROUPS OF MANIFOLDS (ONE TANK ISOL VALVE CONTROLS 2 MANIFOLDS AND TWO PARALLEL ISOL VALVES CONTROL THE REMAINING 2 PRIMARY MANIFOLDS AND THE VERMIER MANIFOLD) THAT MAY EXHIBIT OPEN OR LEAKAGE FAILURES AND TO ISOLATE THE TANK DURING INTERCONNECT & RCS OR OMS CROSSFEED OPERATIONS. ALSO USED TO PREVENT HELIUM INGESTION TO ENGINE AT PROP PUMP-OUT (MANUAL SWITCH). FUEL & OXID VALVES CAN BE OPERATED INDEPENDENTLY FOR C/O. LINE PRESS RELIEF TO TANK IS PROVIDED.
- .FAILURE MODE: INTERNAL LEAKAGE (F)
- . FAILS OPEN, FAILS TO CLOSE, FAIL TO REMAIN CLOSED.
- .CAUSE(S):
 - . VIBRATION, LIMIT SWITCH MALFUNCTION, STRUCTURAL FAILURE, SEAT CRACKS CONTAMINATION, CORROS, LOSS OF SIGNAL (RPC SHORTS OR OPEN).
- .EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 - . (A,B) LOSS OF REDUNDANCY - (MANIFOLD ISOLATION). (C) ABORT DECISION - PROPELLANT MANAGEMENT PROBLEMS DURING CROSSFEED OPERATIONS. (D) NO EFFECT - CRIT 1 FOR RTLS. IF RCS TANK ISOLATION VALVE WILL NOT CLOSE DURING OMS DEPLETION BURN THE RCS PROPELLANT MAY BE DEPLETED IF ASSOC MANIFOLD ISOLATION VALVES ARE NOT CLOSED.
- .DISPOSITION & RATIONALE (A)DESIGN (3)TEST (C)INSPECTION (D)FAILURE HISTORY:
 - . (A) AC MOTOR VALVE IS 3-PHASE - 2 OF 3 WINDINGS ARE ADEQUATE FOR VALVE FUNCTION. PARALLEL (HYBRID) RELAYS PROVIDE REDUNDANCY FOR ELECTRICAL POWER SIGNAL. A 400-MICRON FILTER IS UTILIZED ON THE INLET AND OUTLET TO LIMIT THE POTENTIAL FOR CONTAMINATION CAUSED FAILURE OR JAMMING OF MOVING PARTS. (B) 2500 OPERATION CYCLES (OPEN-CLOSE-OPEN) AND RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS ARE PERFORMED DURING QUAL. ITEM IS USED DURING SYSTEM EVALUATION TESTS AT WSTF ALLOWING EVALUATION UNDER SIMILATED MISSION USAGE CONDITION. PROOF PRESSURE, LEAKAGE, OPERATION, CONDUCTED AS PART OF PRE/POST FLIGHT CHECKOUT. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED. CONTAMINATION CONTROL PROCESS, COROS. PROTECTION PROVISIONS, NOE EXAM OF WELDS, INSP FOR SURFACE AND SUBSURFACE DEFECTS AND PROPER ELECTRICAL TERMINATIONS, RAW MAT'L (LOT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE

ORIGINAL PAGE IS
OF POOR QUALITY

1016

SHUTTLE CRITICAL ITEMS LIST - CRBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -202110-3 REV:12/12/78
VERIFIED BY SHOP TRAVELER MANDATORY INSP POINTS. THE ABOVE ITEMS AND
THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED JULY 1976/
CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE
ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L AND EQUIP
CONFORMANCE TO CONTRACT REQMTS. TURNAROUND - FUNCTIONAL FLOW & LEAKAGE
TESTS ARE MONITORED TO VERIFY THAT VALVES OPEN AND CLOSE PROPERLY UPON
COMMAND. (D) NO PRIOR FAILURE HISTORY FOR THIS TYPE DESIGN.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM APT - RCS

FMEA NUMBER 03-2A-202111-2

ITEM Interconnect Valve, A. C.

FAILURE MODE Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In Flight Detectability
☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. "Failed off" thruster gives first indication.
6. One success path remains after first failure.
- 8B. Same as primary.

SECRET - FOLLOW-UP AND AFTER-EFFECTS ANALYSIS - CONTINUED

75

CIVILIL FILLURE COUNCIL AND FREEDOM ANALYSIS - CIVILIL 1107

8. SYSTEMS: 1. REACTION CONTROL FGA 100-2A-100-111-1 100-111-1
2. 100-111-1 100-111-1 100-111-1 100-111-1
3. 100-111-1 100-111-1 100-111-1 100-111-1

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - CR3ITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-24 -202111-2 REV: 12/12/78
 ASSEMBLY : PROPELLANT FEED ABCRT: ABCRT, CRIT. FUNC: 2R
 P/N RI : MC284-0430-JJJ7/-0003 RTLS CRIT. HDW: 3
 P/N VENDOR: 5750025/5750026 MISSIONS: HF VF X FF TF S1
 QUANTITY : 3 PHASE(S): PL LO X CO X JO X LS
 : TWO INTERCONNECT LINES
 : PER PROPELLANT TANK

REDUNDANCY SCREEN: A-PASS B-PASS C-PASS

PREPARED BY: DES R GONZALEZ *R.G.* APPROVED BY: *[Signature]* APPROVED BY (NASA): *[Signature]*
 REL C M AKERS REL *[Signature]* SSN *[Signature]*
 REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

ITEM: VALVE.
 INTERCONNECT, 3 PHASE 400 HZ AC MOTOR OPERATED (115-200V), OMS/RCS (1 1/2").

- FUNCTION:
- TO PROVIDE CONTROL OF INTERCONNECT LINE FOR VARIOUS MODES OF PROPELLANT FEED: 1) OPEN FOR OMS TO RCS 2) OPEN FOR RCS TO RCS 3) CLOSED FOR RCS TO SAME SIDE RCS AND OMS TO OMS. TWO INTERCONNECT VALVES PER PROP TANK ARE USED. EACH GOES INDEPENDENTLY TO SEPARATE MANIFOLD BANKS. LINE PRESSURE RELIEF TOWARDS PROP TANK IS PROVIDED.
- FAILURE MODE: FAILS CLOSED (F)
- FAILS TO REMAIN OPEN.
- CAUSE(S):
- VIB, LIMIT SW FAILURE, PREMATURE POWER TO MOTOR, ELECTRICAL SHORT RPO OPEN, JAMMING OF CAM.
- EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CRAFT/VEHICLE:
- (A) LOSS OF REDUNDANCY. (B) DEGRADATION OF INTERFACE FUNCTION-CROSSFEED PROP CAN BE UTILIZED BY ONLY 2 OF 4 MANIFOLD BANKS. (C) MISSION MODIFICATION-OPERATION CHANGES FOR ITEM B ABOVE. (D) NO EFFECT FOR OBT MISSIONS (LOSS OF THRUSTER MAY BE CRITICAL FOR RTLS IN SUBSEQUENT MISSIONS FOR OMS DEPLETION BURN). CRIT 1 FOR RTLS - LOSS OF 1 MANIFOLD FORWARD & 1 MANIFOLD AFT IS CRITICAL FOR ET SEPARATION & MATED COAST DURING RTLS. SINGLE COMPUTER FAILURE COULD RESULT IN THIS TYPE CONDITION. (E) FUNCTIONAL CRITICALITY EFFECT - POSSIBLE EARLY MISSION TERMINATION - INABILITY TO DEMONSTRATE OMS PROP FEED TO RCS.
- DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
- (A) AC MOTOR VALVE IS 3-PHASE - 2 OF 3 WINDINGS ARE ADEQUATE FOR VALVE FUNCTION. SERIES (HYBRID) RELAYS PROVIDE REDUNDANCY FOR THE PREMATURE CLOSE MODE. PARALLEL (HYBRID) RELAYS PROVIDE REDUNDANCY FOR ELECTRICAL POWER SIGNAL. ADDITIONALLY, REDUNDANT VALVES ARE PROVIDED. A 400-MICRON FILTER IS UTILIZED ON THE INLET AND OUTLET TO LIMIT THE POTENTIAL FOR CONTAMINATION CAUSED FAILURE OR JAMMING OF MOVING PARTS. (B) 2500 OPERATION CYCLES (OPEN-CLOSE-OPEN) AND RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS ARE PERFORMED DURING QUAL. ITEM IS USED DURING SYSTEM EVALUATION TESTS AT WSTF ALLOWING EVALUATION UNDER SIMULATED MISSION USAGE CONDITION. PROOF PRESSURE, LEAKAGE, OPERATION, CONDUCTED AS PART OF PRE/POST FLIGHT CHECKOUT. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED. CONTAMINATION CONTROL PROCESS, CORDS. PROTECTION PROVISIONS, NDE EXAM OF WELDS, INSP FOR SURFACE AND SUBSURFACE DEFECTS AND PROPER ELECTRICAL TERMINATIONS, RAW MAT'L (LOT) CERTIFICATION, PARTS : PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP POINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO. 03-2A-202111-2 REV: 12/12/78
JULY 1976/CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND
STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L
AND EQUIP CONFORMANCE TO CONTRACT REQMTS. TURNAROUND/FUNCTIONAL FLOW &
LEAKAGE TESTS ARE MONITORED TO VERIFY THAT VALVES OPEN AND CLOSE PROPERLY
UPON COMMAND. (D) NO PRIOR FAILURE HISTORY FOR THIS TYPE DESIGN.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-202120-3

ITEM Manifold Isolation Valve, A. C.

FAILURE MODE Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☒ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

3. RCS RM automatically detects and prevents thrusting.

[illegible][illegible]

REFERENCE LIST:

$$A \cap K \subseteq V = \bigcup_{i=1}^n Y_i$$

Figure 1

F. CLAZALÉZ

55

1-1-1

C N A K E - 2 3

n = 1

11-11-11 11:11:11

[illegible]

1) IS LATE INSULATION FROM PROPRIETARY PRIOR TO SYSTEM ACTIVATION.
2) IS INSULATION A FIBERED GYM INSULATOR OR COMPOSITE TYPE. EACH
MINIMUM INSULATION VALUE CONTAINS 3 PRIMARY PROPERTIES. BENEFIT
GAIN TOWARDS FROM TASK IS PROVIDED.

• 1991 • 4027 • 1991 12 20 • 1991 12 20 • 1991 12 20 (1)

• "The oil", Fells told the jury.

• C. 154 (5) :

• VOLTAGE, LIGHT SENSING MALFUNCTION, PROXIMITY SENSOR IN ALARM, EXHAUSTION, NOISE SIGNAL, RIG SHORT.

*.FREQ(1(5): 2, (4) SUBSYSTEM = (5) INTERFACES (6) EMISSION (7) CABLE/VOLUME;

• (A)(2) LOSS OF RESILIENCY-LOSS OF PROOF FLOW & USE IF A PRIMARY

TRUSTERS (1 OF 4 MANIFOLDS). (C) (E) NO EFFECT FOR SINGLE FAILURE FOR GET VISSIONS (LOSS OF TRUSTER MAY BE CRITICAL FOR RTLS IN SUBSISTENT POSITION FOR GET RELEASED). (D) 1 FOR RTLS - LOSS OF 1 MANIFOLD. FAILURE OF MANIFOLD IS CRITICAL FOR RT SEPARATION. (E) LOSS OF 1 RTLS. (F) SINGLE COMPUTER FAILURE COULD RESULT IN THIS TYPE CONDITION. (G) FUNCTIONAL CRITICALITY EFFECT - POSSIBLY CREW/VEHICLE LOSS DUE TO INABILITY TO USE RCS IF ALL MANIFOLD VALVES FAIL CLOSED.

CLASSIFIED BY: [redacted]

- UTILIZE ADJUSTING THROTTLES FOR FUNCTION. ATTEMPT TO KNOCK DOWN CLOSED VALVE BY USE OF MANUAL SET.

• 2006-05/06/07/08/09/10/11/12/13/14/15/16/17/18/19/20/21/22/23/24/25/26/27/28/29/30/31/32/33/34/35/36/37/38/39/40/41/42/43/44/45/46/47/48/49/50/51/52/53/54/55/56/57/58/59/60/61/62/63/64/65/66/67/68/69/70/71/72/73/74/75/76/77/78/79/80/81/82/83/84/85/86/87/88/89/90/91/92/93/94/95/96/97/98/99/100/101/102/103/104/105/106/107/108/109/110/111/112/113/114/115/116/117/118/119/120/121/122/123/124/125/126/127/128/129/130/131/132/133/134/135/136/137/138/139/140/141/142/143/144/145/146/147/148/149/150/151/152/153/154/155/156/157/158/159/160/161/162/163/164/165/166/167/168/169/170/171/172/173/174/175/176/177/178/179/180/181/182/183/184/185/186/187/188/189/190/191/192/193/194/195/196/197/198/199/200/201/202/203/204/205/206/207/208/209/210/211/212/213/214/215/216/217/218/219/220/221/222/223/224/225/226/227/228/229/230/231/232/233/234/235/236/237/238/239/240/241/242/243/244/245/246/247/248/249/250/251/252/253/254/255/256/257/258/259/260/261/262/263/264/265/266/267/268/269/270/271/272/273/274/275/276/277/278/279/280/281/282/283/284/285/286/287/288/289/290/291/292/293/294/295/296/297/298/299/300/301/302/303/304/305/306/307/308/309/310/311/312/313/314/315/316/317/318/319/320/321/322/323/324/325/326/327/328/329/330/331/332/333/334/335/336/337/338/339/340/341/342/343/344/345/346/347/348/349/350/351/352/353/354/355/356/357/358/359/360/361/362/363/364/365/366/367/368/369/370/371/372/373/374/375/376/377/378/379/380/381/382/383/384/385/386/387/388/389/390/391/392/393/394/395/396/397/398/399/400/401/402/403/404/405/406/407/408/409/410/411/412/413/414/415/416/417/418/419/420/421/422/423/424/425/426/427/428/429/430/431/432/433/434/435/436/437/438/439/440/441/442/443/444/445/446/447/448/449/450/451/452/453/454/455/456/457/458/459/460/461/462/463/464/465/466/467/468/469/470/471/472/473/474/475/476/477/478/479/480/481/482/483/484/485/486/487/488/489/490/491/492/493/494/495/496/497/498/499/500/501/502/503/504/505/506/507/508/509/510/511/512/513/514/515/516/517/518/519/520/521/522/523/524/525/526/527/528/529/530/531/532/533/534/535/536/537/538/539/540/541/542/543/544/545/546/547/548/549/550/551/552/553/554/555/556/557/558/559/560/561/562/563/564/565/566/567/568/569/570/571/572/573/574/575/576/577/578/579/580/581/582/583/584/585/586/587/588/589/590/591/592/593/594/595/596/597/598/599/600/601/602/603/604/605/606/607/608/609/610/611/612/613/614/615/616/617/618/619/620/621/622/623/624/625/626/627/628/629/630/631/632/633/634/635/636/637/638/639/640/641/642/643/644/645/646/647/648/649/650/651/652/653/654/655/656/657/658/659/660/661/662/663/664/665/666/667/668/669/670/671/672/673/674/675/676/677/678/679/680/681/682/683/684/685/686/687/688/689/690/691/692/693/694/695/696/697/698/699/700/701/702/703/704/705/706/707/708/709/710/711/712/713/714/715/716/717/718/719/720/721/722/723/724/725/726/727/728/729/730/731/732/733/734/735/736/737/738/739/740/741/742/743/744/745/746/747/748/749/750/751/752/753/754/755/756/757/758/759/760/761/762/763/764/765/766/767/768/769/770/771/772/773/774/775/776/777/778/779/780/781/782/783/784/785/786/787/788/789/790/791/792/793/794/795/796/797/798/799/800/801/802/803/804/805/806/807/808/809/810/811/812/813/814/815/816/817/818/819/820/821/822/823/824/825/826/827/828/829/830/831/832/833/834/835/836/837/838/839/840/841/842/843/844/845/846/847/848/849/850/851/852/853/854/855/856/857/858/859/860/861/862/863/864/865/866/867/868/869/870/871/872/873/874/875/876/877/878/879/880/881/882/883/884/885/886/887/888/889/890/891/892/893/894/895/896/897/898/899/900/901/902/903/904/905/906/907/908/909/910/911/912/913/914/915/916/917/918/919/920/921/922/923/924/925/926/927/928/929/930/931/932/933/934/935/936/937/938/939/940/941/942/943/944/945/946/947/948/949/950/951/952/953/954/955/956/957/958/959/960/961/962/963/964/965/966/967/968/969/970/971/972/973/974/975/976/977/978/979/980/981/982/983/984/985/986/987/988/989/990/991/992/993/994/995/996/997/998/999/1000/1001/1002/1003/1004/1005/1006/1007/1008/1009/1010/1011/1012/1013/1014/1015/1016/1017/1018/1019/1020/1021/1022/1023/1024/1025/1026/1027/1028/1029/1030/1031/1032/1033/1034/1035/1036/1037/1038/1039/10

THE PARKER PNEU # RPA 575022. NO HAZARDS IDENTIFIED FOR NORMAL
MISSION. LANDING HAZ, AERODYNAMIC CONTROL, TOXIC, FIRE & EXPLOSION IF
GAS/NOX PROP NOT DEPLETED PRIOR TO LANDING (RTLS). VALVES ARE NORMALLY
OPENED BY EMERGENCY CLOSE SIGNAL DURING LAUNCH PHASE (RTLS) IS CONSIDERED.

SHUTTLE CRITICAL ITEMS LIST - CRBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A - 202120-3 REV: 12/12/73
 .ASSEMBLY : PROPELLANT FEED ABORT: ABCPT. CPIT. FUNC: 12
 .P/N RI : MC 284-0430-0001/-0002 RTLS CRIT. HOW: 3
 .P/N VENGR: 5750023/5750024 MISSIONS: HF VF X FF CF SM
 .QUANTITY : 16 PHASE(S): PL LO X CC X DO X LS
 . : FOUR PRIMARY VALVE MANI-
 . : FOLCS PER PROP

REDUNDANCY SCREEN: A-PASS B-PASS C-PASS

.PREPARED BY:

.DES R. GONZALEZ R.
 .REL C M AKERS

APPROVED BY:

DES *[Signature]*
 REL *[Signature]* 12/77

APPROVED BY (NASA):

SSM *[Signature]*
 REL *[Signature]*

APPROVED WITH CHANGES

See Section 13.0

.ITEM: VALVE

.MANIFOLD ISOLATION, 3 PHASE, 400 HZ AC MOTOR OPERATED (115-200V) (1 1/2" INLET, 1 1/4" OUTLET).

.FUNCTION:

- 1) TO ISOLATE THRUSTERS FROM PROPELLANTS PRIOR TO SYSTEM ACTIVATION AND
- 2) TO ISOLATE A FAILED OPEN THRUSTER OR DOWNSTREAM LEAK. EACH MANIFOLD ISOLATION VALVE CONTROLS 3 PRIMARY THRUSTERS. LINE PRESSURE RELIEF TOWARDS PROP TANK IS PROVIDED.

.FAILURE MODE: FAILS CLOSED-PREMATURE (F)

.OPERATION, FAILS TO REMAIN OPEN.

.CAUSE(S):

- VIBRATION, LIMIT SWITCH MALFUNCTION, PREMATURE POWER TO MOTOR.
- PREMATURE MOTOR SIGNAL, PPC SHORT.

.EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

- (A)(B) LOSS OF REDUNDANCY-LOSS OF PROP FLOW & USE OF 3 PRIMARY THRUSTERS (1 OF 4 MANIFOLDS). (C)(D) NO EFFECT FOR SINGLE FAILURE FOR OFT MISSIONS (LOSS OF THRUSTER MAY BE CRITICAL FOR RTLS IN SUBSEQUENT MISSIONS FOR OMS DEPLETION BURN). CRIT 1 FOR RTLS - LOSS OF 1 MANIFOLD FORWARD & 1 MANIFOLD AFT IS CRITICAL FOR ET SEPARATION & MATED COAST DURING RTLS. SINGLE COMPUTER FAILURE COULD RESULT IN THIS TYPE CONDITION. (E) FUNCTIONAL CRITICALITY EFFECT - POSSIBLE CREW/VEHICLE LOSS DUE TO INABILITY TO USE RCS IF ALL MANIFOLD VALVES FAIL CLOSED.

.DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

- (A) AC MOTOR VALVE IS 3-PHASE - 2 OF 3 WINDINGS ARE ADEQUATE FOR VALVE FUNCTION. SERIES (HYBRID) RELAYS PROVIDE REDUNDANCY FOR THE PREMATURE CLOSE MODE. PARALLEL (HYBRID) RELAYS PROVIDE REDUNDANCY FOR ELECTRICAL POWER SIGNAL. ADDITIONALLY, REDUNDANT VALVES ARE PROVIDED. A 400-MICRON FILTER IS UTILIZED ON THE INLET AND OUTLET TO LIMIT THE POTENTIAL FOR CONTAMINATION CAUSED FAILURE OR JAMMING OF MOVING PARTS. (B) 2500 OPERATION CYCLES (OPEN-CLOSE-OPEN) AND RANDOM VIBRATION AT ANTICIPATED MISSION LEVELS ARE PERFORMED DURING QUAL. ITEM IS USED DURING SYSTEM EVALUATION TESTS AT WSTF ALLOWING EVALUATION UNDER SIMULATED MISSION USAGE CONDITION. PROOF PRESSURE, LEAKAGE, OPERATION, CONDUCTED AS PART OF PRE/POST FLIGHT CHECKOUT. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED. CONTAMINATION CONTROL PROCESS, CORDS. PROTECTION PROVISIONS, NDE EXAM OF WELDS, INSP FOR SURFACE AND SUBSURFACE DEFECTS AND PROPER ELECTRICAL TERMINATIONS, RAW MAT'L (LOT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP POINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED JULY 1976/CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L AND EQUIP CONFORMANCE

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO. 03-2A-202120-3 REV: 12/12/78
TO CONTRACT REQMTS. TURNAROUND/FUNCTIONAL FLOW & LEAKAGE TESTS ARE MONITORED
TO VERIFY THAT VALVES OPEN AND CLOSE PROPERLY UPON COMMAND. (D) NO PRIOR
FAILURE HISTORY FOR THIS TYPE DESIGN.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-202140-1

ITEM Manifold Isolation Valve, D.C.

FAILURE MODE Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☒ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

3. The RCS Redundancy Management software will inhibit the firing of those jets associated with the failed valve.

6. There are no success paths remaining after first failure.

8B. Same as primary.

U. S. DEPARTMENT OF JUSTICE - FEDERAL BUREAU OF INVESTIGATION - WASHINGTON, D. C. 20535

1. PRIMARY SITE - LOCATION, COORDINATES
 2. SECONDARY SITE - LOCATION, COORDINATES
 3. TERTIARY SITE - LOCATION, COORDINATES
 4. PRIMARY SITE - TYPE
 5. PRIMARY SITE - STATUS
 6. PRIMARY SITE - COMMENTS
 7. PRIMARY SITE - NOTES
 8. PRIMARY SITE - ACTION
 9. PRIMARY SITE - RESULTS
 10. PRIMARY SITE - SUMMARY
 11. PRIMARY SITE - CONCLUSION
 12. PRIMARY SITE - RECOMMENDATION
 13. PRIMARY SITE - ACTION PLAN
 14. PRIMARY SITE - MONITORING
 15. PRIMARY SITE - EVALUATION
 16. PRIMARY SITE - REPORTING
 17. PRIMARY SITE - ARCHIVING
 18. PRIMARY SITE - DISTRIBUTION
 19. PRIMARY SITE - REVIEW
 20. PRIMARY SITE - CLOSURE

APPROVED - 12

۲۵۳

 Δ

111. : 72LVZ.

• "SOLUBLE INSULATION", VERNIER INSTRUMENT, SOLENOID (SERVIC) 11-14-14-14
(L-101114) LV 273/257/ 31/318.

2000 年 12 月 1 日

1) PROVIDE VENTILATION THROUGHOUT: 1) PREP TO SYSTEM ACTIVATION AND 2) IN THE EVENT OF A MANUAL THROUSTER OR MANIFOLD LEAK.

(17)

$$f(u) = \{ \varepsilon \} :$$

INSTRUMENT ELECTRICAL SIGNAL (CONTINUOUS SHORT) OR LOW MAGNETIC FLUX ON
FIELD LATCHING MAGNET, RECH SHOCK; VIO., CONTAM (AIR LIP).

(A) LOSS OF FUNCTION (OVERHEAT, THROTER). (C) DEGRADATION OF INTERFAC
 SUB-SYSTEM-PAYLOAD MANIPULATION. (C) MISSION MODIFICATION OR ABORT
 DECISION. (C) NO EFFECT UNLESS ADDITIONAL FAILURES OCCUR.

COLLECTING ACTION:

UTILIZE STANDARD RCS VANNER. ATTEMPT TO REOPEN WATFOLD 1504 VALVE BY
USE OF KAYROL SH.

05/05/2014

POTENTIAL FOR COLLISION WITH/OR LOSS OF PAYLOAD/SATELLITE. DUAL
 SWITCHING WILL PRECLUDE INADVERTENT ACTUATION. SEE CONSOLIDATED
 CONTROLS FMEA # 75095 FMEA 1. REF HAZ NO 1YXX-002-09. REFER FOR
 USE OF FLD PCS VERNIER & FREE DRIFT AS BACK-UP MODES DELETED AT VISA
 REQUEST.

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : AFT - REACTION CONTROL
 ASSEMBLY : PROPELLANT FEED
 P/N RI : MC234-0420-0011/-0012
 P/N VENDOR: 73895
 QUANTITY : 4
 : TWO PER MODULE

FMEA NO 03-24 -202140-1 REV: 12/12/70
 ABORT: ~~CRIT. FCTG: 2~~
 CRIT. HDW: 2
 MISSIONS: HF VF X FF 2F SM
 PHASE(S): PL LO CC X DO LS

REDUNDANCY SCREEN: A-PASS B-PASS C-FAIL

PREPARED BY:
 DES- R. BURKHART
 REL C M AKERS

APPROVED BY:
 DES- *M.W. Loken*
 REL *C.E. Hansen* 12/77

APPROVED BY (NASA):
 SSN *W. Kerschul*
 REL *R. Kerschul*

APPROVED WITH CHANGES
 See Section 13.0

ITEM: VALVE.

MANIFOLD ISOLATION, VERNIER THRUSTER, SOLENOID (28VDC) 31-STABLE
 (LATCHING) LV 258/257/357/352.

FUNCTION:

TO PROVIDE VERNIER THRUSTER ISOLATION: 1) PRIOR TO SYSTEM ACTIVATION
 AND 2) IN THE EVENT OF A RUNAWAY THRUSTER OR MANIFOLD LEAK.

FAILURE MODE: FAILS CLOSED.

(F)

CAUSE(S):

IMPROPER ELECTRICAL SIGNAL (CONTINUOUS SHORT) OR LOW MAGNETIC FORCE
 FROM LATCHING MAGNET, MECH SHOCK, VIB., CONTAM (AIR GAP).

EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 (A) LOSS OF FUNCTION (VERNIER THRUSTER). (B) DEGRADATION OF INTERFACE
 SUBSYSTEM-PAYLOAD MANIPULATION. (C) MISSION MODIFICATION OR ABORT
 DECISION. (D) NO EFFECT UNLESS ADDITIONAL FAILURES OCCUR.

DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

(A) SERIES SWITCHES (RPC'S) MINIMIZE POTENTIAL FOR UNDESIRABLE ACTUATION.
 PARALLEL SWITCHES (RPC'S) PROVIDE ELECT REDUND FOR THE OPENING SIG.
 AN INDUCT VOLTAGE SUPPRESS CIRCUIT IS PROVIDED IN THE ELECTRICAL SYSTEM TO
 PREVENT DAMAGE TO OTHER ON-LINE COMPS. REDUNDANT DIODES LIMIT THE POSS OF
 DIODE FAILURE ALLOWING CURRENT SHUNT FROM THE COIL.

100 MICRON FILTER IS PROVIDED TO LIMIT THE POSS OF CONTAM CAUSING
 JAMMING MOVING PARTS. TO LIMIT THE
 ELECT SHORT POTENTIAL, THE LEAD AND MAGNET WIRES ARE ENCASED BY POTTING AND
 A FIXTURE IS USED DURING ASSEMBLY TO ENSURE THAT INSUL IS NOT DAMAGED
 BY THE EXIT NOTCH WHEN THE COIL SLEEVE IS PRESSED ONTO THE COIL. (B)
 2000 CYCLES (ON-OFF-FLOW) AND RANDOM VIB AT ANTIC MISSION LEVELS ARE
 PERF DURING OAL. ITEM IS USED DURING SYS EVAL TESTS AT WSTF ALLOWING
 EVAL UNDER SIMUL MISSION USAGE COND. PROOF PRESS, LEAKAGE, OPER AND
 INSUL TESTS ARE PERF DURING ATP. APPROPRIATE LOCATED TEST POINTS ALLOW
 PRE/POST FLIGHT LEAKAGE TESTS AND OPER TESTS ARE ALSO COND AT THIS TIME.
 (C) AND IDENTIF IS PERF AND THE UNIT TAGGED. CONTAM CONT PROCESS,
 CORROS. PROT PROVIDED. NDE EXAM. OF WELDS AND BRAZES. INSP. FOR SURFACE AND
 SUBSURFACE DEFECTS AND PROPER ELECT TERMINATIONS ARE VERIFIED BY INSPECT.
 THE FOLLOWING ITEMS ARE VERIFIED BY SHOP TRAVELER INSP. POINTS- RAW MAT'L (LOT
 CERTIF), PARTS PROT, MANUF., COATING, PLATING, INSTALL AND ASSY OPER.
 THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT COND

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-24 -202140-1 REV:12/12/78
8-31-77. CONTAM CONT PROC, CORROS. PROT PROV TURNAROUND- FUNCT FLOW
TESTS ARE MONIT TO VERIFY THAT VALVES OPEN AND CLOSE PROPERLY UPON
COMMAND. (D) APOLLO FAILURES WERE MAINLY ASSOC WITH REVERSE POLARITY
AND DEGUASSING OF MAGNETS. THE SHUTTLE VALVE UTILIZES A CONNECTOR
(RATHER THAN LEAD WIRES) AND A BLOCKING DIDGE WHICH PREVENTS THIS TYPE
OF ERROR DURING CONN. DEVEL TEST AND ANAL SHOWED PRESS SURGE FATIGUE
PROBLEM. THIS IS BEING RESOLVED BY REDUCING THE LIFE OF THE VALVE TO 50
MISSIONS.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-202150-1

ITEM Propellant Fill & Bleed Disconnect

FAILURE MODE Fails Open

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In Flight Detectability
☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Gross leak detection will give first indication.
6. There is one success path remaining after the first failure.
- 8B. Same as primary.
2. Measurements V42P2313C, 2315C, 2313C and 3315C are not listed in the MML.

SOCIETY FOR POLYMER SCIENCE AND POLYMER ANALYSIS - 10311, 10312, 10313, 10314, 10315, 10316, 10317, 10318, 10319, 10320, 10321, 10322, 10323, 10324, 10325, 10326, 10327, 10328, 10329, 10330, 10331, 10332, 10333, 10334, 10335, 10336, 10337, 10338, 10339, 10340, 10341, 10342, 10343, 10344, 10345, 10346, 10347, 10348, 10349, 10350, 10351, 10352, 10353, 10354, 10355, 10356, 10357, 10358, 10359, 10360, 10361, 10362, 10363, 10364, 10365, 10366, 10367, 10368, 10369, 10370, 10371, 10372, 10373, 10374, 10375, 10376, 10377, 10378, 10379, 10380, 10381, 10382, 10383, 10384, 10385, 10386, 10387, 10388, 10389, 10390, 10391, 10392, 10393, 10394, 10395, 10396, 10397, 10398, 10399, 10400, 10401, 10402, 10403, 10404, 10405, 10406, 10407, 10408, 10409, 10410, 10411, 10412, 10413, 10414, 10415, 10416, 10417, 10418, 10419, 10420, 10421, 10422, 10423, 10424, 10425, 10426, 10427, 10428, 10429, 10430, 10431, 10432, 10433, 10434, 10435, 10436, 10437, 10438, 10439, 10440, 10441, 10442, 10443, 10444, 10445, 10446, 10447, 10448, 10449, 10450, 10451, 10452, 10453, 10454, 10455, 10456, 10457, 10458, 10459, 10460, 10461, 10462, 10463, 10464, 10465, 10466, 10467, 10468, 10469, 10470, 10471, 10472, 10473, 10474, 10475, 10476, 10477, 10478, 10479, 10480, 10481, 10482, 10483, 10484, 10485, 10486, 10487, 10488, 10489, 10490, 10491, 10492, 10493, 10494, 10495, 10496, 10497, 10498, 10499, 10500, 10501, 10502, 10503, 10504, 10505, 10506, 10507, 10508, 10509, 10510, 10511, 10512, 10513, 10514, 10515, 10516, 10517, 10518, 10519, 10520, 10521, 10522, 10523, 10524, 10525, 10526, 10527, 10528, 10529, 10530, 10531, 10532, 10533, 10534, 10535, 10536, 10537, 10538, 10539, 10540, 10541, 10542, 10543, 10544, 10545, 10546, 10547, 10548, 10549, 10550, 10551, 10552, 10553, 10554, 10555, 10556, 10557, 10558, 10559, 10560, 10561, 10562, 10563, 10564, 10565, 10566, 10567, 10568, 10569, 10570, 10571, 10572, 10573, 10574, 10575, 10576, 10577, 10578, 10579, 10580, 10581, 10582, 10583, 10584, 10585, 10586, 10587, 10588, 10589, 10590, 10591, 10592, 10593, 10594, 10595, 10596, 10597, 10598, 10599, 10600, 10601, 10602, 10603, 10604, 10605, 10606, 10607, 10608, 10609, 10610, 10611, 10612, 10613, 10614, 10615, 10616, 10617, 10618, 10619, 10620, 10621, 10622, 10623, 10624, 10625, 10626, 10627, 10628, 10629, 10630, 10631, 10632, 10633, 10634, 10635, 10636, 10637, 10638, 10639, 10640, 10641, 10642, 10643, 10644, 10645, 10646, 10647, 10648, 10649, 10650, 10651, 10652, 10653, 10654, 10655, 10656, 10657, 10658, 10659, 10660, 10661, 10662, 10663, 10664, 10665, 10666, 10667, 10668, 10669, 10670, 10671, 10672, 10673, 10674, 10675, 10676, 10677, 10678, 10679, 10680, 10681, 10682, 10683, 10684, 10685, 10686, 10687, 10688, 10689, 10690, 10691, 10692, 10693, 10694, 10695, 10696, 10697, 10698, 10699, 10700, 10701, 10702, 10703, 10704, 10705, 10706, 10707, 10708, 10709, 10710, 10711, 10712, 10713, 10714, 10715, 10716, 10717, 10718, 10719, 10720, 10721, 10722, 10723, 10724, 10725, 10726, 10727, 10728, 10729, 10730, 10731, 10732, 10733, 10734, 10735, 10736, 10737, 10738, 10739, 10740, 10741, 10742, 10743, 10744, 10745, 10746, 10747, 10748, 10749, 10750, 10751, 10752, 10753, 10754, 10755, 10756, 10757, 10758, 10759, 10760, 10761, 10762, 10763, 10764, 10765, 10766, 10767, 10768, 10769, 10770, 10771, 10772, 10773, 10774, 10775, 10776, 10777, 10778, 10779, 10780, 10781, 10782, 10783, 10784, 10785, 10786, 10787, 10788, 10789, 10790, 10791, 10792, 10793, 10794, 10795, 10796, 10797, 10798, 10799, 10800, 10801, 10802, 10803, 10804, 10805, 10806, 10807, 10808, 10809, 10810, 10811, 10812, 10813, 10814, 10815, 10816, 10817, 10818, 10819, 10820, 10821, 10822, 10823, 10824, 10825, 10826, 10827, 10828, 10829, 10830, 10831, 10832, 10833, 10834, 10835, 10836, 10837, 10838, 10839, 10840, 10841, 10842, 10843, 10844, 10845, 10846, 10847, 10848, 10849, 10850, 10851, 10852, 10853, 10854, 10855, 10856, 10857, 10858, 10859, 10860, 10861, 10862, 10863, 10864, 10865, 10866, 10867, 10868, 10869, 10870, 10871, 10872, 10873, 10874, 10875, 10876, 10877, 10878, 10879, 10880, 10881, 10882, 10883, 10884, 10885, 10886, 10887, 10888, 10889, 10890, 10891, 10892, 10893

89

SHUTTLE CRITICAL ITEMS LIST - CR6ITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -202150-1 REV:11/03/79
 ASSEMBLY :PROPELLANT ABORT: CRIT. FUNC: 1
 P/N RI :MC276-0018 CRIT. HCN: 1
 P/N VENDOR:76301000 & 76306000 MISSIONS: HF VF X FF OF SM
 QUANTITY :12 PHASE(S): PL LO X CO X DO X LS

:VEHICLE

:6/POD

2 OF 1/2 IN.

4 OF 1/4 IN.

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY:
 DES C SCARLETT
 REL C MAKERS

APPROVED BY:
 DES *C. Scarlett* 12/15/78
 REL *C. E. Barnett* 12/17/78

APPROVED BY (MESA):
 SSM *W. Ranshel*
 REL *W. Ranshel*

APPROVED WITH CHANGES
 See Section 13.0

ITEM: DISCONNECT-FILL & BLEED

PROPELLANT, SPRING LOADED POPPET WITH STRUCTURAL CAP(1/4" & 1/2").

FUNCTION:

TO PROVIDE FOR VENTING AND BLEEDING PROPELLANT TANKS DURING SERVICING IN VERTICAL VEHICLE ORIENTATION. ONE INCH COUPLING, (FUEL-LEFT POD AND OX-RIGHT POD) SERVICES APCS AND CMS. ITEM INCORPORATES SECONDARY INTERNAL SEALS AND HAS A PRESSURE CAP WHICH IS REDUNDANT SEAL. CAP INSTALLED PRIOR TO FLIGHT.

FAILURE MODE: FAILS OPEN. (S)

CAP LEAKS IN EXCESS OF ACCEPTABLE RATE, SEALS DAMAGED RETAINING NOT LOOSENS NEGATING CAP SEAL REDUNDANCY.

CAUSE(S):

VIBRATION, PIECE PART STRUCTURAL FAILURE, MECHANICAL SHOCK CONTAM, EXCESS TORQUE, SEAL DAMAGE, NO LINE SUPPORT-SHAFT OR CORE BENT, INADEQ MAINT OF GSE HALF.

EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

(A) LOSS OF SUBSYSTEM PROPELLANT. (B) DEGRADATION OF INTERFACE SUBSYSTEM (PROPELLANT EFFECTS). (C) LAUNCH DELAY OR ABORT DECISION. (D) POTENTIAL CREW LOSS DURING MISSION IF PROPELLANT CANNOT BE UTILIZED OR DEPLETED.

DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

(A) F.S. IS 2.0 X WORKING PRESS. GROUND HALF COUPLINGS AND LINES ARE ADEQ SUPPORTED TO LIMIT ANY UNDUE STRESS ON THE COUPLING DURING SERVICE AND PREV DAMAGE TO SEALS. A SAFETY FEATURE PRIOR TO REMOVAL OF THE END CAP IS A PROV WEREBY ANY LEAKAGE PAST THE AIRBORNE POPPET SEAL CAN BE VENTED OVERBOARD BY ROTATING A BLEED SCREW. COMPLETE STRESS ANAL HAS BEEN CONDUCTED. UTIL OF STRUCT CAP MINIMIZES LEAKAGE POTENTIAL AND PROVIDES A REDUNDANT SEAL EXCEPT FOR STRUCT FAILURE. (B) THE COUPLING IS SUBJECT TO 600 OPER CYCLES (COUPLING AND UNCOUPLING) DURING QUAL IN ADDITION TO PRESS SURGE CYCLING AND PROP EXPOSURE TESTS. RANDOM VIB TESTING IS ALSO CONDUCTED AT ANTIC VEH LEVELS FOR 34 MINUTES IN EACH AXIS. USAGE DURING SYS EVAL TESTS AT WSTF ALLOWS EVAL UNDER ACTUAL USAGE COND. PROOF PRESS TESTS ARE CONDUCTED DURING ATP & LEAKAGE TESTS ARE PERF BEFORE & AFTER OPER CYCLES. (C) AN IDENT IS PERF. RAW MAT'L NDE EXAM, VISUAL INSP FOR SURFACE DEFECTS, & EQUIP CONFORMANCE TO CONTRACT REQMTS ARE VERIF BY RECEIVING INSP. MEASUREMENT STANDARDS & TEST EQUIP. STANDARDS ARE IMPLEMENTED PER REQMTS OF MIL SPECS. THE FOLLOWING ITEMS ARE VERIF BY SHOP TRAVELER MANDATORY INSP POINTS-PARTS.

SHUTTLE CRITICAL ITEMS LIST - CRBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-24 -202150-1 REV:11/08/75
PROT, MFG. PROCESSES, COATING, ASSY AND INSTALLATION. THE ABOVE ITEMS
& THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 5-23-77. COPROS
PROT PROV, CONTAM CONT PROCESSES, TEST HANDLING, & STORAGE ENVIR.
THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT OF MARCH 6, 1978. INSPECTION
VERIFIES ASSEMBLY PER INSPECTION POINTS IN MASTER RECORD. LOG OF CLEAN
ROOM AND CALIBRATION OF TOOLS VERIFIED. CRITICAL DIMENSION 100%
VERIFIED BY INSPECTION. PARTS CLEANLINESS AND PASSIVATION BY
INSPECTION. ADE INSPECTION PERFORMED AFTER ASSEMBLY.
TURNAROUND-COUPPLINGS ARE VISUALLY INSP FOR EVID OF DAMAGE SEALS & LEAK
TESTS ARE PERFORMED. (D) APOLLO FAILURE HISTORY WAS IN THE MAIN ASSOC
WITH GROUND USAGE, IMPROPER HANDLING.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-211110-1

ITEM Propellant Tank Assy.

FAILURE MODE External Leak

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Gross leak detection gives first indication.
6. Pod redundancy.
- 8B. Backup flight system same as primary.

[illegible]

APPROVED : Y:

423

821

TEACHING ACQUISITION: EVIDENCE AND PRACTICE RESEARCH (120 PAGES OF
TEXT) BY: 003/204/304/204

10. FOR SUPPLY PUMPELLANT FOR REACTION CONTROL PROPELLANT, ALL OTHER
 11. FLUIDS BEING PUMPELLANTS FOR ALLUATE FORD DURING 1970, 1971 AND 1972
 12. 1973 CONDITIONS. ITULATED BEING IS SUPPLIED TO THE ALLUATE TO FORD
 13. PROPELLANT TO THE REACTORS AS PERCENT. 240 M2IA (+ 5% -10) 1.0 SAFETY
 14. FACTOR (17.95 QUANT FEF).

EXHIBIT L-26, TIAA WELL CHECK ON STATE FIDELITY.

WELD SHOCK, FATIGUE/VOID, OVERSTRESS, STRESS CORROSION, IMPURITIES, FLOW
OR TEST FLUID, OVER TEMP, PROBLEMS WITH GASES, STRESS RISERS, TYPE
OF WELD DEFECT, INCOMPLETE OR DAMAGED SEAL.

(A) LOSS OF DEGRADATION OF SUB-SYSTEM DEPENDENT OR EXTENT OF FAILURE.
(B) LOSS OF DEGRADATION OF INTER-FCI SUB-SYSTEM-DEPENDS, POSS. LOSS OF
VIA TAPING. (C) ALLOY COLLISION. (D) POSSIBLE LOSS OF DEGRADATION
(E) COLLISION, LACK OF PROPELLANT OR INABILITY TO DEplete OPPOSITE
PROPELLANT).

TAKE ISOLATION VALVE AS APPROPRIATE EVAL SITUATION & EXTENT OF DAMAGE.
INITIATE ABORT OR RESCUE.

PROBABLE CAUSE OF PROP TANKS AND DAMAGE TO FUEL & IPS RESULTING IN FIRE OR EXPLOSION TOXIC, CORROS, FIRE & HAZARD TO GND CREW & VEH. THERE IS EVIDENCE POINTING FOR THIS FAILURE MODE. REFERENCE HAZARDS 1YXX-0302-03, 1YXX-0302-04 AND 1YXX-0304-05.

SHUTTLE CRITICAL ITEMS LIST - CRBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -211110-1 'REV:11/08/78
 ASSEMBLY : PROPELLANT FEED ABORT: CRIT. FUNC: 1
 P/N RI : MC282-0061-0001,-0002 CRIT. HDW: 1
 P/N VENDOR: 355C3310000-010,-020 MISSIONS: HF VF X FF JF SM
 QUANTITY : 4 PHASE(S): PL X LD X OG X DO X LS
 : TWO PER
 : MODULE

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY: DES R BEMIS APPROVED BY: DES *R. Bemis* APPROVED BY (NASA): SSM *W. K. Smith*
 REL C M AKERS REL *C. E. Sams 1479* REL *W. K. Smith*
 APPROVED WITH CHANGES
 See Section 13.0

ITEM: TANK ASSY, PROPELLANT
 INCLUDING ACQUISITION DEVICE AND RETENTION SCREENS (1.5 FACTOR OF
 SAFETY) TK 203/204/303/304.

FUNCTION:

TO STORE/SUPPLY PROPELLANT FOR REACTION CONTROL THRUSTERS. TANK SHELL
 CONTAINS PROPELLANT AND ACQUISITION DEVICE RETAINS PROPELLANTS FOR ADEQUATE FEED
 DURING 1"G, 0"G AND HIGH "G" CONDITIONS. REGULATED HELIUM IS SUPPLIED TO THE
 ULLAGE TO FORCE PROPELLANT TO THE THRUSTERS AS REQ'D. 245 PSIA (+ OR -15)
 (17.95 CUBIC FEET).

FAILURE MODE: STRUCTURAL FAILURE (F)
 EXTERNAL LEAK, TANK WALL CRACK OR SEAL FAILURE.

CAUSE(S):

MECH SHOCK, FATIGUE/VIB, OVERPRESS, STRESS CORROSION, IMPROPER PROP PURITY,
 OR TEST FLUID, OVER TEMP, PLUME OR REENTRY GASES, STRESS RISER, WELD
 OR MAT'L DEFECT, INCORRECT OR DAMAGED SEAL.

EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

(A) LOSS OR DEGRADATION OF SUB-SYSTEM DEPENDENT ON EXTENT OF FAILURE.
 (B) LOSS OR DEGRADATION OF INTERFACE SUB-SYSTEM-AFT RCS, POD, TPS OR
 VEH DAMAGE. (C) ABORT DECISION. (D) POSSIBLE LOSS OF CREW/VEHICLE
 (EXPLOSION, LACK OF PROPELLANT OR INABILITY TO DEplete OPPOSITE
 PROPELLANT).

DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

(A) THE F.S. (BURST) IS 1.5 X WORKING PRESSURE. COMPLETE STRESS
 ANALYSIS FOR EACH TANK SEGMENT WAS PERFORMED. TANK IS CLASSIFIED AS
 FRACTURE CRITICAL FOR HANDLING AND IS SUBJECT TO FRACTURE CONTROL
 REQMTS. ALL FITTINGS AND FLANGES USED ON THE TANK HAVE DUAL ELASTOMER
 SPRING LOADED SEALS. (B) QUAL REQUIRES 800 PRESSURE WITH (INCLUDING
 200 EXPULSION CYCLES AND A 90 DAY CREEP AND PROPELLANT EXPOSURE TEST.
 PROOF PRESSURE (1.3X WORKING PRESSURE) AND LEAKAGE TESTS ARE PERFORMED
 DURING ATP- RADIOGRAPHIC AND DYE PENETRANT TESTS ARE PERFORMED TO
 VERIFY NO PERMANENT DEFORMATION OR FLAW GROWTH. WELDS ARE VISUALLY
 INSPECTED FOR EVIDENCE OF STRESS RISER OR OTHER FLAWS. (C) AN
 IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. RAW MAT'L AND
 PURCHASED COMPONENT REQMTS ARE VERIFIED BY RECEIVING INSP. MEASUREMENT
 STANDARDS AND TEST EQUIP. STANDARDS ARE IMPLEMENTED PER REQMTS OF MIL
 SPECS. THE FOLLOWING ITEMS ARE VERIFIED BY SHOP TRAVELER MANDATORY
 INSPECTION POINTS- PARTS PROTECTION, MFG. PROCESSES, FINISHES, ASSY AND
 INSTALLATION. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -211110-1 REV: 11/03/75
AUDIT CONDUCTED 11-1-76. CORROSION PROTECTION PROVISIONS, TEST
HANDLING, AND STORAGE ENVIRONMENTS. TENSILE, HEAT TREAT AND WELD
SAMPLES ARE TESTED DURING IN-PROCESS FABRICATION IN ADDITION TO X-RAY
AND DYE PENETRANT INSPECTION FOR SURFACE AND SUBSURFACE DEFECTS. BOTH
CERTIFIED WELDERS AND CERTIFIED INSPECTORS ARE USED FOR ALL WELDS.
TURNAROUND- INSPECTION TO MONITOR FUNCTIONAL TEST DURING PRESSURIZATION
CYCLE FOR EVIDENCE OF LEAKS. LEAKAGE TESTS ARE PERFORMED AFTER
INSTALLATION INTO THE SYSTEM AND PERIODICALLY AS PART OF CHECK-OUT
PROCEDURE PRIOR TO FLIGHT. PRESSURE CYCLES ACCUMULATED ARE ALSO
RECORDED. (D) APOLLO FAILURES WERE ASSOC. WITH INCORRECT TEST FLUID
(METHYL ALCOHOL), IMPROPER PROPELLANT NO CONTENT, STRESS RISE OR TEST
ERROR RESULTING IN CREATION OF VACUUM. CORRECTIVE ACTION WAS TAKEN FOR
ALL OF ABOVE FAILURES AND ALSO IMPLEMENTED ON SHUTTLE.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-211110-2

ITEM Propellant Tank Assy

FAILURE MODE Bubbles in Propellant

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☒
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. "Failed off" thruster may illuminate if < 40 psi is sensed 3 times 80 milliseconds apart.

5. Crossfeed.

8b. Same as primary.

97

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-24 -211110-2 REV: 12/13/79
 ASSEMBLY : PROPELLANT FEED ABORT: CRIT. FUNC: 1
 P/N RI : MC292-0061-0001,-0002 CRIT. HDW: 1
 P/N VENDOR: 855C3310000-010,-020 MISSIONS: HF VF X FF OF SM
 QUANTITY : 4 PHASE(S): PL LO X DO X DO LS
 : TWO PER
 : MODULE

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY:

DES R BEMIS
 REL C M AKERS

APPROVED BY:

DES *R. Bemis*
 REL *C. M. Akers*

APPROVED BY NASA:

SSM *W. K. ...*
 REL *...*

APPROVED WITH CHANGES
 See Section 13.0

ITEM: TANK ASSY. PROPELLANT
 INCLUDING ACQUISITION DEVICE AND RETENTION SCREENS (1.5 FACTOR OF
 SAFETY) TK 203/204/303/304.

FUNCTIONS:

TO STORE/SUPPLY PROPELLANT FOR REACTION CONTROL THRUSTERS. ACQUISITION
 DEVICE RETAINS PROPELLANTS FOR ADEQUATE FEED DURING 1"G", 0"G" AND HIGH "G"
 CONDITIONS. REGULATED HELIUM IS SUPPLIED TO THE ULLAGE TO FORCE PROPELLANT TO THE
 THRUSTERS AS REQ'D. 245 PSIA (+ OR -15) (17.95 CUBIC FEET).

FAILURE MODE: STRUCTURAL FAILURE (S)

FAILS TO FEED PROPELLANT DUE TO RETENTION DEVICE FAILURE, GAS BUBBLES
 IN PROPELLANT.

CAUSE(S):

FATIGUE, STRESS CORROSION, CONTAM, VIB, MECH SHOCK, SCREEN COLLAPSE,
 FROZEN PROP, PROP SLOSH LOADS, FASTENING HOWRE FAILS

EFFECT(S): ON (A) SUBSYSTEM (S) INTERFACES (C) MISSION (D) CREW/VEHICLE:

(A,B) SUBSYSTEM AND INTERFACE DEGRADATION - GAS BUBBLES IN PROP CAUSING
 REDUCED THRUST OR COMB INSTAB. (C) ABORT DECISION. (D) POSSIBLE LCSS

OF CREW VEHICLE - NASA STATES FAILURE OF ACQUISITION DEVICE SCREENS COULD CAUSE PREMATURE
 GAS INJECTION INTO THE THRUSTER MANIFOLDS DURING ENTRY MANEUVERING.

DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

(A) SAFETY FACTORS OF 1.5 (MINIMUM) IN SCREEN WILL MINIMIZE FAILURE POTENTIAL. (B) QUAL
 REQUIRES 200 EXPULSION CYCLES A 90 DAY PROPELLANT EXPOSURE TEST. DEVELOPMENT CERTIFICATION
 TESTS DEMONSTRATE 100 MISSION FLOW TRANSIENTS (188,800 CYCLES) AND TWO YEAR PROPELLANT
 COMPATIBILITY. PROPELLANT ACQUISITION DEVICE AND WELD INTEGRITY VERIFIED VIA BUBBLE
 POINT TESTS AT THE COMPONENT, SUBASSEMBLY & TANK ASSY LEVEL. (C) AN IDENTIFICATION IS
 PERFORMED AND THE UNIT TAGGED. RAW MAT'L AND PURCHASED COMPONENT REQMTS ARE VERIFIED BY
 RECEIVING INSP. MEASUREMENT STANDARDS & TEST EQUIP STANDARDS ARE IMPLEMENTED PER REQMTS
 OF MIL SPECS. THE FOLLOWING ITEMS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSPECTION
 POINTS-PARTS PROTECTION, MFG. PROCESSES, FINISHES, ASSY AND THE ABOVE ITEMS AND THE
 FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 11-1-76. CORROSION PROTECTION PROVISIONS,
 TEST HANDLING, AND STORAGE ENVIRONMENTS. BOTH CERTIFIED WELDERS AND CERTIFIED INSPECTORS
 ARE USED FOR ALL WELDS. TURNAROUND - BUBBLE POINT TESTS ARE PERIODICALLY PERFORMED IN
 THE SYSTEM AS PART OF CHECKOUT PROCEDURE PRIOR TO FLIGHT. PRESSURE CYCLES ACCUMULATED
 ARE ALSO RECORDED. (D) NO IN-FLIGHT FAILURE EXPERIENCE FOR THIS DESIGN.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-211120-1

ITEM Gimbal Joint

FAILURE MODE External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☒ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☒ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☐ *NO ☒

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-flight detectability

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Gross leak detection gives first indication.
2. Fuel tank outlet pressure measurements V42P2310, 3310 were omitted from the FMEA and need to be added.
- 3A. Low pressure transducer signals could be used by software to isolate the system automatically if desired.
6. There is one success path remaining after first failure. Cross-feed.
- 8B. Same as primary.

UNITED STATES AIR FORCE - OFFICE OF THE SECRETARY

[illegible]

ተጽዕኖታቸው ሲሆን፡

122

142

N I LAVINICH

C M AKERS

APPROVED BY:

17.44

2. L

1. Introduction

PLATE 11, GERALD J. J. J.

100714

ALL EXTERNALLY CONSTRAINED ELEMENTS (UNIVERSAL SYMBOL SET 1 ONLY) ARE PROVIDED FOR THE IMPERIAL TASK COILLET LINES TO WELD. DIVISION 10 AND 11 SHOWN. DIVISIONS 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837,

SYNOPSIS: STRUCTURAL FAILURE (S)

SYNOPSIS LITERATURE.

$$f^{-1}(S) =$$

FATIGUE, STRESS, CRACKING INADEQUATE WALL PENET, INCOMP. FUSION, POROSITY, SURFUS RESULTING IN FIM HOLE LEAK THRU CORROSION, FROG & LIEPOT, IMPROPER PRESS. STAGE, FLOW INDUCED VIB-FROG DEFECT, FLEI VIB.

4.1 - (C) (S): (a) SUBSYSTEMS (b) INTERFACES (c) MISSION (d) COST/VOLUME:

(A) CUSSETED DEGRADATION - LOSS OF PROPELLANT. (B) DEGRADATION OF INTERFACE FUNCTION - PRESSURE DAMAGE WITHIN POL AND ALUMINUM REFLECTION OR TPS (MOLECULAR VENTING). (C) LAUNCH DELAY OR ALERT DECLINE. (D) POSSIBLE LOSS OF CRYSTAL - IF FELLOWS JOINT SUPPORTS RESULTING IN INABILITY TO ORBIT/CONTROL FROM OR FROM REACTS WITH FUEL OR CAUSING FIRE OR EXPLOSION.

CLOPPING ACTION:

ISOLATE LIAISON AT TANK FUEL VALVE. UTILIZE CMS PROP AS REFUEL. ADVISE CRY
RE FUELING.

90 91 92 93 94 95 :

COMPOSITION 100% FREE PHOSPHORANIS. NOT TOXIC HAZ TO HUM ORFA. DANGER OF
FIRE NOT CATASTROPHIC IF LOW BOOF UNLESS AIR OR CATALYST PRESENT. HAZ
HEAT SHIELD ENVIR IN BOOF. RLF HAZ NO. 1YXX-0302-05.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -211120-1 REV: 11/03/78
 ASSEMBLY : PROPELLANT FEED ABORT: CRIT. FUNC: 1
 P/N RI : 73P550015-101&102 (MDAC) CRIT. HDW: 1
 P/N VENDOR: 1C08099-101&102 (SSP) MISSIONS: HF VF X FF CF SM
 QUANTITY : 12 PHASE(S): PL X LO X CO X DO X LS X
 : 3 PER PROP TANK

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY:
 DES N GLAVINICH
 REL C M AKERS

APPROVED BY:
 DES *[Signature]*
 REL *[Signature]*

APPROVED BY (NASA):
 SSM *[Signature]*
 REL *[Signature]*

APPROVED WITH CHANGES
 See Section 13.0

ITEM: CONNECTOR
 FLEXIBLE, GIMBAL JOINT.

FUNCTION:
 AN EXTERNALLY CONSTRAINED BELLOWS (UNIVERSAL SOCKET JOINT ASS'Y) IS PROVIDED FOR THE PROPELLANT TANK OUTLET LINES TO ALLOW MOVEMENT DURING PRESSURE SURGES. CONNECTING TUBES ARE WELDED TO THE BELLOWS AND TO THE PROP LINES.

FAILURE MODE: STRUCTURAL FAILURE (S)
 EXTERNAL LEAKAGE.

CAUSE(S):
 FATIGUE, SHOCK, HANDLING INDUCED WELD PENET, INCOMP FUSION, POROSITY, CORROS RESULTING IN PIN HOLE LEAK THRU CONVOLUTE, PROP & SI-PROP EXPOSURE PRESS SURGE, FLOW INDUCED VIB-POGC EFFECT, FLT VIB.

EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:
 (A) SUBSYSTEM DEGRADATION - LOSS OF PROPELLANT. (B) DEGRADATION OF INTERFACE FUNCTION - POSS CORROS DAMAGE WITHIN PCD AND ADVERSE EFFECT ON TPS (MOLECULAR VENTING). (C) LAUNCH DELAY OR ABORT DECISION. (D) POSSIBLE LOSS OF CREW/VEHICLE - IF BELLOWS JOINT RUPTURES RESULTING IN INABILITY TO UTILIZE/DEplete PROP OR PROP REACTS WITH FUEL OR OX CAUSING FIRE OR EXPLOSION.

DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:
 (A) MULTIPLE BELLOWS ARE UTILIZED. FLOW INDUCED VIBRATION ANALYSIS AND STRESS ANALYSIS ARE CONDUCTED TO VERIFY ACCEPTABLE DESIGN. THE EXTERNAL CONSTRAINT (UNIVERSAL SOCKET JOINT ASS'Y) WOULD TEND TO LIMIT ANY GROSS PROPELLANT LEAK IN EVENT OF BELLOWS FAILURE. ITEM IS USED DURING SYSTEM EVALUATION TESTS AT WSTF ALLOWING EVALUATION UNDER SIMULATED MISSION USAGE CONDITION. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. CONTAMINATION CONTROL PROCESS, CORROS. PROTECTION PROVISIONS, NDE EXAM OF WELDS, INSP FOR SURFACE AND SUBSURFACE DEFECTS, RAW MAT'L (LOT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP POINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 8-29-77. CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L CONFORMANCE TO CONTRACT REQMTS. TURNAROUND - MONITOR LEAKAGE TESTS PERFORMED AFTER INSTALLATION INTO THE SYSTEM AND AS PART OF CHECKOUT.

SHUTTLE CRITICAL ITEMS LIST - CRBITER 102.

SUBSYSTEM :AFT - REACTION CONTROL . FMEA NO 03-2A -211120-1 REV:11/08/78
- PROCEDURE PRIOR TO FLIGHT. (0) NO FAILURE HISTORY AVILABLE ALTHOUGH THE
APOLLO PROGRAM DID SHOW SOME PROBLEMS ON FLEX HOSE ASSY DUE TO PIN HOLE
CORROSION ASSOC. WITH RESIDUAL SOLVENTS AND PROPELLANT.

.HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT-RCS

FMEA NUMBER 03-2A-221308-1

ITEM Bel lows Assy.

FAILURE MODE External Leakage

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-flight detectability

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. Gross leak detection gives first indication.

1
2
3
4
5

FJC78-2551-24:
 5072-50-1102-4

REVISED 1988

53

421

• 1 - ALIQUOT.

7. STRENGTHEN STEEL EXTERNALLY (CYLINDER) CONFINED THERMS WITH WALL THICKNESS CORRECTIONS IS PROVIDED AS A MEANS OF CORRECTING FOR THE LOSS OF THROTTLE VALVES TO THE PROPPELLANT SYSTEM.

• JENSEN, AL L. / KANSAS. •

• PATIENCE, CHECK, HANDLING, INKED-RED PENIT, INKED FUSION, FUSIONITY, CLOSURE-PAGE 8 (1-PROG) EXPLOSIVE, PRESS SURGE, FLAM INKED VIOLET TO EFFECT, FLAM VIO.

• (a) See SYSTEM DEGRADATION - LOSS OF PROPELLANT. (b) See LOSS OF

7. TPS (MOLECULAR VENTURES). (U) LAUNCH DELAY OR ABORT DECISION. (U)

STANDARD AND HAVE BEEN LIT. FROM SOFTWARE FOR RESEARCH AND MATH.

2. GOALING ACTION:

$\bullet \sim \frac{1}{2} V_{AF} \wedge / m_L Z, R_1 S :$

• COMPOSITION FROM FREE PROPELLANTS. POT. TOXIC HAZ TO GND CREW". DENT AP -
TUNE OUT CATASTROPHIC FELD. DOOF UNLESS AIR OR CATALYST PRESENT. NO
HEAT SHIELD ENVIR IS BACH. FLR HAZ NO. 1YXK-0502-C5.

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - CR6ITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -221308-1 REV:11/08/73
 ASSEMBLY :THRUSTER/PROPELLANT FEED ABORT: CPIT. FUNC: 1
 P/N RI :MC621-0059 CRIT. HDW: 1
 P/N VENDOR:73P5500C3-1001THRU1005 MISSIONS: HF VF X FF CF SM
 QUANTITY :56 PHASE(S): PL X LD X CC X DO X LS X
 :ONE FUEL AND ONE OXIDIZ.
 :PER THRUSTER(PRI & VERN)
 REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY: .
 DES N GLAVINICH
 REL C M AKERS

APPROVED BY:
 DES *[Signature]*
 REL *[Signature]* 12/77

APPROVED BY NASA:
 SSM *[Signature]*
 REL *[Signature]*
 APPROVED WITH CHANGES
 See Section 13.0

ITEM: BELLOWS ASSEM.,
 ENGINE ALIGNMENT.
 FUNCTION:

A STAINLESS STEEL EXTERNALLY (CYLINDER) CONSTRAINED BELLOWS WITH RIGID TUBE END CONNECTIONS IS PROVIDED AS A MEANS OF CONNECTING AND ALIGNING THE THRUSTER VALVES TO THE PROPELLANT SYSTEM.

FAILURE MODE: STRUCTURAL FAILURE (S)
 EXTERNAL LEAKAGE.

CAUSE(S):

FATIGUE, SHOCK, HANDLING, INADEQ WELD PENET, INCOMP FUSION, PROPOXITY, CORROS-PROP & BI-PROP EXPOSURE, PRESS SURGE, FLOW INDUCED VIB-POGO EFFECT, FLT VIB.

EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:
 (A) SUBSYSTEM DEGRADATION - LOSS OF PROPELLANT. (B) DEGRADATION OF INTERFACE FUNCTION - POSS CORROS DAMAGE WITHIN POD AND ADVERSE EFFECT ON TPS (MOLECULAR VENTING). (C) LAUNCH DELAY OR ABORT DECISION. (D) POSSIBLE LOSS OF CREW/VEHICLE - FAILURE NOT DETECTABLE SINCE PVT MEASUREMENTS HAVE BEEN DELETED FROM SOFTWARE FOR ASCENT AND RTLS. (ISOLATION IS POSSIBLE DURING OTHER MISSION PHASES).

DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:
 (A) MULTIPLE BELLOWS ARE UTILIZED. FLOW INDUCED VIBRATION ANALYSIS AND STRESS ANALYSIS WERE CONDUCTED TO VERIFY ACCEPTABLE DESIGN. THE EXTERNAL CONSTRAINT WOULD TEND TO LIMIT ANY GROSS PROPELLANT LEAK IN EVENT OF BELLOWS FAILURE. PROPELLANT LEAK FROM LINE TO THRUSTER COULD BE ISOLATED BY MANIFOLD VALVE. (B) ITEM IS USED DURING SYSTEM EVALUATION TESTS AT WSTF ALLOWING EVALUATION UNDER SIMULATED MISSION USAGE CONDITION. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. CONTAMINATION CONTROL PROCESS, CORROS. PROTECTION PROVISIONS, NOE EXAM OF WELDS, INSP FOR SURFACE AND SUBSURFACE DEFECTS, RAW MAT'L (LOT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP PCINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 8-29-77. CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L CONFORMANCE TO CONTRACT REQTS. TURNAROUND - MONITOR LEAKAGE TESTS PERFORMED AFTER INSTALLATION INTO THE SYSTEM AND AS PART OF CHECKOUT PROCEDURE PRIOR TO FLIGHT. (D) NO FAILURE HISTORY AVAILABLE ALTHOUGH THE APOLLO PROGRAM DID SHOW SOME PROBLEMS ON FLEX HOSE ASSY DUE TO PIN HOLE CORROSION ASSOC. WITH RESIDUAL SOLVENTS AND PROPELLANT.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-221310-4

ITEM Engine Inlet Valve

FAILURE MODE Fails Closed

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☒ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☒ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☒ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|---|--|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input checked="" type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. "Failed off" thruster C&W.

9. FILE FOLDER: "024 ARS FREIGHTS ANALYSIS - 1954-1955" 117

[illegible]

ORIGINAL PAGE IS
OF POOR QUALITY

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-221311-1

ITEM Injection Plate

FAILURE MODE Restricted Flow

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☒ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

In-Flight Detectability

☒ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. "Failed off" thruster C&W.

ARTICLE FAILURE MODE AND EFFECTS ANALYSIS - UNIT 111

NOTE: 1.00 - ELECTRIC CONTROL - PART NO. 00-02-02100-1 - SERIALIZED
2.00 - 1.00 - PART NO. 100-020-00.

ORIGINAL PAGE 11
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -221311-1 REV:11/03/73
 ASSEMBLY :THRUSTER, PRIMARY ABORT: CPIT. FUNC: 23
 P/N RI :MC467-0028 CRIT. HOW: 3
 P/N VENDOR:X30898 MISSIONS: HF VF X FF CF SM
 QUANTITY :24 PHASE(S): PL LO X CO X DO X LS
 :ONE INJECTOR PROVIDED FOR
 :R EACH PRIMARY THRUSTER

REDUNDANCY SCREEN: A-PASS B-FAIL C-PASS

PREPARED BY:

DES
REL

W SEARCY
C M AKERS

APPROVED BY:

DES
REL

[Signature]
[Signature]

APPROVED BY (NASA):

SSM
REL

[Signature]
[Signature]

DELETE

See Section 13.0

ITEM: INJECTOR, PLATE

FUNCTION:

PROVIDES INJECTION & VAPORIZATION OF FUEL AND OXIDIZER FROM THRUSTER INLET VALVES AND PROVIDES DOUBLET MIXING AT 1.50 OX TO FUEL RATIO FOR A HYPERGOLIC REACTION WHICH PRODUCES 825 POUNDS OF THRUST AT 70,000 FEET. ALSO CONTROL CHAMBER WALL COOLING. THE INJECTOR IS CONSTRUCTED OF C-103 COLUMBIUM & WELDED TO THE COMB CHAMB. ACOUSTIC CAVITIES ARE LOCATED AT THE OUTER PERIPHERY OF THE INJ FACE TO PREVENT HIGH FREQ COMB INSTAB.

FAILURE MODE: FAILS OUT OF TOLERANCE (F)
AT RESTRICTED FLOW.

CAUSE(S):

CONTAMINATION, PRODUCTS OF COMBUSTION BLOCKING ORIFICES, FREEZING OF PROPELLANTS.

EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

(A) LOSS OF REDUNDANCY OR FUNCTIONAL DEGRADATION - REDUCED PROP FLOW-CHAM PRESS & THRUST, INADEQ CHAM/INJ FILM COOLING. (B) DEGRADATION OF INTERFACE FUNCTION-INCP GN&C & USE OF ALT THRUSTERS (C) NO EFFECT. (D) NO EFFECT. (E) FUNCTIONAL CRITICALITY EFFECT - ABORT DECISION - DEGRADED PERFORMANCE OF REDUNDANT THRUSTERS WOULD REQUIRE MISSION ABORT.

DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

74 MICRON NOMINAL FILTERS ARE PROVIDED TO CONTROL CONTAMINATION FROM SYS AND SUBSEQUENT HAZARD. AUTOMATIC SWITCH OVER (AND ISOLATION) BY GN&C FAILURE DETECTION SYS. COMPLETE THERMAL AND STRESS ANALYSIS HAVE BEEN COMPLETED. (B) RCS SYS EVAL TEST AT WSTF. THRUSTER QUAL FOR 50,000 CYCLES. SPRAY PATTERN CHECKED DURING ATP. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. CONTAMINATION CONTROL PROCESS, CORROS. PROTECTION PROVISIONS, NDE EXAM OF WELDS, RAW MAT'L (LOT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP POINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 9-2-76. CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L AND EQUIP CONFORMANCE TO CONTRACT REQTS. TURNAROUND INSPECTION TO INCLUDE USE OF OPTICS WHERE ACCESSIBLE TO DETERMINE EVIDENCE OF PLUGGED ORIFICE. FLUID SAMPLING TO BE PERFORMED TO DETECT CONTAMINATION. (D) NO DIRECT FAILURE HISTORY AVAILABLE.

TH

1024

SD75-SH-0003

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-221312-1

ITEM Thrust Chamber

FAILURE MODE Burn-Thru

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☒ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☒ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☒ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. "Failed off" thruster C&W.

SPUTNIK FAILURE MODE AND EFFECTS ANALYSIS - (00114) 112

1. TITLE: SPUTNIK - SPUTNIK JOURNAL
 2. AUTH: SPUTNIK, SPUTNIK
 3. DATE: 1967-001
 4. TYPE: SPUTNIK
 5. CATEGORY: SPUTNIK
 6. SUBJECT: SPUTNIK
 7. ABSTRACT: SPUTNIK
 8. KEYWORDS: SPUTNIK
 9. REFERENCES: SPUTNIK
 10. DISTRIBUTION: SPUTNIK
 11. AVAILABILITY: SPUTNIK
 12. SECURITY: SPUTNIK
 13. CLASSIFICATION: SPUTNIK
 14. DECLASSIFICATION: SPUTNIK
 15. SECURITY: SPUTNIK
 16. SECURITY: SPUTNIK
 17. SECURITY: SPUTNIK
 18. SECURITY: SPUTNIK
 19. SECURITY: SPUTNIK
 20. SECURITY: SPUTNIK
 21. SECURITY: SPUTNIK
 22. SECURITY: SPUTNIK
 23. SECURITY: SPUTNIK
 24. SECURITY: SPUTNIK
 25. SECURITY: SPUTNIK
 26. SECURITY: SPUTNIK
 27. SECURITY: SPUTNIK
 28. SECURITY: SPUTNIK
 29. SECURITY: SPUTNIK
 30. SECURITY: SPUTNIK
 31. SECURITY: SPUTNIK
 32. SECURITY: SPUTNIK
 33. SECURITY: SPUTNIK
 34. SECURITY: SPUTNIK
 35. SECURITY: SPUTNIK
 36. SECURITY: SPUTNIK
 37. SECURITY: SPUTNIK
 38. SECURITY: SPUTNIK
 39. SECURITY: SPUTNIK
 40. SECURITY: SPUTNIK
 41. SECURITY: SPUTNIK
 42. SECURITY: SPUTNIK
 43. SECURITY: SPUTNIK
 44. SECURITY: SPUTNIK
 45. SECURITY: SPUTNIK
 46. SECURITY: SPUTNIK
 47. SECURITY: SPUTNIK
 48. SECURITY: SPUTNIK
 49. SECURITY: SPUTNIK
 50. SECURITY: SPUTNIK
 51. SECURITY: SPUTNIK
 52. SECURITY: SPUTNIK
 53. SECURITY: SPUTNIK
 54. SECURITY: SPUTNIK
 55. SECURITY: SPUTNIK
 56. SECURITY: SPUTNIK
 57. SECURITY: SPUTNIK
 58. SECURITY: SPUTNIK
 59. SECURITY: SPUTNIK
 60. SECURITY: SPUTNIK
 61. SECURITY: SPUTNIK
 62. SECURITY: SPUTNIK
 63. SECURITY: SPUTNIK
 64. SECURITY: SPUTNIK
 65. SECURITY: SPUTNIK
 66. SECURITY: SPUTNIK
 67. SECURITY: SPUTNIK
 68. SECURITY: SPUTNIK
 69. SECURITY: SPUTNIK
 70. SECURITY: SPUTNIK
 71. SECURITY: SPUTNIK
 72. SECURITY: SPUTNIK
 73. SECURITY: SPUTNIK
 74. SECURITY: SPUTNIK
 75. SECURITY: SPUTNIK
 76. SECURITY: SPUTNIK
 77. SECURITY: SPUTNIK
 78. SECURITY: SPUTNIK
 79. SECURITY: SPUTNIK
 80. SECURITY: SPUTNIK
 81. SECURITY: SPUTNIK
 82. SECURITY: SPUTNIK
 83. SECURITY: SPUTNIK
 84. SECURITY: SPUTNIK
 85. SECURITY: SPUTNIK
 86. SECURITY: SPUTNIK
 87. SECURITY: SPUTNIK
 88. SECURITY: SPUTNIK
 89. SECURITY: SPUTNIK
 90. SECURITY: SPUTNIK
 91. SECURITY: SPUTNIK
 92. SECURITY: SPUTNIK
 93. SECURITY: SPUTNIK
 94. SECURITY: SPUTNIK
 95. SECURITY: SPUTNIK
 96. SECURITY: SPUTNIK
 97. SECURITY: SPUTNIK
 98. SECURITY: SPUTNIK
 99. SECURITY: SPUTNIK
 100. SECURITY: SPUTNIK

PREFARED BY:

DES
REL

SEARCH
C M AKERS

APPROVED BY:

DES
REL

1. TITLE: THRUST CHAMBER

2. ABSTRACT: THRUST CHAMBER (COATED COLUMNAR).

3. FUNCTION:

TO CONTAIN HYPERBOLIC REACTION OF PROPELLANTS AND DIRECT COMBUSTION PRODUCTS THROUGH NOZZLE & EXTENSION TO PROVIDE IMPULSE TO VEHICLE. CHAMBER IS CONSTRUCTED OF CH-103 COLOMBIUM WITH R-117 A COATING. A SUSPENDED COATING AND UTILIZES FILM COOLING. THE CHAMBER HAS A 100% EFFICIENCY & IS DESIGNED TO PRODUCE A THRUST OF 57 LBS VACUUM AT A NOMINAL STEADY STATE SPECIFIC IMPULSE OF 280 SECONDS.

4. FAILURE MODE: STRUCTURAL FAILURE (S)

5. BURN THROUGH FRACTURE IN CHAMBER.

6. CAUSE(S):

1. THERMAL CYCLING/STRESS FATIGUE, VIB, COME INSTANT, SPOON. 2. FLOWING OF PROPELLANT, HIGH TEMP/LICALIZED HOT SPOTS/INADEQ COOLING/COOLING RESTRICTION.

7. EFFECT(S): (A) SUBSYSTEM (B) INTERFACES (C) COMMISSION (D) CRYSTAL/VEHICLE:

(A) LOSS OF REDUNDANCY-POSS LOSS OF 3 THRUSTERS IF VALVE 100% VALVE NOT BE CLOSED. (B) DEGRADATION OF INTERFACE FUNCTION-ACK BACK W/ ALL THRUSTERS (C) POSSIBLE POLYMERIZATION/DEGRADATION OF POLYMER COOLING DAMAGED PROPAGATION. (D) POSSIBLE LOSS OF CRYSTAL/VEHICLE CONNECTION MAY CAUSE HIGH TEMP DAMAGE TO SURR STRUCT & ADJ THRUSTERS RESULTING IN POSS ENTRY HAZ IF IFS IS DAMAGED.

8. CORRECTIVE ACTION:

1. ISOLATE PROPELLANTS FROM THRUSTER (AT MANIFOLD LEVEL) AND ASSESS FOR LEAKAGE AND DAMAGE TO SURROUNDING STRUCTURE.

9. REMARKS/HAZARDS:

LONG HAZ IF OXS/ACS PUMP NOT DEPLETED PRIOR TO LONG (RFL). ALSO CHIT FOR RFLS ET SEP (DOWN FIRING). THERE IS NO AUTO THRUSTER ISOL AFTER PURS INITIATION (LORIN FIRING). POT IMPINGMT OF HOT GASES ON MODULE STRUCT & ADJ THRUSTERS. BURN-THRU MAY CAUSE HIGH TEMP DAM TO SURR

5. OTHER FAILURE MODE AND EFFECTS ANALYSIS - UNCLASSIFIED

SC SYSTEMS DEPT - REACTOR CONTROL - ENDA NO 75-22-72131-7 - EVALUATION
STRENGTH AND DISPOSITIONS RESULTING IN POOR QUALITY OF THE PRODUCT

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -221312-1 REV:11/08/78
 ASSEMBLY :THRUSTER, PRIMARY ABORT: CPIT. FUNC: 1
 P/N RI :MC467-0028 CRIT. HDW: 1
 P/N VENDOR:X30958 MISSIONS: HF VF X FF OF SM
 QUANTITY :24 PHASE(S): PL LO X OC X DO X LS
 :ONE PER THRUSTER
 :

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY:
 DES
 REL

SEARCHY
 C M AKERS

APPROVED BY:
 DES
 REL

APPROVED BY: NASA
 SSM
 REL

APPROVED WITH CHANGES

See Section 13.0

ITEM: THRUST CHAMBER

FROM INJECTOR TO NOZZLE EXTENSION (COATED COLUMBIAN).

FUNCTION:

TO CONTAIN HYPERGOLIC REACTION OF PROPELLANTS AND DIRECT COMBUSTION PRODUCTS THROUGH NOZZLE & EXTENSION TO PROVIDE IMPULSE TO VEHICLE. THE CHAMB IS CONSTRUCTED OF C-103 COLUMBIUM WITH P-512 A OXIDATION RESISTANT COATING AND UTILIZES FILM COOLING. THE CHAMB PRESS IS 152 PSI & IS DESIGNED TO PRODUCE A THRUST OF 870 LBS VACUUM AT A NOMINAL STEADY STATE SPECIFIC IMPULSE OF 280 SECONDS.

FAILURE MODE: STRUCTURAL FAILURE (S)
 BURN THRU OR RUPTURE IN CHAMBER.

CAUSE(S):

THERMAL CYCLING/STRESS FATIGUE, VIB, COMB INSTAB, SHOCK. BLOCKED INJ ORIFICES, HIGH TEMP/LOCALIZED HOT SPOTS/INADEQ COOLING NOZZLE RESTRICTION.

EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

(A) LOSS OF REDUNDANCY-POSS LOSS OF 3 THRUSTERS IF M'FOLD ISOL VALVE MUST BE CLOSED. (B) DEGRADATION OF INTERFACE FUNCTION-INCR GM&C & USE OF ALT THRUSTERS (C) MISSION MODIFICATION/ABORT DECISION IF FAILURE CAUSES DAMAGE PROPAGATION. (D) POSSIBLE LOSS OF CREW/VEHICLE BURN-THRU MAY CAUSE HIGH TEMP DAMAGE TO SURR STRUCT & ADJ THRUSTERS RESULTING IN POSS ENTRY HAZ IF TPS IS DAMAGED.

DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

(A) STRUCTURAL MARGINS (2.0 TO 4.0) MINIMIZE FAILURE EFFECT(S). ENG DESIGNED TO INGEST UP TO 45 CU. IN. OF GAS. (B) RCS SYS EVAL TEST AT WSTF. THRUSTER QUAL FOR 50,000 CYCLES. (C) A VISUAL INSP. AND IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. CONTAMINATION CONTROL PROCESS, CORROS. PROTECTION PROVISIONS, NOE EXAM OF WELDS, RAW MAT'L (LOT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP POINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 9-2-76. CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MATL AND EQUIP CONFORMANCE TO CONTRACT REQMTS. TURNAROUND INSPECTION TO INCLUDE USE OF OPTICS WHERE ACCESSIBLE TO DETERMINE EVIDENCE OF PLUGGED ORIFICE. FLUID SAMPLING TO BE PERFORMED TO DETECT CONTAMINATION. (D) NO DIRECT FAILURE HISTORY AVAILABLE.

Hardware/Software Analysis Checklist SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-221313-1

ITEM Nozzle Extension

FAILURE MODE Burn-Thru

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☐ NO ☒
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☐ NO ☒
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☐ *1 ☐ 2 ☒
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

Soils: FAIRBANKS, N. D. AND EFFECTS ANALYSIS - (5417) 15.

SUBJECT : FBI - CLEVELAND OFFICE
REPLY : DEPOSELIS, PERSAPPY
CITY : CLEVELAND
SUBJECT : 07-67-0000
DEPOSELIS :
PERSAPPY :
DEPOSELIS :

[illegible]

WILSON'S COLLEGE IN CHICAGO, YET
THEY WOULD LIKE DEEP RISE
TOSS INTO THE

3. FUEL TURNAROUND?.....YES
VISUAL INSPECTION

PREPARED BY:

٤٠٨

٤٤٤

W CLARCY

C. H. Akerl

$$A_1^2 \cdot P^2 \cdot V \in \mathbb{Q} \quad \text{and} \quad Y:$$

122

434

2110: NOZZLE EXTENSION,
 2120: COARSE COILS (WITH INSULATION BLANKET).
 2130: FLOWLINE

FOR "WIDE ISENTROPIC EXPANSION OF COMBUSTION GASES" FOR USE IN
JET ENGINES. THE EXT IS CONSTRUCTED OF C-113 COMPOSITE WITH AN ALUMINUM
NITRIDE COATING. THE NOZZLE EXPANSION RATIO IS 25 TO 1. THE EXT IS
INTEGRAL WITH THE CLAMP CHAMF AND ENCLOSED IN A CYMA FLOW INLET
CONUS SO THAT THE EXT TEMP IS MAINTAINED PER THE PROPOSED
CERTIFICATION REQ'T.

FAILURE MODE: STRUCTURAL FAILURE, (S)
 OCCURRENCE.

Case (7) :

HIGH TEMPERATURE IN LOCAL SPOT CONTAMINATES INJECTOR CONTROL PIPES AND
IS STILL DEFECT.

EFFECTS: (A) SUBSYSTEM (C) INTERFACES (C) MISSION (C) CREW/VEHICLE
 (A) LOSS OF REDUNDANCY-POSS LOSS OF 2 THROSTERS IF OFFLED ISOL VALVE
 CLOSURE. (B) DEGRADATION OF INTERFACE FUNCTION-THROSTERS & ALL
 OF ALL THROSTERS. PUMP-THRU MAY CAUSE HIGH TEMP DPM TO SOME STRUCTS,
 TIES, & ALL THROSTERS. (C) POSSIBLE COMPLICATION/ACCIDENT DUE TO
 FAILURE CAUSES DAMAGE PROPAGATION. (D) LOSS OF CREW/VEHICLE-CON-
 THRU MAY CAUSE HIGH TEMP DAMAGE TO SOME STRUCT & ALL STRUCTURES
 RESULTING IN POSS ENTRY HAZ IF TPS IS DAMAGED

CONFLICTING ACTION:

ISOLATE THROUSTER AT INLET VALVE OR MANIFOLD AND ASSESS FOR LEAKAGE AND DAMAGE TO SURROUNDING STRUCTURE.

REF ID: A66574

LONG FAZ IF OMS/ROS PROP NOT DEPLETED PRIOR TO LONG CRUISE). ALSO CRUISE
FIRING OF SEP (DOWN FIRING). THERE IS NO APU THROUSTER ISOLATION
BURN INITIATION (DURING FIRING). NOT IMPROVED UP FOR CASE OF APU
SHUT DOWN + APU THROUSTERS. BURN-THRU MAY CAUSE HIGH TEMP DAM TO SOAK

SELECTED PATHOLOGIC AND EFFECTS ANALYSIS - CONTINUED

EXPERIMENT - REACTIVE CONTROL - EPA NO. 03-74-00102 - 10/15/74
EFFECTS - EFFECTS RESULTING IN POSSIBLY DEleterious WORK

ORIGINAL PAGE IS
OF POOR QUALITY

8

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -221313-1 REV: 11/08/78
 ASSEMBLY : THRUSTER, PRIMARY ABORT: CRIT. FUNC: 1
 P/N RI : MC467-0028 CRIT. HOW: 1
 P/N VENDOR: X30872 MISSIONS: HF VF X FF CF SM
 QUANTITY : 24 PHASE(S): PL LD X CC X DC X LS
 : ONE PER THRUSTER
 :

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY:

DES

REL

W. SEARCY

C. M. AKERS

APPROVED BY:

DES

REL

APPROVED BY (NASA):

SSM

REL

APPROVED WITH CHANGES

See Section 13.0

ITEM: NOZZLE EXTENSION.

COATED COLUMBIUM (WITH INSULATION BLANKET).

FUNCTION:

TO PROVIDE ISENTROPIC EXPANSION OF COMBUSTION GASES FOR MAX EFF IN VACUUM. NOZ EXT IS CONSTRUCTED OF C-103 COLUMBIUM WITH P-512A OXIDATION RESISTANT COATING. THE NOZZLE EXPANSION RATIO IS 22 TO 1. THE NOZ EXT IS INTEGRAL WITH THE COMB CHAM AND ENCLOSED IN A DYNA FLEX INSUL SHROUD SO THAT THE EXT TEMP IS MAINTAINED PER THE PROCUREMENT SPECIFICATION REQMT.

FAILURE MODE: STRUCTURAL FAILURE, (S)

BURN-THRU.

CAUSE(S):

HIGH TEMPERATURE IN LOCAL SPOT CONTAMINATED INJECTOR COOLANT HOLES WELD OR MAT'L DEFECT.

EFFECT(S): ON (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE:

(A) LOSS OF REDUNDANCY-POSS LOSS OF 3 THRUSTERS IF XIFOLD ISOL VALVE MUST BE CLOSED. (B) DEGRADATION OF INTERFACE FUNCTION-INCR GNEC & USE OF ALT THRUSTERS. BURN-THRU MAY CAUSE HIGH TEMP DAM TO SURR STRUCT, TPS, & ADJ THRUSTERS (C) MISSION MODIFICATION/ABORT DECISION IF FAILURE CAUSES DAMAGE PROPAGATION. (D) LOSS OF CREW/VEHICLE-BURN-THRU MAY CAUSE HIGH TEMP DAMAGE TO SURR STRUCT & ADJ STRUCTURES RESULTING IN POSS ENTRY HAZ IF TPS IS DAMAGED

DISPOSITION & RATIONALE (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY:

(A) HIGH THERMAL MARGINS IN NOZZLE EXTENSION AND HIGH COOLING MARGIN WILL MINIMIZE FAILURE EFFECT. ENG DESIGNED TO INGEST 45 CU. IN. OF GAS. THRUSTER CAN BE ISOLATED AT INLET OR MANIFOLD VALVE. (B) RCS SYS EVAL TEST AT WSTF. THRUSTER QUAL FOR 50,000 CYCLES. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. CONTAMINATION CONTROL PROCESS, CORROS. PROTECTION PROVISIONS, NOE EXAM OF WELDS, RAW MAT'L (LOT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF. INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP POINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 9-2-76. CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L AND EQUIP CONFORMANCE TO CONTRACT REQTS. TURNAROUND INSPECTION TO INCLUDE USE OF OPTICS WHERE ACCESSIBLE TO DETERMINE EVIDENCE OF BURN-THRU. (D) NO DIRECT FAILURE HISTORY AVAILABLE.

. HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-231310-1

ITEM Vernier Thruster

FAILURE MODE Loss of Output

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☒ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☒ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

3. Down modes to free drift.
- 6.. No redundancy in the verniers.

```

FMSA RT 08-24 -C1101-0          SV1117-0
ALERT:                               C1101-0002
                                      C1101-0003
DISCUSSION:  RE  MR / FR  N/A
FRASER(S):   PL  LL  E  N  L  LS
NUMBER OF SUCCESS PAGES CONTAINED
AFTER FIRST FAILURE:

```

RELEASED BY SOURCE: ATLAS: 1-7/50 (1-7/50)
 1100 11 11 11 11
 11 11 11 11
 REFERENCE: 1-7/50
 11 11 11 11
 11 11 11 11
 11 11 11 11
 11 11 11 11
 11 11 11 11

LES
VILLE

NO HAZARDS IDENTIFIED. PRIMARY THRUSTERS MOVE VEHICLE TO WITHIN 25-40 FT OF PAYLOAD. PAYLOAD (JAW ARMS ARE 55 FT LONG. (THEY ARE NOT DESIGNED TO WITHSTAND FORCES OF PRIMARY THRUSTING). IT IS POSSIBLE PAYLOAD COULD BE RETRIEVED WHILE IN FREE DRIFT MODE AND IN SOME INSTANCES PAYLOAD JAW

SHUTTLE CRITICAL ITEMS LIST - CRITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO. 03-2A -231310-1 REV: 11/08/75
 ASSEMBLY : VERNIER THRUSTER ABORT: CRIT. FUNC: 2
 P/V RI : MC467-0029 CRIT. HDW: 2
 P/N VENDOR: MISSIONS: HF VF X FF GF SM
 QUANTITY : 4 PHASE(S): PL LO CO X OO LS
 : 2 PER POD
 : 1 PITCH, 1 YAW

REDUNDANCY SCREEN: A-PASS B-PASS C-FAIL

PREPARED BY:

DES
REL

J. TAGGART
C. M. AKERS

APPROVED BY:

DES
REL

[Signature]
[Signature]

APPROVED BY: KINASH:

SSM
REL

[Signature]
[Signature]

APPROVED WITH CHANGES
See Section 13.0

ITEM: THRUSTER, ASSY, VERNIER

25 POUND THRUST LEVEL. EN 357/358/257/258.

FUNCTION:

ONE PITCH (2 AXIS-UP FIRING) AND ONE YAW (PLUS/MINUS Y AXIS) VERNIER THRUSTER ARE PROVIDED IN EACH ARCS MODULE TO PROVIDE PRECISE LOW LEVEL PULSING AND ATTITUDE HOLD REQ'D FOR PAYLOAD POINTING. THEY ARE CONCEPTUALLY SIMILAR TO THE PRIMARY THRUSTER BUT LIMIT PLUME IMPINGEMENT AND PROP RESIDUE CONTAM TO THE PAYLOAD.

FAILURE MODE: LOSS OF OUTPUT (THRUST) (F)

INLET VALVES CLOSED OR INJ ORIFICE PLUGGED.

CAUSE(S):

OPEN SGL COIL, AUTO SHUT-DOWN, INLET VLV LEAK/STRUCT FAIL, INJ CONTAM/RESIDUE OR FROZEN PROP BLOCKING ORIFICE, COMB CHAM/NOZ STRUCT FAIL.

EFFECT(S): ON (A) SUBSYSTEM (9) INTERFACES (C) MISSION (J) CREW/VEHICLE:

(A) LOSS OF FUNCTION (VERNIER THRUSTERS)-CURRENTLY LOSS OF SINGLE VERNIER THRUSTER CAUSES LOSS (SHUTDOWN) OF VERNIER CONTROL. (B) NO EFFECT. (C) MISSION MODIFICATION OR ABORT DECISION (POTENTIAL INABILITY TO RETRIEVE PAYLOAD). - IT IS POSSIBLE PAYLOAD COULD BE RETRIEVED WHILE IN FREE DRIFT MODE AND IN SOME INSTANCES PAYLOAD MAY HAVE ATTITUDE & TRANSLATION CONTROL. IT MAY BE POSSIBLE TO USE FWD & AFT RCS (X AXIS) ENGINES FOR PITCH (DOWNWARD) MOTION. (D) NO EFFECT.

DISPOSITION & RATIONALE (A) DESIGN (9) TEST (C) INSPECTION (D) FAILURE HISTORY:

(A) POSS REDUND MODES IN X AXIS PRIMARY THRUSTER, PAYLOAD ATTITUDE CONTROL & FREE DRIFT MODES. 100 MICRON FILTRATION & HEATERS PROVIDED TO LIMIT CONTAM & PREVENT PROP FREEZING. (B) THRUSTER QUAL FOR 500,000 CYCLES, 125,000 SEC BURN TIME, INLET VALVE TESTED FOR 500,000 WET CYCLES & 5000 DRY. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. CONTAMINATION CONTROL PROCESS, CORROS. PROTECTION PROVISIONS, NDE EXAM OF WELDS, RAW MAT'L (LOT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP POINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 9-2-76. CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L AND EQUIP CONFORMANCE TO CONTRACT REQMTS. TURNAROUND - VISUAL INSP USING OPTICAL INSTRUMENTATION. SYSTEM FLUIDS ARE ANALYSED FOR EVIDENCE OF CONTAMINATION. PROPER INLET VALVE FUNCTION AND ELECTRICAL LOGIC POWER IS VERIFIED. (D) NO DIRECT FAILURE HISTORY AVAILABLE.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT- RCS

FMEA NUMBER 03-2A-231310-2

ITEM Vernier Thruster

FAILURE MODE Fails to Stop Firing

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☒ NO ☐
2. ARE THE ANSWERS TO QUESTIONS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☒ *NO ☐
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☐ NO ☒
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☐ NO ☒
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. "Failed on" thruster C&W.
6. No redundancy in the verniers.

ORIGINAL PAGE IS
OF POOR QUALITY

LIFE-SPAN, HEALTH, AND LIFE-COSTS ANALYSIS - 1981-1982-1983

1. TYPE : 11 - REACTION CONTROL
 2. NAME : MR. JOHN HENRIKSON
 3. DOB : 1927-06-29
 4. GRADE :
 5. ID :
 6. RANK :
 7. POSITION :
 8. STATUS :
 9. COMMENTS :
 10. DATE :
 11. BY :
 12. APPROVED :
 13. SIGNATURE :
 14. DATE :
 15. BY :
 16. APPROVED :
 17. SIGNATURE :
 18. DATE :
 19. BY :
 20. APPROVED :
 21. SIGNATURE :
 22. DATE :
 23. BY :
 24. APPROVED :
 25. SIGNATURE :
 26. DATE :
 27. BY :
 28. APPROVED :
 29. SIGNATURE :
 30. DATE :
 31. BY :
 32. APPROVED :
 33. SIGNATURE :
 34. DATE :
 35. BY :
 36. APPROVED :
 37. SIGNATURE :
 38. DATE :
 39. BY :
 40. APPROVED :
 41. SIGNATURE :
 42. DATE :
 43. BY :
 44. APPROVED :
 45. SIGNATURE :
 46. DATE :
 47. BY :
 48. APPROVED :
 49. SIGNATURE :
 50. DATE :
 51. BY :
 52. APPROVED :
 53. SIGNATURE :
 54. DATE :
 55. BY :
 56. APPROVED :
 57. SIGNATURE :
 58. DATE :
 59. BY :
 60. APPROVED :
 61. SIGNATURE :
 62. DATE :
 63. BY :
 64. APPROVED :
 65. SIGNATURE :
 66. DATE :
 67. BY :
 68. APPROVED :
 69. SIGNATURE :
 70. DATE :
 71. BY :
 72. APPROVED :
 73. SIGNATURE :
 74. DATE :
 75. BY :
 76. APPROVED :
 77. SIGNATURE :
 78. DATE :
 79. BY :
 80. APPROVED :
 81. SIGNATURE :
 82. DATE :
 83. BY :
 84. APPROVED :
 85. SIGNATURE :
 86. DATE :
 87. BY :
 88. APPROVED :
 89. SIGNATURE :
 90. DATE :
 91. BY :
 92. APPROVED :
 93. SIGNATURE :
 94. DATE :
 95. BY :
 96. APPROVED :
 97. SIGNATURE :
 98. DATE :
 99. BY :
 100. APPROVED :
 101. SIGNATURE :
 102. DATE :
 103. BY :
 104. APPROVED :
 105. SIGNATURE :
 106. DATE :
 107. BY :
 108. APPROVED :
 109. SIGNATURE :
 110. DATE :
 111. BY :
 112. APPROVED :
 113. SIGNATURE :
 114. DATE :
 115. BY :
 116. APPROVED :
 117. SIGNATURE :
 118. DATE :
 119. BY :
 120. APPROVED :
 121. SIGNATURE :
 122. DATE :
 123. BY :
 124. APPROVED :
 125. SIGNATURE :
 126. DATE :
 127. BY :
 128. APPROVED :
 129. SIGNATURE :
 130. DATE :
 131. BY :
 132. APPROVED :
 133. SIGNATURE :
 134. DATE :
 135. BY :
 136. APPROVED :
 137. SIGNATURE :
 138. DATE :
 139. BY :
 140. APPROVED :
 141. SIGNATURE :
 142. DATE :
 143. BY :
 144. APPROVED :
 145. SIGNATURE :
 146. DATE :
 147. BY :
 148. APPROVED :
 149. SIGNATURE :
 150. DATE :
 151. BY :
 152. APPROVED :
 153. SIGNATURE :
 154. DATE :
 155. BY :
 156. APPROVED :
 157. SIGNATURE :
 158. DATE :
 159. BY :
 160. APPROVED :
 161. SIGNATURE :
 162. DATE :
 163. BY :
 164. APPROVED :
 165. SIGNATURE :
 166. DATE :
 167. BY :
 168. APPROVED :
 169. SIGNATURE :
 170. DATE :
 171. BY :
 172. APPROVED :
 173. SIGNATURE :
 174. DATE :
 175. BY :
 176. APPROVED :
 177. SIGNATURE :
 178. DATE :
 179. BY :
 180. APPROVED :
 181. SIGNATURE :
 182. DATE :
 183. BY :
 184. APPROVED :
 185. SIGNATURE :
 186. DATE :
 187. BY :
 188. APPROVED :
 189. SIGNATURE :
 190. DATE :
 191. BY :
 192. APPROVED :
 193. SIGNATURE :
 194. DATE :
 195. BY :
 196. APPROVED :
 197. SIGNATURE :
 198. DATE :
 199. BY :
 200. APPROVED :
 201. SIGNATURE :
 202. DATE :
 203. BY :
 204. APPROVED :
 205. SIGNATURE :
 206. DATE :
 207. BY :
 208. APPROVED :
 209. SIGNATURE :
 210. DATE :
 211. BY :
 212. APPROVED :
 213. SIGNATURE :
 214. DATE :
 215. BY :
 216. APPROVED :
 217. SIGNATURE :
 218. DATE :
 219. BY :
 220. APPROVED :
 221. SIGNATURE :
 222. DATE :
 223. BY :
 224. APPROVED :
 225. SIGNATURE :
 226. DATE :
 227. BY :
 228. APPROVED :
 229. SIGNATURE :
 230. DATE :
 231. BY :
 232. APPROVED :
 233. SIGNATURE :
 234. DATE :
 235. BY :
 236. APPROVED :
 237. SIGNATURE :
 238. DATE :
 239. BY :
 240. APPROVED :
 241. SIGNATURE :
 242. DATE :
 243. BY :
 244. APPROVED :
 245. SIGNATURE :
 246. DATE :
 247. BY :
 248. APPROVED :
 249. SIGNATURE :
 250. DATE :
 251. BY :
 252. APPROVED :
 253. SIGNATURE :
 254. DATE :
 255. BY :
 256. APPROVED :
 257. SIGNATURE :
 258. DATE :
 259. BY :
 260. APPROVED :
 261. SIGNATURE :
 262. DATE :
 263. BY :
 264. APPROVED :
 265. SIGNATURE :
 266. DATE :
 267. BY :
 268. APPROVED :
 269. SIGNATURE :
 270. DATE :
 271. BY :
 272. APPROVED :
 273. SIGNATURE :
 274. DATE :
 275. BY :
 276. APPROVED :
 277. SIGNATURE :
 278. DATE :
 279. BY :
 280. APPROVED :
 281. SIGNATURE :
 282. DATE :
 283. BY :
 284. APPROVED :
 285. SIGNATURE :
 286. DATE :
 287. BY :
 288. APPROVED :
 289. SIGNATURE :
 290. DATE :
 291. BY :
 292. APPROVED :
 293. SIGNATURE :
 294. DATE :
 295. BY :
 296. APPROVED :
 297. SIGNATURE :
 298. DATE :
 299. BY :
 300. APPROVED :
 301. SIGNATURE :
 302. DATE :
 303. BY :
 304. APPROVED :
 305. SIGNATURE :
 306. DATE :
 307. BY :
 308. APPROVED :
 309. SIGNATURE :
 310. DATE :
 311. BY :
 312. APPROVED :
 313. SIGNATURE :
 314. DATE :
 315. BY :
 316. APPROVED :
 317. SIGNATURE :
 318. DATE :
 319. BY :
 320. APPROVED :
 321. SIGNATURE :
 322. DATE :
 323. BY :
 324. APPROVED :
 325. SIGNATURE :
 326. DATE :
 327. BY :
 328. APPROVED :
 329. SIGNATURE :
 330. DATE :
 331. BY :
 332. APPROVED :
 333. SIGNATURE :
 334. DATE :
 335

PREFACE : Y :

Dr. S.

J. TACHAKI

REL

C. A. K. E. S.

APPROVED BY:

452

544

• 11-27 1900 100, ASSY, VALLEY

1. LOSS OF USE. FR 257/258/259/260.

NOTES

JOINTS (TO ANISOTROPY PLATING) ARE THE YAW (PLUG/HINGE Y AXIS) JOINTS. THROUSTERS ARE PROVIDED IN EACH AREA MODULE TO PROVIDE PRECISE LOW LEVEL POSITIONING AND ATTITUDE HOLD SCORD FOR PAYLOAD POINTING. THEY ARE CONCEPTUALLY SIMILAR TO THE PRIMARY THRUSTER BUT DIFFER IN THE FOLLOWING: 1) AND PROP NOZZLES CONTAIN TO THE PAYLOAD.

• ILU: 000 : FAILS TO STOP

(F)

• FIELD COPY, FIELD RECORDS (INCLUSIVE COMPILES FILING).

$$e_1 \cup e_2 = \{6\} :$$

- CONTAMINATION, STRUCTURAL FAILURE, LOCAL SHORT IN DRIVE, DISCORD IN WORK
 OF FIRE COMMAND, VIP, SMOKE SEAL SEAT BAG, PROP RESIDUE, FLAME SPILLS,
 CIGARETTE, WASH.

• TOPICS: (1) SUBSYSTEMS (2) INTERFACES (3) DESIGN (4) CASE STUDIES

• (-) LOSS OF FUNCTION (VARIER THROSTERS) - CURRENTLY LOSS OF SINGLE

• WISCONSIN TO SUSPECT CAUSE LOSS (SHOOTDOWN) OF VERNIER CONTROL. (U)

DEVIATION OF INTERFACE SUB-SYSTEM - PROP LOSS DUE TO EXCESS EXHAUSTIVE
GATE HANDLED CAN BE ISOLATED-LOSS DUE TO PAYLOAD OF PAYLOAD BY
AFTER (C) MISSION MODIFICATION OR ABORT DECISION. (D) ALL EFFECT.

- DIRECTIONAL ACTING:

• ISOLATE POOLED THROUSTER WITH UPSTREAM MANIFOLD ISOLATION VALVE.

EVOLVED TO DETERMINE NEED FOR ALERT VERSUS USE OF PRIMARY THROTTLES,
FIRE DRIFT MODE OR PAYLOAD ATTITUDE CONTROL.

• 227-5/1-27-65:

• POSSIBLE DAMAGE TO PAYLOAD OR PAYLOAD BAY ARMS. PRIMARY THREATS TO THE VEHICLE WITHIN 25-40 FT OF PAYLOAD. PAYLOAD BAY ARMS ARE 14 FT LONG. IT IS POSSIBLE PAYLOAD COULD BE RETRIEVED WHILE IN FREE DRIFT MODE & IN SOME INSTANCES PAYLOAD MAY HAVE ATTITUDE & TRANSLATION CONTROL. IT MAY BE POSS TO USE FWL & AFT RCS (X AXIS) ENGINES FOR FLIP (DOWNWARD)

ORIGINAL PAGE IS
OF POOR QUALITY

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM :AFT - REACTION CONTROL FMEA NO 03-2A -231310-2 REV:11/09/79
 ASSEMBLY :VERNIER THRUSTER ABORT: CPIT. FUNC: 2
 P/N RI :MC467-0029 CRIT. HDW: 2
 P/N VENDOR: MISSIONS: HF VF X FF DF SM
 QUANTITY :4 PHASE(S): PL LO CO X DO LS
 :2 PER POD
 :1 PITCH, 1 YAW

REDUNDANCY SCREEN: A-PASS B-PASS C-FAIL

PREPARED BY:

DES

REL

J TAGGART

C M AKERS

APPROVED BY:

DES

REL

APPROVED BY (NASA)

SSM

REL

DELETE

See Section 13.0

ITEM: THRUSTER, ASSY, VERNIER

25 POUND THRUST LEVEL. EN 357/358/257/258.

FUNCTION:

ONE PITCH (2 AXIS-UP FIRING) AND ONE YAW (PLUS/MINUS Y AXIS) VERNIER THRUSTER ARE PROVIDED IN EACH ARES MODULE TO PROVIDE PRECISE LOW LEVEL PULSING AND ATTITUDE HOLD REQ'D FOR PAYLOAD POINTING. THEY ARE CONCEPTUALLY SIMILAR TO THE PRIMARY THRUSTER BUT LIMIT PLUME IMPINGEMENT AND PROP RESIDUE CONTAM TO THE PAYLOAD.

FAILURE MODE: FAILS TO STOP (F)

FAILS OPEN, FAILS TO CLOSE (THRUSTER CONTINUES FIRING).

CAUSE(S):

CONTAMINATION, STRUCTURAL FAILURE, DUAL SHORT IN DRIVER CIRCUIT OR DUAL MDM FIRE COMMAND, VIB, SHOCK SEAL SEAT DAM, PROP RESIDUE, FLUSH SALTS, CORROS, WEAR.

EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

(A) LOSS OF FUNCTION (VERNIER THRUSTERS) - CURRENTLY LOSS OF SINGLE VERNIER THRUSTER CAUSES LOSS (SHUTDOWN) OF VERNIER CONTROL. (B) DEGRADATION OF INTERFACE SUB-SYSTEM - PROP LOSS DUE TO EXCESS BURN-TIME UNTIL MANIFOLD CAN BE ISOLATED-POSS DAMAGE TO PAYLOAD OR PAYLOAD BAY ARMS. (C) MISSION MODIFICATION OR ABORT DECISION. (D) NO EFFECT.

DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

(A) ISOLATION CAPABILITY IS AN AUTOMATIC FUNCTION WHICH WILL MINIMIZE FAILURE EFFECT. POSS REDUND MODES OF OPERATION. (PRIMARY THRUSTERS, FREE DRIFT MODE & PAYLOAD ATTITUDE CONTROL MAY PROVIDE ADDITIONAL CONTROL POTENTIAL). 100 MICRON FILTRATION PROVIDED. INADVERTENT FIRE SIGNAL IS IMPROBABLE DUE TO GPC/MDM DESIGN. (B) THRUSTER QUAL FOR 500,000 CYCLES, 125,000 SEC BURN TIME, INLET VALVE TESTED FOR 500,000 WET CYCLES & 5000 DRY. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. CONTAMINATION CONTROL PROCESS, CORROS. PROTECTION PROVISIONS, NDE EXAM OF WELOS, RAW MAT'L (LGT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER MANDATORY INSP POINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 9-2-76. CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L AND EQUIP CONFORMANCE TO CONTRACT REQTS. TURNAROUND - SYSTEM FLUIDS ARE ANALYSED FOR EVIDENCE OF CONTAMINATION. PROPER INLET VALVE FUNCTION AND ELECTRICAL LOGIC POWER IS VERIFIED. (D) NO DIRECT FAILURE HISTORY AVAILABLE.

HARDWARE/SOFTWARE ANALYSIS CHECKLIST SD72-SH-0103-2

SUBSYSTEM AFT - RCS

FMEA NUMBER 03-2A-231310-3

ITEM Vernier Thruster

FAILURE MODE Burn Thru

1. DOES THE FLIGHT SOFTWARE DETECT THIS FAILURE MODE (i.e., AUTOMATICALLY ANNUNCIATE OR TAKE ACTION IN RESPONSE)? YES ☒ NO ☐
- 1a. IF NOT, DOES THE HARDWARE PROVIDE INFORMATION THAT THE FLIGHT SOFTWARE COULD USE TO DETECT THE FAILURE? *YES ☒ NO ☐
2. ARE THE ANSWERS 1 AND 1a CONSISTENT WITH THE FMEA EVALUATION OF IN-FLIGHT DETECTABILITY? YES ☐ *NO ☒
3. DOES THE FLIGHT SOFTWARE TAKE ACTION TO NEGATE THE EFFECTS OF THE FAILURE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? YES ☒ NO ☐
- 3a. IF NOT, DOES THE CAPABILITY EXIST FOR THE SOFTWARE TO COMPENSATE FOR THIS FAILURE MODE (EITHER BY COMMANDING HARDWARE ACTION OR IMPLEMENTING ALTERNATE PROGRAM LOGIC)? *YES ☒ NO ☐
4. AS A RESULT OF THIS FAILURE MODE, CAN THE SOFTWARE OVERSTRESS THE HARDWARE OR INDUCE ANOTHER FAILURE? *YES ☐ NO ☒
5. CAN THIS FAILURE MODE, IN COMBINATION WITH SOFTWARE LOGIC, ADVERSELY AFFECT OTHER FUNCTIONS? *YES ☐ NO ☒
6. HOW MANY OF THESE HARDWARE FAILURES CAN THE SHUTTLE TOLERATE (CONSIDER CREW ACTION AND HARDWARE/SOFTWARE OPERATION)? NOTE CHANGE TO FMEA CRITICALITY. *0 ☒ *1 ☐ 2 ☐
7. IF CREW ACTION IS REQUIRED TO RESPOND TO THIS FAILURE MODE, ARE CUES PROVIDED TO SIGNAL THE NEED FOR INTERVENTION AND THE REQUIRED CORRECTIVE ACTION? N/A ☐ YES ☒ NO ☐
8. IF THE ANSWER TO EITHER 1 OR 3 IS YES:
 - A. CAN THE BFS BE ENGAGED AFTER OCCURRENCE? YES ☒ *NO ☐
 - B. WILL BFS TOLERATE FAILURE WITHOUT LOSS OF CREW/VEHICLE? YES ☒ *NO ☐

*EXPLANATION REQUIRED (SEE BELOW)

CHANGE/RETENTION RATIONALE SUMMARY

- | | | |
|--|---|--|
| 1. <input type="checkbox"/> NO H/S ISSUES | 3. <input type="checkbox"/> NO SOFTWARE DETECTION | 5. <input type="checkbox"/> ACCEPTANCE RATIONALE BELOW |
| 2. <input checked="" type="checkbox"/> HARDWARE ACCEPTS RISK | 4. <input type="checkbox"/> DETECTION DURING CHECKOUT | 6. <input type="checkbox"/> RECOMMENDED CHANGES BELOW |

☐ FMEA CHANGE RECOMMENDED

EXPLANATION/COMMENTS:

1. "Failed off" thruster C&W.
3. Down modes to free drift.
6. No redundancy in the verniers.

SHUTTLE FAILURE MODE AND EFFECTS ANALYSIS - ORBITER 102

| | | |
|---|--------------------------------------|---------------|
| SUBSYSTEM :AFT - REACTION CONTROL | FMEA NO 03-2A -231310-3 | REV:11/C8/78 |
| ASSEMBLY :VERNIER THRUSTER | ABORT: | CRIT. FUNC: 1 |
| P/N PI :MC467-0C29 | | CRIT. HWD: 1 |
| P/N VENDOR: | MISSIONS: HF VF X HF OF SM | |
| QUANTITY :4 | PHASE(S): PL LQ X QO X QO X LS | |
| :2 PER POD | NUMBER OF SUCCESS PATHS REMAINING | |
| :1 PITCH, 1 YAW | AFTER FIRST FAILURE: | 2 |
| | REDUNDANCY SCREEN: A-N/A B-N/A C-N/A | |
| FAILURE DETECTABLE IN FLIGHT?. YES | TIME TO EFFECT: | |
| CHAMBER PRESSURE ON EACH ENGINE, V42P82521 THRU | SECONDS | |
| V42P-2534 AND V42P-3521 THRU V42P-3534 | REFERENCE DOCUMENTS: | |
| | MC 621-C059 | |
| GROUND TURNAROUND?.....YES | MJ070-0001-018 | |
| VISUAL INSPECITON | SD72-SH-C103-2 | |
| | VS70-421001 | |

PREPARED BY:

DES
REL

J. TAGGART
C M AKERS

APPROVED BY:

DES
REL

ITEM: THRUSTER, ASSY, VERNIER
25 POUND THRUST LEVEL. EN 357/358/257/258.

FUNCTION:

ONE PITCH (2 AXIS-UP FIRING) AND ONE YAW (PLUS/MINUS Y AXIS) VERNIER THRUSTER ARE PROVIDED IN EACH ARCS MODULE TO PROVIDE PRECISE LOW LEVEL PULSING AND ATTITUDE HOLD REQ'D FOR PAYLOAD POINTING. THEY ARE CONCEPTUALLY SIMILAR TO THE PRIMARY THRUSTER BUT LIMIT PLUME IMPINGEMENT AND PROPP RESIDUE CONTAM TO THE PAYLOAD.

FAILURE MODE: STRUCTURAL FAILURE (S)

BURN THRU OR RUPTURE IN CHAMBER.

CAUSE(S):

THERMAL CYCLING/STRESS FATIGUE, VIB, COMB INSTAB, SHOCK. BLOCKED INJ ORIFICES; HIGH TEMP/LOCALIZED HOT SPOTS/INADEQ COOLING NOZZLE RESTRICTION.

EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

(A) LOSS OF FUNCTION-CURRENTLY LOSS OF SINGLE VERNIER THRUSTER CAUSES LOSS (SHUTDOWN) OF VERNIER CONTROL. (B) DEGRADATION OF INTERFACE FUNCTION-INCR GN&C & USE OF ALT THRUSTERS (C) MISSION MODIFICATION/ABORT DECISION IF FAILURE CAUSES DAMAGE PROPAGATION. (D) POSSIBLE LOSS OF CREW/VEHICLE-BURN-THRU MAY CAUSE HIGH TEMP DAMAGE TO SUPR STRUCT & ADJ THRUSTERS RESULTING IN POSS ENTRY HAZ IF TPS IS DAMAGED.

CORRECTING ACTION:

ISOLATE PROPELLANTS FROM THRUSTER (AT MANIFOLD LEVEL) AND ASSESS FOR LEAKAGE AND DAMAGE TO SURROUNDING STRUCTURE.

REMARKS/HAZARDS:

THERE IS NO AUTO THRUSTER ISOL AFTER BURN INITIATION (DURING FIRING). POT IMPINGENT OF HLT GASES ON MODULE STRUCT & ADJ THRUSTERS. BURN-THRU MAY CAUSE HIGH TEMP DAM TO SUPR STRUCT & ADJ THRUSTERS RESULTING IN POSS ENTRY HAZ IF TPS IS DAMAGED.

SHUTTLE CRITICAL ITEMS LIST - ORBITER 102

SUBSYSTEM : AFT - REACTION CONTROL FMEA NO 03-2A -231310-3 FEV:11/08/78
 ASSEMBLY : VERNIER THRUSTER ABORT: CRIT. FUNC: 1
 P/N RI : MC467-0029 CRIT. HCN: 1
 P/N VENDGR: MISSIONS: HF VF X FF CF SM
 QUANTITY : 4 PHASE(S): PL LD X CO X DC X LS
 : 2 PER POD
 : 1 PITCH, 1 YAW

REDUNDANCY SCREEN: A-N/A B-N/A C-N/A

PREPARED BY:

DES J TAGGART
 REL C M AKERS

APPROVED BY:

DES *[Signature]*
 REL *[Signature]*

APPROVED BY (NASA):

SSM *[Signature]*
 PEV *[Signature]*

APPROVED WITH CHANGES

See Section 13.0

ITEM: THRUSTER, ASSY, VERNIER

25 POUND THRUST LEVEL. EN 357/358/257/258.

FUNCTION:

ONE PITCH (2 AXIS-UP FIRING) AND ONE YAW (PLUS/MINUS Y AXIS) VERNIER THRUSTER ARE PROVIDED IN EACH APCS MODULE TO PROVIDE PRECISE LOW LEVEL PULSING AND ATTITUDE HOLD REQ'D FOR PAYLOAD POINTING. THEY ARE CONCEPTUALLY SIMILAR TO THE PRIMARY THRUSTER BUT LIMIT PLUME IMPINGEMENT AND PROP RESIDUE CONTAM TO THE PAYLOAD.

FAILURE MODE: STRUCTURAL FAILURE (S)

BURN THRU OR RUPTURE IN CHAMBER.

CAUSE(S):

THERMAL CYCLING/STRESS FATIGUE, VIB, COMB INSTAB, SHOCK. BLOCKED INJ ORIFICES, HIGH TEMP/LOCALIZED HOT SPOTS/INADEQ COOLING NOZZLE RESTRICTION.

EFFECT(S): ON (A)SUBSYSTEM (B)INTERFACES (C)MISSION (D)CREW/VEHICLE:

(A) LOSS OF FUNCTION-CURRENTLY LOSS OF SINGLE VERNIER THRUSTER CAUSES LOSS (SHUTDOWN) OF VERNIER CONTROL. (B) DEGRADATION OF INTERFACE FUNCTION-INCR GN&C & USE OF ALT THRUSTERS (C) MISSION MODIFICATION/ABORT DECISION IF FAILURE CAUSES CAMPE PROPAGATION. (D) POSSIBLE LOSS OF CREW/VEHICLE-BURN-THRU MAY CAUSE HIGH TEMP DAMAGE TO SURR STRUCT & ADJ THRUSTERS RESULTING IN POSS ENTRY HAZ IF TPS IS DAMAGED.

DISPOSITION & RATIONALE (A)DESIGN (B)TEST (C)INSPECTION (D)FAILURE HISTORY:

(A) STRUCTURAL MARGINS (2.0 TO 4.0) MINIMIZE FAILURE EFFECT(S). POSS REDUND MODES IN X AXIS PRIMARY THRUSTER, PAYLOAD ATTITUDE CONTROL & FREE DRIFT MODES. 100 MICRON FILTRATION & HEATERS PROVIDED TO LIMIT CONTAM & PREVENT PROP FREEZING. (B) THRUSTER QUAL FOR 500,000 CYCLES, 125,000 SEC BURN TIME, INLET VALVE TETED FOR 500,000 WET CYCLES & 5000 DRY. (C) A VISUAL INSP AND IDENTIFICATION IS PERFORMED AND THE UNIT TAGGED. CONTAMINATION CONTROL PROCESS, CORROS. PROTECTION PROVISIONS, NOE EXAM OF WELDS, RAW MAT'L (LOT) CERTIFICATION, PARTS PROTECTION, COATING AND PLATING PROCESSES ARE VERIFIED BY INSPECTION. MANUF, INSTALLATION, AND ASSY OPERATIONS ARE VERIFIED BY SHOP TRAVELER, MANDATORY INSP POINTS. THE ABOVE ITEMS AND THE FOLLOWING ITEMS WERE VERIFIED BY AUDIT CONDUCTED 9-2-76. CONTAMINATION CONTROL PLAN, PROPERLY MONITORED HANDLING AND STORAGE ENVIRONMENT, SPECIAL MEASUREMENT STANDARDS AND EQUIP AND MAT'L AND EQUIP CONFORMANCE TO CONTRACT REQMTS. TURNAROUND - VISUAL INSP USING OPTICAL INSTRUMENTATION. SYSTEM FLUIDS ARE ANALYSED FOR EVIDENCE OF CONTAMINATION. PROPER INLET VALVE FUNCTION AND ELECTRICAL LOGIC POWER IS VERIFIED. (D) NO DIRECT FAILURE HISTORY AVAILABLE.

MEETING MINUTES

Review of JSC 14651, Hardware/Software Interaction Analysis Volume VIII,
AFT Reaction Control System Part 2 of 2.

1. Telecon held between Boeing-Houston/Rockwell, Downey 11/5/79 12:30 PM
to 2:00 PM.

| <u>2. Attendees</u> | <u>Organization</u> | <u>Phone</u> |
|---------------------|------------------------------|----------------|
| Lonnie Jenkins | NASA/JSC | X 3851' |
| Dave Latham | Boeing/Reliability | 527-0323 (FTS) |
| Don Cagle | Boeing Reliability | 527-0323 (FTS) |
| Herb Saxton | Rockwell Propulsion/RCS | X 4503 |
| Larry Gladu | Rockwell Systems Engineering | X 1189 |

3. The following changes were discussed and will be incorporated in the final
release of AFT Reaction Control System Hardware/Software Interaction Analysis
and will be reflected in the next update of AFT RCS FMEA.

03-2A-201010-1: Change SM to RM GAX, change 400 psi to 500. Add gross leak
detection. Add crossfeed.

03-2A-201013-1: No. 1 same as 201010-1. Add crossfeed. Add gross leak detection.

03-2A0201020-1: Change question 1 to ullage transducer will give C&W alert
< 200 psi. Change no to yes.

03-2A-201030-2: Question 1 same as 201020-1

03-2A-201035-1: Question 1 same as 201020-1. Add gross leak detection.

03-2A-201060-4: Change question 1 no to yes and "No Software Detection" to
"Hardware Accepts Risk". Add gross leak detection.

03-2A-201070-1: Change question 1 and 2 to gross leak detection. Add POD
Redundancy to question 6.

03-2A-201080-1: Change question 1 to gross leak detection. Change question
6 from 2 to 0 and add "Need minimum of 2 yaw thrusters.
Crossfeed is available. Pods are redundant.

03-2A-201090-1: Change question 1 to gross leak detection. Add question 6 -
Pod redundancy.


03-2A-201095-2: Change question 6 from 1 to 2 and delete comments.


03-2A-202108-1: Change question 1 to gross leak detection. Delete question 7.


03-2A-202109-1: Delete questions 1, 3a and 6.


- 03-2A-202110-1: Change question 1 to - First indication "failed off" thruster C&W for 1/2 leg, redundant paths on 3,4,5 leg.
- 03-2A-202111-2: Question 1 change no to yes. Add "failed off" thruster gives first indication.
- 03-2A-202120-3: Change question 1 from yes to no and delete comments. Change question 3 from no to yes and add "RCS RM automatically detects and prevents thrusting".
- 03-2A-202150-1: Change question 1 to gross leak detection. Change question 6 from 0 to 1 and add "There is one success path remaining after first failure.
- 03-2A-211110-1: Change question 1 to gross leak detection. Change question 6 to POD Redundancy
- 03-2A-211110-2: Delete 1a/3a add question 1 "failed off" thruster may illuminate if < 40 psi is sensed 3 times, 80 milliseconds apart. Change no to yes. Question 2 change yes to no. Change question 3a from yes to no. Change question 6 from 0 to 1. Add crossfeed.
- 03-2A-211120-1: Change question 1 to-gross leak detection. Change question 6 from 0 to 1. Add crossfeed.
- 03-2A-221308-1: Change question 1 to gross leak detection. Delete comments question 2. Delete comments question 3 and change yes to no.
- 03-2A-221310-4: Delete 1a/3a, add question 1 "failed off" thruster C&W. Change no to yes. Question 3 change no to yes.
- 03-2A-221311-1: Same as 221310-4.
- 03-2A-221312-1: Same as 221310-4.
- 03-2A-221313-1: Question 1a change yes to no. Question 3a change yes to no.
- 03-2A-231310-1: Change no to yes, question 1 change no to yes, question 3 and add "down modes to free drift". Change yes to no, question 3a. Question 6 change 2 to 0 and add "No redundancy in the verniers".
- 03-2A-231310-2: Question 1 change no to yes, add "failed on" thruster C&W. Question 3a change yes to no. Question 6 change 2 to 0 and add "down modes to free drift."
- 03-2A-231310-3: Question 1 change no to yes. Change comments to "failed off" thruster C&W. Question 2, delete comments. Question 3, change no to yes and add "down modes to free drift". Question 6 change 2 to 0 and add "No redundancy in the verniers."

Approved by:

 11/29/79
Larry Gladu, RI
System Engineering


Dave Latham
JSC Reliability (Boeing)

 12/4/79
Lonnie Jenkins
JSC Propulsion


Don Cagle
JSC Reliability (Boeing)

Document Number: JSC 14651

Title: HARDWARE/SOFTWARE INTERACTION ANALYSIS
Volume VIII, AFT Reaction Control System, Part 2 of 2

Prepared by: NB - Reliability Division

Distributed by: NB - SR&QA Data Center

Authorized Distribution

NASA/JSC

EH/J. F. Hanaway (2)
JM6/(3) ←
MG/A. D. Aldrich
NA/M. L. Raines/L. T. Spence
SR&QA Data Center (Boeing, HS-01)
NB/J. H. Levine/H. L. Williams
W. L. Bunce (Boeing, HS-02)
ND/T. J. Adams
S. Costello (Boeing, HS-03)
NE3/E. Vonusa
NS/J. B. Hammack

Rockwell-Downey

041-AD45/C. O. Baker, Jr./V. P. Ostrander
041-FA46/G. A. Phelps
041-FA46/L. W. Gladu
041-FA46/W. A. Harris
041-FB75/W. B. Fouts